

Maintenance Incident Report

Machine: Hydraulic-Press-9

Error code: H33

Description:

Press is losing hydraulic pressure mid-cycle and stalling before reaching full clamping force. Small amount of hydraulic fluid pooling on the floor near the main valve assembly. Pressure gauge reads below the minimum operating threshold within about 5 minutes of startup.

Reported by: Line Technician, Shift 1

Date: 2026-09-11