16		
₹ V	edanta	ľ
UZ.	transforming elements	

VEDANTA LIMITED – VALUE ADDED BUSINESS	Format No.:	VL/IMS/PP1/MECH/WI/24
INTEGRATED MANAGEMENT SYSTEM	Revision Date:	05.04.2021
Work Instructions for River water pump	Revision No.:	00
	Page No.:	1 of 3

Activities River water pump suction end at river Point

Objective Modification of Structure, HDPE work at river point

Responsibility Engineer in charge and workmen at job

PPEs to be used Helmet, Shoes, hand gloves, life boy, rescue apparatus,

Aspect-Impact

Steel Scrap Resource Depletion FRP material Spillage Land contamination

Hazards Identified

Energy Sources	Potential hazards
Electrical	- Electric shock,
	- Cable damage,
	- Loose connection.
Mechanical	- Falling, tripping.
Wiechanical	3, 11 3
	- Proper fixing of fall arrestor.
	- Entanglement, Impact, Cut injury
Potential	- River at high tide
	- All steady structures
Human	- Loose connection,
behavior	- Non use of PPEs,
	- Alcoholism
Biological	- Mosquitoes
	- Birds
Bio	- Body posture of workmen
mechanical	

SAFETY PRECAUTION

24 volt DC supply should be used for providing illumination
Cotton/Leather hand gloves, nose mask, white/black goggles should be used
Proper checking of Welding machine, gas cutting set, grinding, cut off, flexible grinding machine, etc.,

Prepared & Reviewed:	Approved:	Issued:
HOD – Mechanical – PP	Head - Power	MR
05.04.2021	05.04.2021	05.04.2021

- 11-		
* v	redanta 💮	H
	transforming elements	

	VEDANTA LIMITED – VALUE ADDED BUSINESS	Format No.:	VL/IMS/PP1/MECH/WI/24
	INTEGRATED MANAGEMENT SYSTEM	Revision Date:	05.04.2021
	Work Instructions for River water pump	Revision No.:	00
5		Page No.:	2 of 3

PRECHECKS

Take the work permit and safety officer clearance at work place.

Ensure rescue apparatus and rescue team available at site.

Before starting of cutting set and welding machine check the testing certificate.

Before starting of welding / gas cutting work check the any leakages, clean the working areas, make a proper arrangement or put some sheet for sitting.

DO'S

- 1 Use PPE's.
- 2 Follow SOP.
- 3 Activity to be carried out during day duty hours.
- 4 Before putting addition helper/operator on job attendant must ensure that Entrant (helper/operator) should familiar with the operation.
- **5** Check the grizzly platform condition (made of rods) for its looseness, to avoid falling of person.

DONT'S

- 1) Do not by pass SOP.
- 2) Use 24V DC supply illumination to avoid electrocution/electric shock.
- 3) Check the grizzly platform (made of rods) for its looseness, if found any deviation correct it if not, stop the work and don't allow any person to go inside main flue duct.
- 4) After job completion ensure that all involved crew members are come out from HESP and close the man hole of it.
- 5) All material/scrap collected during executiondo not keep at job site after completion of work.
- 6) Normalize the system and release all equipment shutdowns and close the work permit.
- 7) Give the clearance to HOD, SS from your side that your assigned job is completed.

Role of Rescue Team

Prepared & Reviewed:	Approved:	Issued:
HOD – Mechanical – PP	Head - Power	MR
05.04,2021	05.04.2021	05.04.2021



Format No.:	VL/IMS/PP1/MECH/WI/24
Revision Date:	05.04.2021
Revision No.:	00
Page No.:	3 of 3
	Revision Date: Revision No.:

As the work is being carried out inside HESP, in an emergency victim can be taken out by use of rescue apparatus such as stretcher. However attendant should call ambulance which is fully equipped. However rescue team members should take a charge of the situation.

Rescue Team member.

Detail activity procedure.

- 1. After obtain clearance from operation department start remove the all unwanted platform / damaged platform material located near work place.
- 2. Provide new platform as per requirement and additional strengthen from bottom civil foundation.
- 3. Structural Platform detail scheme, stability has to be ensure from internal design department.
- 4. After placing platform, lock the existing FRP pipe to structure by providing double clamping.
- 5. After locking of FRP suction point, all damaged portion frp joint to be repaired.
- 6. All generated scrap during execution to be removed from site and shift to designated scrap yard.

Prepared & Reviewed:	Approved:	Issued:
HOD – Mechanical – PP	Head - Power	MR
05.04.2021	05.04.2021	05.04.2021