

VEDANTA LIMITED – VALUE ADDED	Document No:	VL/IMS/PID1/
BUSINESS		INST/WI/05
INTEGRATED MANAGEMENT SYSTEM	Revision Date:	05/01/2022
Work Instructions for Calibration of Cast	Revision No:	05
Iron Weight	Page No.:	1 of 1

CALIBRATION OF CAST IRON WEIGHTS

Objective: To check accuracy of C.I. weight

Scope: This procedure is applicable to check the accuracy of all CI weight used for the

Calibration of bins.

Reference: SP/44-H & RISK/INST/17

Performance Criteria: Accuracy of CI weight

Aspect for the Activity: Waste generation

Identification of Hazards:

Mechanical: Impact of falling of C.I weights, Impact due to trapping of fingers under

C.I Weight, Dust, Trip & fall. **Chemical:** Dust, Graphite.

Ergonomics: Insufficient work practices

Hazard due to Human Behavior/Human error: Not adhering to WI/ PPE, Alcoholism

, Use on non-certified tools/equipment.

Responsibility: Sr. Engineer Instrumentation/Associate / Inst Technician

A) CALIBRATION OF C.I WEIGHT

Frequency: -Once in 2 Years.

Procedure:

All Engineers/Technicians should follow this procedure whilst checking accuracy Of C.I. weight. Care should be taken to avoid falling of weights.

- 1) Use hand gloves while shifting the weight.
- 2) Put one 20 kg standard C.I. weight on digital weigh scale.
- 3) Adjust reading to 20.00 kg.
- 4) Take out the standard C.I. weight from the weigh scale.
- 5) Put test weights on the weigh scale.
- 6) Put the Sr. No and the corresponding weight value on the CI weight.

Prepared By:	Reviewed & Issued By:	Approved By:
Associate Manager–	Management	Head – Electrical &
Electrical &	Representative	Instrumentation PID1
Instrumentation PID1		
Signature:	Signature:	Signature:
	Signature:	Signature:
	Signature:	Signature: