1		Γ
₩V	edanta	Γ
U.S.	transforming elements	

_			
	VEDANTA LIMITED – VALUE ADDED BUSINESS	Format No.:	VL/IMS/PP2/MECH/WI/7
	INTEGRATED MANAGEMENT SYSTEM	Revision Date:	05.04.2021
		Revision No.:	02
ts	Work instruction for Lubrication	Page No.:	1 of 2

Objective: - Safe handling & Usage procedure for Lubrication

Scope :- power plant Accessories.

Ref: - Safety Data sheets of lubricating oil **Responsibility:** - Engineer In Charge & workmen at job

PPE –s to be used: - Helmet, Safety shoes, Dust masks, Hand gloves and goggles.

Work No 1 : Lubrication of gear box/ equipment

Work No 2 : Greasing of Equipment.

Work no 3 : Collection and disposal of waste oil

Aspect: Oil Spillage, Oil traced waste generation, Noise

Impact: Land contamination, Resource Depletion, work environment

Hazard Identified:

Mechanical Hazard- Entanglement between moving parts due to improper guarding,

Removal of machine guard etc

Slip and Fall of person due to poor housekeeping and grease / oil

Human Behavior:- No usage of PPE, Improper housekeeping, Alcoholism,

overconfidence, Negligence

Safety precautions:

- Avoid using mobile phone while working.
- Use appropriate tools required for the job.
- After job always do proper housekeeping.
- Always prevent body from line of action of force.
- Perform proper communication verbal and non-verbal as required.
- All barrels should have secondary Containment

Work No 1 :- Lubrication of gear box/ equipment

- Clean the gear box/equipment with the cotton rags/compressed air. Use goggles
 while cleaning compressed air for cleaning. Do not use compressed air for body
 cleaning.
- Check the oil level and quality by visual examination.
- Make up the oil level by pouring oil through the inspection door / vent in the gear box / pump
- Do not keep the gear box open for long time
- If the oil is contaminated by, replace the oil completely
- Fit back vent after filling oil.

Prepared & Reviewed:	Approved:	Issued:
HOD – Mech – PP	Head – Power	MR
05.04.2021	05.04.2021	05.04.2021



	VEDANTA LIMITED – VALUE ADDED BUSINESS	Format No.:	VL/IMS/PP2/MECH/WI/7
	INTEGRATED MANAGEMENT SYSTEM	Revision Date:	05.04.2021
		Revision No.:	02
s	Work instruction for Lubrication	Page No.:	2 of 2

- Use funnel for pouring the oil & keep a tray below the equipment to avoid spillage to ground
- Use hand pump and clean hose for filling up oil to hydraulic power pack.
- Inspect the equipment and fitting for leakage

Work No 2 :- Greasing of Equipment.

- Clean the portion of the equipment which is to be greased.
- Clean the grease nipple and operate grease gun for filling grease.
- Keeps a tray below the equipment to avoid spillage to ground.
- Collect the waste grease and return back to store

Work No 3: Collection and disposal of waste and burnt oil

- Waste oil removed from equipment shall be shifted to waste oil barrels
- Return the barrel to stores after it is filled
- Ensure no oil is kept open
- Keep the Oil/Grease traced material in separate bins and return to store as oil traced waste.
- Do not lubricate the equipment which is in operation without close supervision.

Prepared & Reviewed:	Approved:	Issued:
HOD – Mech – PP	Head – Power	MR
05.04.2021	05.04.2021	05.04.2021