

# CODE OF PRACTICE FOR OXYGEN GAS PIPELINE

IPSS: 1-06-034-98\_

Corresponding IS does not exist

#### o. FOREWORD

This Inter Plant Standard prepared by the Standards Committee on Pipes, Fittings, Valves and Piping Layout, IPSS 1:6 with the active participation of the representatives of all the steel plants and associated organizations in the field was adopted in June 1998.

oxygen is distributed to consumers from a generation plant LOX storage and vaporization plant or a cylinder discharge manifold by means of pipelines. Oxygen is a highly oxidizing gas which under certain conditions combines with almost all the elements giving rise to a brisk exothermic reaction. In view of the possibility of spontaneous combustion in oxygen piping systems, special precautions need to be taken in design, fabrication, erection, testing and commissioning of oxygen pipelines.

#### SCOPE

This Inter Plant Standard stipulates engineering requirements for safe design, construction and commissioning of oxygen gas pipelines made of carbon steel or non-ferrous metals or alloys for operation at pressures upto 42 kg/cm $^2$ (g) and temperature upto 55 $^{\circ}$ C. The requirements are covered after pressure regulation system.

NOTE: In this Standard, wherever "oxygen pipeline" is mentioned, the same should be construed as referring to "oxygen gas pipeline" only.

#### CLASSIFICATION OF PIPELINES

1 Depending on the maximum operating pressures, oxygen gas pipelines shall be categorized as follows:-

Category I - for operating pressure upto 16 kg/cm<sup>2</sup>

Category II = for operating pressure, above 16 upto 42 kg/cm<sup>2</sup>

Pipe Sizing

### 2.2.1 Design Criteria

The three basic criteria that determine the design of pipes and components shall be:

- Gas velocity
- Pressure losses
- Mechanical strength of pipe (pressure, temperature and stress)

AUTHENTICATED COPY

AMA: V

(ASSESS RUVIAN)

SR

PAGE 1/19

### 2.2.2 Design Procedure

For each section of the pipeline, the flow rate and required pressure being known the usual sequence of selection shall be as follows:

- The diameter of the pipeline shall be finalized so that the required pressure is available at consumer point with the maximum flow in a given pipe run. It shall be selected by judging from economical velocity calculated separately for each pipeline.
- Verification of velocity and possible adjustment of the diameter so as to observe velocity limits.
- Selection of thickness of the pipeline based on the desired resistance to pressure.

# 2.2.3 Selection of Velocity

Selection of velocity in a particular section of a pipe depends on various factors like flow materials off the pipe, dust and foreign matter content etc. Velocity means the gas velocity in a given cross section calculated under the conditions of pressure temperature and flow.

It shall be calcullated as follows:-

Maximum Recommended velocities in pipelines shall be:

Category I - 10 m/sec
Category II - 8 m/sec

Velocity of oxygen in the pipeline depends on the material of the pipe selected and the pressure range for which the pipeline system is designed. Although international standards and norms allow higher velocities of oxygen gas in pipeline, the velocities recommended by this code is limited to the values given above, considering prevailing qualities of workmanship and cleanliness achieved.

# LAYOUT OF PIPELINES

## .1... Intershop oxygen pipelines (outdoor)

- 3.1.1 Oxygen pipework shall preferably be routed overhead, however, underground routing may also be permitted, if the requirements so demand.
- 3.1.2 While routing overhead oxygen pipelines depending on the route through which they pass the minimum clearance (from surface to surface) from other structure shall be as per Table-1 and the minimum clearance (in height) shall be as per Table-2.

TABLE-1

MINIMUM CLEARANCES OF OVERHEAD OXYGEN PIPELINES (surface to surface)
(clause 3.1.2)

S.No.	Structures	Clearance (m)	Remarks
i.	Explosion Hazardous Shops	3 .	<del>-</del>
2.	Railway Tracks	<b>3</b>	To the nearest
3.	Railway Bridges & Platform	3	
4.	Roads	1.5	1.5m upto the embankment
	High voltage transmission lines	<b>4</b>	· · · · · · · · · · · · · · · · · · ·
	a) parallel to pipeline	10	•
	b) crossing the pipelines	et e	
	upto 20 KV	3	
	35 - 150 KV	4	
	150 - 220 KV	5	
6.	To the place of hot metal tapping and source of open fire	10	
7.	(a) - for insulated LT cable	0.5	
	(b) - for bare conductor LT	. 1	

TABLE-2

MINIMUM CLEARANCE OF OVERHEADS OXYGEN PIPELINES (in height)

(clause 3.1.2)

s.No.	Route	Clearance (m)	Remarks		
1.	Roads	6.0	From the road surface to the bottom of pipe or to the bottom of pipe sup- port structure whichever is lower		
2.	Pavements	2.2			
3	Non-electrified Railway Track	6.0	From the top surface of the rail to the bottom of the pipe or platform or heat shield whichever is lower		
5	Electrified Railway and Tram Track  Hot metal Track: - Without heat shield - With heat shield	7.1 10.0 6.0			

- 3.1.3 Pipeline shall be laid on the platforms, pillars, columns and on the external walls of the building using the external bracket.
- 3.1.4 It is permitted to lay oxygen pipeline along with other pipelines on common supports, keeping a clear distance of 300 mm (both vertical, and horizontal). For gaseous pipelines, refer IPSS:1-06-014-95.
- 3:1.5 Oxygen piping shall have electrical continuity across all connections and shall be effectively earthed at suitable intervals (generally they are in the range of 100-150 mm).
- 3.1.6 When gaseous oxygen pipeline crosses another pipeline of 300 mm and more diameter, the distance between them shall not be less than 150 mm and when the diameter is less than 300 mm, the distance should not be less than 100 mm.
- 3.1.7 The laying out of gaseous oxygen pipelines shall not be permitted in the following cases:
  - Along the walls of explosion hazardous building
  - Through the ware houses of inflammable materials
  - With electrical wires and electrical cables.

- 3.2 Underground laying out of pipelines.
- 3.2.1 Underground pipelines shall be laid in the trenches and then back-filled with soil unless specially permitted otherwise by the Engineer to protect against frost, casual surface construction, shifting due to unstable soil, back-fill damage to the external surface of the pip or the coating, and above ground loads such as vehicles or equipment moving over path of pipeline. All buried oxygen pipelines shall have a minimum horizontal distance of 3 m from buildings and 3.5 m from centre line of railway tracks. A vertical distance of 1 m shall preferably be kept between burried oxygen lines and other underground piping cabling at crossings.
- 3.2.2 An earth cover of atleast 1.2 m shall be maintained from the top of the pipe to the ground level in areas subject to temporary load, and atleast 1 m in areas not subject to temporary loads.
- In case of laying oxygen pipelines in open trench a depth of minimum 1 m shall be maintained from the top of the pipe to the finished level of the road. In rocky soils, a clear distance of minimum 0.1 m shall be maintained between the bottom of the pipe and lowest level of the trench. Compacted sand shall be provided on the top and bottom of the pipe to an extent of 0.2 m and 0.1 m respectively.
- 3.2.4. Piping shall be all of welded construction applying a specification and inspection code such as API 1104 (7). No mechanical joints should be installed underground either buried or in pits because of possibility of leaks.
- 3.2.5 Cathodic protection of the unberground sections of the pipeline shall be provided in addition to passive protection by coating and wrapping. This shall be as per APPENDIX-A.
- 3.2.6 Underground portions of the pipeline systems shall be connected to the above ground portions through an electrically insulated joint to isolate the underground cathodic protection system. The insulation gastet shall be oxygen compatible.
- 3.2.7 Oxygen pipes passing through walls, ceilings, fences and other structures of the buildings or constructions shall be encased in a state pipe having inside dia atleast 50 mm more than that of oxygen lines. The lines shall have no joints in the sections at such crossings. The gap between the oxygen pipe and the outer pipe shall be filled with non-inflammable material, but allowing vertical and horizontal movements.
- 3.3 Inside shop layout
- 8.3.1 Oxygen pipelines serving to the technological equipment inside or outside the shop are called the inside shop pipelines.
- 1.3.2 Inside the oxygen plants and the distribution compartments, the pipelines may be laid along the walls or columns of the buildings.
- 3.3.3 Oxygen pipelines is the consumer shops shall be routed as far away as practicable from other lines and process equipment containing fluids which are hazardous in an oxygen environment. If located in a multi-pipe rack the mechanical joints in the oxygen line shall not

be located close to mechanical joints in other fluid lines where hazardous mixtures could be formed if simultaneous leakage or failure occurred. In places of through walls, floorings, partition and other building structures oxygen pipelines shall be encased. The runs of pipelines within the casing shall be free of joints.

- 3.3.4 Each run of oxygen pipelines between the fixed supports shall be designed for compensation of thermal expansion. The compensation of thermal expansion can be achieved either by adopting a routing configuration which is self-flexible, or by using U-loops made from seamless pipes assumed either horizontally or vertically.
- 3.3.5 The gate valves on the oxygen lines, which are situated in the open shall be atleast 3 m. away from pump houses and other buildings and equipment.
- 3.3.6 Necessary provision shall be kept on oxygen lines for purging by nitrogen for this purpose.
- 3.4 Other System design considerations
- 3.4.1 Fire break sections may be installed in the oxygen pipeline to limit the propagation of combustion in a steel pipeline. Fire break sections may be introduced immediately downstream of the main isolation and throttling valves where the velocities can be high. The fire break section will be either a length of copper pipe having the same inside diameter as the main pipe with flanges fitted at the two ends which is installed between the steel pipes or copper insert tube made from copper sheet/tube and inserted inside the steel pipe downstream of the valves. The copper insert tube shall generally used in large diameter steel pipelines.
- 3.4.2 In steel pipelines care shall be taken to install isolation valves do straight sections of the pipeline. Any pipeline component which is likely to cause a change in the flow pattern like reducer, bend, tee or "Y" connection, orifice plate etc. shall be at a distance of it least four diameters away from the valve.

# MATERIALS FOR USE IN OXYGEN SERVICE

- 51 materials used in oxygen piping systems shall be compatible with a companion of the cleaned for oxygen service prior to their use. Violations of these requirements are extremely hazardous and can lead to a fire. Recommended specification for pipes and other pipe fittings shall be as per Table-3
- 4.2 The metals most frequently used in oxygen service shall be as follows:
  - i) Carbon steels for delivery and distribution pipelines above or below ground and for the construction of pipe work fittings.
  - ii) Copper and its alloys where resistance to oxidation and ignition are required and where the velocities in the pipework are on the higher side.
  - (ii) Stainless steel where greater mechanical strength is desired. It also facilitates ease of cleaning.

- Valves in oxygen piping systems shall be for isolation, process control and pressure relief purposes and shall be kept to a minimum since they have mechanical joints susceptible to leaks. Recommended specification of valves shall be as per Table-4
- 4.4 Valves & accessories used in the oxygen gas pipeline shall be designed to function without lubrication. However, if a lubricant is necessary to permit assembly operations or the functioning of a component, it shall be selected from lubricants like graphite. molybdenum disulphate flourinated or non-flourinated silicons per-flourinated poly-ethers.
- 4.5 Lubricants used in actuators for valves on oxygen lines shall be suitable for oxygen service.
- In case of a non-metallic being used for gaskets, valve seats, etc...
  care shall be taken to ensure that the material selected is dense,
  non porous and free from surface or other defects. Compacted fibers
  and powders shall be excluded. These parts shall be securely
  enclosed with the minimum of play in solid metallic supports which
  are conductors of heats.
- Plastic or organic materials have a distinctly lower ignition temperature than metallic materials and on ignition they eventually heat particles and adjacent metal particles to the point of ignition. It is, therefore, good practice to use such materials in the smallest possible quantities and only in intimate contact with metallic pirts of greater mass and good conductivity to dissipate the heat. The use of these materials in direct contact with oxygen cas shall be limited to the following:
  - Seals and packings in components and assemblies
     Deformable elements (diaphragms) in regulating devices
    hoses
    Suggested product and their uses:

Product	Properties	Uses
PTFE and FEP	Good antifriction	Valve-seats
	Tendency to flow	Antifriction bearings
	Tendency to sublimate	Antifriction coatings
		Thrust washers
기약 기업에 기업이다. 실취하기 회장 기업 기업이 기업이 기업이다.		Thread seals
		Gland packings
PTFCE	Harder than PTFE	Valve seats
	Greater mechanical	Bearings
	strength than PTFE	Insulating seals
	and FEP	Gland packings
Flourinated	Flexibility	O-ring seals
Chloroflourinated elastomers (Viton)	Elasticity	Diaphragms

Pipurinated and chloroflourinated resins can be reinforced with oxides, aspectos, glass, ceramic, metals and alloys in order to improve some of their mechanical properties. Such reinforcement shall not affect resistance to ignition.

TABLE-3 RECOMMENDED SPECIFICATION OF PIPES AND PIPE FITTINGS (clause-4.1)

S. No.	Item	Nominal dia (mm)	Specification
1.	Pipe	6 to 10	Seamless tube, deoxidized non-arsenic copper or copper alloys for both category I & II.
		15 to 600	Carbon steel seamless to ASTM A 106-1992 Grade B/A53 Gr-B-1993, black with ends bevelled for both category T & II.
2.	Pipe	40 and below	Forged carbon steel socket as per class 300 weld fittings as per ASTM A 105-1994 to ANSI B 16.11 for both category I & II.
		50 and above	Forged carbon steel butt welded fittings as per ANSI B 16.9 to ASTM A 234-1990. Grade WBP for category I & II.
3.	Flanges	40 and below	Forged carbon steel, socket weld, raised face, class 300 for category I & class 300 for category II to ANSI B 16.5 and ASTM A 105-1994/carbon steel raised face slip on flanges to IS:6392-1971 made from plates to IS:2002-1992 Gr 2A with bore to suit pipe O.D.
		50 and above	Forged carbon steel, weld neck, raised face, class 300 for category I & class 600 for category II to ANSI B 16.5 and ASTM A 105-1994/carbon steel raised face slip on flanges to IS:6392-1971 made from plates to IS:2002-1992 Gr 2A with bore to suit pipe O.D.
4.	Gaskets	All size	Teflon (LOX grade) or paronite (oil free)
5.	Bolting	All size	IS:1367 for category I
	Studs Nu	ts	ASTM A 193-1994 Gr B7 ASTM A 194-1994 Gr 2H for category II.
6.	Bends	40 and below and upto 50	Cold bend ( R = 5D )
		50 and above	Forged carbon steel alternatively hot bend ( $R = 5D$ )
7.	Filters		Copper alloy/stainless steel body, copper alloy filtering element (for pipeline category-I)/glass cloth filtering element (for category-II), ends flanged
8.	Copper i	nserts	Made of copper tube/sheets, to be located inside steel pipes downstream of obstruction (valves, etc), length 600 mm or 5xDN (whichever is more) as per working drawings.

IPSS: 1-06-034-98

# TABLE-4 RECOMMENDED SPECIFICATION OF VALVES (clause 4.3)

	S.No.	Item	Nominal dia (mm)	Pipeline category-I	Pipeline category-II
	1.1	Isolation valve	40 and below	Class 800 Bronze/stainless steel ball/globe valve, teflon	Class 800 Bronze/stainless steel ball/globe valve
			• .	packing and seats with bronze/ SS trim, ends flanged	with teflon packing and bronze/stainless steel
					trim, flanged end
	·		50 and above	Class 300 ball valve bronze/ stainless steel body and trim,	Class 300 ball valve, bronze/SS body and trim
				tefion packing, flanged ends to ANSI 816.5	tefion packing, flanged ends to ANSI B16.5 size
					provided with gear reducer
	1.2	Throttling	40 and below	Class 800 bronze, globe valve, teflon packing and seats with	Class 800 bronze, globe valve, teflon packing and
			•	bronze/SS trim, ends flanged	seats with bronze trim,
			50 and above	Class 300 bronze, globe valve, flanged ends to ANSI B16.5	Class 300 bronze globe valve, bronze trim, teflon
	1.3	Non return	All sizes	Bronze/stainless steel valves	•
				of swing/lift cheek type with soft seat to suit installation,	
				flanged ends	
			40 and below		Class 800 bronze/stainless
			50 and above		Class 300 bronze/stainless
					steel swing cheek valve with soft seat bronze/SS
					trim, teflon packing
			. •		flanged ends to ANSI 816.5 working drawings
ite:					trim, teflon packing flanged ends to ANSI 816.

### Note:

- Steel mating flanges for flanged copper valves/appurtences shall be flat faced with full face gaskets.
- Rating and drilling details of companion flanges for valves and fittings shall match with those of valves and fittings.

5.

#### PREREQUISITES FOR PIPELINE ERECTION

- All general pipes, valves, fittings, instruments and appurtenances for oxygen service shall be permitted for erection only after physical inspection at installation site and verifying the suppliers documents/certificates regarding satisfactory compliance with the requirements for oxygen services. The important aspects to be checked are listed below:
  - a) All components of pipework shall be checked for their standard of manufacture, dimensional and material suitability.
  - b) The accompanying documents and certificates showing results of tests at manufacturers works shall be verified. Without such certificates, the item shall not be used for oxygen service.
  - c) The packings shall be checked to ensure that they are not damaged while in transport between place of manufacturer and site installation.
  - d) Presence of grease or oil shall be checked in light on visible outer surfaces. Inside of pipes or fittings may be checked by passing a white lint free cotton. Alternatively the pipes and fittings may be subjected to ultra-voilet radiation. Any presence of oil or grease on the surface will create fluorescence.
  - e) Presence of seals shall be visually checked. Presence of other foreign matters such as fillings, scale flux, corrosion products, common dirt, wood and metal chips, threading compounds, sealers, tar, asphalt, moisture, paint, chalk, flushing compound etc shall also be checked.
  - f) It shall be ensured that all pipework are cleaned free of all foreign matter.

# 5.2 Cleaning by Manufacturers

- 5.2.1 At the manufacturer's works, all pipes and fittings shall be pickled, neutralized and phosphated as per IS:3618 after completing shop tests. Then these shall be tightly sealed by plugs or blank flanges, packed with sachets of dry silica gel inside and tagged "pickled for oxygen services" before despatch.
- 5.2.2 Valves, regulators, filters etc shall be thoroughly cleaned and degreased, their ends sealed by plugs or blank flanges and packed in clean polythene bags and tagged "degreased for oxygen service" before despatch. The method of degreasing shall be same as that described in clause 5.3.3.
- 5.3 Cleaning at Erection Site
- 5.3.1 All pipes, valves, fittings, etc after visual examination verification of documents mentioned in clauses 5.1 and 5.2 above, shall also be cleaned at site as described herein.

- In case the oxygen pipes and fittings delivered to site by manufacturers/stockists are found to contain scales, rust, etc, they shall be subjected to cleaning, pickling, neutralizing and phosphating as per procedure given in APPENDIX-B. After this treatment they shall be dried in open air or by blowing dry air. The ends shall then be kept sealed till degreasing commences.
- 5.3.3 Degreasing
- 5.3.3.1 Before erection, all piping components shall be degreased thoroughly, using solvents such as trichloroethylene, carbon tetrachloride etc suitable for oxygen service. Patented procedures for vapour degreasing may also be adopted, subject to approval by Purchaser/Engineer.
- 5.3.3.2 The degreasing solvent quality shall be checked before using the same for degreasing.
- 5.3.3.3 Before degreasing, the pipe work shall be dried by blowing air.
- 5.3.3.4 Then the outer surface of pipes shall be cleaned by wiping with cloth dipped in solvent and then dried in open air.
- 5.3.3.5 Inner surfaces of pipe shall be degreased by plugging one end, filling the pipe with solvent as per quantities given at Table 5 and then plugging the other end. The pipe shall then be kept horizontally and rotated on its axis at least once every minute, this process shall continue for 15 minutes. After draining the solvent the pipe shall be blown with dry, oil free air or nitrogen of at least 94.0 percent purity at 60 Deg C to 70 Deg C temperature for about 5 minutes, or till the smell of solvent is completely eliminated. Alternatively, the drying may be done in open air for a minimum period of 24 hours.

TABLE-5 Minimum Quantity of solvent to be used for degreasing

(size of pipe in mm)	32	50	100	150	200	250	300
quantities ltr/m.	0.4	0.6	0.9	1.4	1.8	2.2	2.3

- 5.3.3.6 If considered necessary after site inspection, the valves, fittings and instruments shall also be degreased at site and dried in open air. The valve and fittings shall be disassembled and kept in closed containers containing the degreasing solvent for 5 to 10 minutes. After removing the components the same shall be dried in open air till the solvent smell is eliminated. Degreasing of asbestos gaskets and packing and packings shall be done in a suitable solvent for 2 to 3 minutes and then dried.
- 5.4 All tools and appurtenances used for cleaning shall also be free of all oil, grease, dirt etc. These shall also be thoroughly cleaned, degreased in a suitable solvent and dried before use.

- 5.5 All personnel involved shall follow a high standard of personal cleanliness. They shall also take adequate safety precautions to avoid inhaling solvent vapours arising during degreasing. They shall use clean gloves and gas masks.
- Cleaned components of pipework shall be well protected from recontamination by proper packing and storing. Pipes shall be sealed with plastic end-covers. It is recommended to place small sachets of dry silica gel inside the cleaned and degreesed pipes by attaching the sachets by tape to the plastic end covers. Small items shall be kept sealed in polythene sheet. All items shall be kept in covered space till issue for erection. Sufficient quantities of descants shall be kept in places of storage to prevent condensation of moisture on ferrous materials.
- 5.7 Quantity of the degreasing shall be checked by the following methods:
  - a) Determination of the oil content in the solvents removed from the components after controlled degreasing; degreasing quality may be considered satisfactory if oil content in the removed solvent does not exceed more by 20 mg/l of oil content in the solvent.
  - b) By wiping off the section of the cleaned surface by degreased napkin from glass-cloth soaked in the clean solvent and by subsequent determination of oil content on this napkin.
  - c) Visual inspection of the open cleaned surface with the help of luminescent devices. Quality of degressing by water detergent solution of surfaces inaccessible for inspection and napkin wiping may be determined by random control degressing with organic solvents of a sample from every batch of simultaneously degressed items

#### 6. ERECTION & MAINTENANCE OF GASEOUS OXYGEN PIPELINES

- All erection work of Oxygen gas pipelines shall have to be closely supervised and rigorously followed up to prevent unforeseen holdup which may result in deterioration in cleanliness of the pipework.
- 6.2 Parts, accessories, materials and pipes used for manufacture, erection and maintenance of the pipe lines, buildings and structures for pipelines shall meet the specifications of the project. Any changes from design shall be made only with the permission of design organization which worked out the project.
- 6.3 Materials, parts, units, accessories and other equipment used for manufacture, erection and maintenance shall meet the required standard norms and technical conditions and shall have certificates of manufacturing plant.
- Accessories shall have marking and distinguishing paint as per standards and norms, according to their use and materials. Steel slide valves, irrespective of their size shall have tag number on housing.
- Pipeline assemblies and welding parts during assembly and welding shall be subjected to careful, one by one, control, the welded joints shall be controlled by physical methods. Openings of accessories shall be closed by blanks or packings.

- 6.6 While laying the pipe lines through the walls, roofs and other structures of buildings, the pipelines shall be covered with sleeves. Portions of pipelines covered with sleeves shall not have joints. Gaps between pipeline and sleeve shall be sealed with asbestos or with other non-combustible materials.
- 6.7 Welding of pipeline
- 6.7.1 Electric arc welding shall be used for erection of pipelines. Welding shall be done by qualified welders. Low Hydrogen electrodes shall be used.
- 6.7.2 Backing rings shall not be used for welding. Root run shall be made with Argon arc (TIG) welding.
- 6.7.3 Welding of each joint shall be carried out without breaks upto the completion of welding qualifying tests for welding, welding procedures and quality control etc shall be generally as per IS 2825:1969 'Code of Practice for Unfired Pressure Vessels'.
- 6.7.4 Radiographic examination of 100% welds for oxygen pipelines with working pressure over 10 kg/cm<sup>2</sup> shall be carried out. Interpretation of radiographs shall be done by a competent agency.
- 6.7.5 For pipelines having working pressure 10 kg/cm<sup>2</sup> (g) and below, 40 welds shall be tested by radiography. In case of failure of any welding joint found, 100% radiography to be carried out.
- 6.7.6 For welding pipelines made of non-ferrous metals and its alloys, helium and argon shall be used. Putrity of Argon used for arc welding of copper pipelines shall not be less than 99.8%.
- 6.7.7 All defective welds shall be removed and redone and then will be subjected to radiographic examination.
- 6.8 Sequence of Inspection of pipework
- 6.8.1 Checking of quality of assembly for welding.
- 6.8.2 Control of technology of welding.
- 6.8.3 Checking of alignment.
- 6.9 Checking of welded joints on pipeline
- 6.9.1 During erection the systematic step by step procedure shall be followed.
- 6.9.2 External inspection of welded joints.
- 6.9.3 Checking of the continuity of the joints.
- 6.10 All the joints shall be subjected to the external inspection for the following defects:
- 6.10.1 Cracks on the external surface of the joint.
- 6.10.2 Uneven surface in the welded zone.

- 6.10.3 Through holes.
- 6.10.4 Depth and width of welded joints for evenness.
- 7. TESTING OF ERECTED OXYGEN PIPELINE
- 7.1 The tests of the pipelines shall be carried out after blowing them with oil free and dry air or nitrogen which do not contain fatty materials or oil. Air can be considered oil free if the oil and grease content is less than 0.005 gm/Nm<sup>3</sup> and is considered dry if its relative humidity is less than 30%.
- 7.2 Pipelines of all categories shall be tested for strength and tightness. The medium used for the pneumatic testing on strength and tightness shall be pure to the extent possible.
- 7.3 The tests shall be carried out under the direct supervision of the person responsible for this job in strict accordance with the rules and the project data.
- 7.4 Strength-cum-leakage test
- 7.4.1 Pneumatic leak tightness test of the pipelines shall be carried out using oil free air or Nitrogen. Valve of the testing pressure shall be equal to 1.1 times the design pressure.
- 7.4.2 The welded seams of steel pipelines during inspection may be tapped with wooden hammer of weight not more than 1.5 Kg. Pipeline from non-ferrous metals and alloys may be tapped with a wooden hammer of weight not more than 0.8 Kg. It shall not be allowed to tap by hammering the pipelines made of the other materials.
- 7.4.3 Pneumatic test of the pipelines may be done on strength and tightness. Pneumatic test of the pipeline on tightness (including the test with detection of pressure fall) is to be performed only after the preliminary test on strength by any method.
- 7.4.4 Pressure shall be gradually raised to the test pressure and all joints checked by soap solution for leakage. The testing pressure shall be held for 30 minutes during which joints shall be lightly tapped with a wooden hammer of 1.5 Kg weight. If any leakage is detected, line shall be depressurised and defect rectified.

Leakage test for the pipeline system shall be done at test pressure for a period of 12 hours. During this period, pressure and temperature readings shall be taken at an interval of 1 hour. The gauges used shall be tested for their accuracy and shall have minimum calibration of atleast 0.1  $Kg/cm^2(g)$  and 0.5°C.

Leakage shall be determined by the formula:

 $A = 100 (1 - P_2T_1/P_1T_2)$ Where

A = Quantity of air leakage in percent

 $P_1$  = Pressure in pipeline at beginning of test (Kg/cm<sup>2</sup>a)

 $P_2 = Pressure in pipeline at the end of test (Kg/cm<sup>2</sup>a)$ 

 $T_1 = Absolute temperature at beginning of test <math>\binom{O}{K}$ 

 $T_2$  = Absolute temperature at the end of test ( $^{\circ}$ K)

The test results shall be considered satisfactorly tested and acceptable if the leakage is less than 0.2% per hour.

After completing the testing, the line shall be kept under a pressure of atleast 1.0  $kg/cm^2(q)$  using Nitrogen, till pipeline blowing/commissioning.

- 7.5 The pipelines which are under blowing shall be disconnected from the operating pipelines with the help of blanks which have special handles.
- 7.6 The final inspection of the pipelines shall be carried out under the working pressure and is combined with tests on tightness. In this case the tightness of the welded seams, flange joints and packings shall be checked by leakage detecting device or by soap solution or by other solutions.

#### 8. BLOWING AND COMMISSIONING OF PIPELINE

- 8.1 The blowing of the pipelines shall be carried out with dry, oil free air or nitrogen (94% purity at velocity >20m/sec) which do not consist of fatty material and oils for 30 min. The pressure of blowing gas may be low (close to atmospheric pressure).
- 8.2 The blowing of the Oxygen pipelines shall be carried out for a period of atleast 8 hours. After finishing the 8 hour blowing, the board with sticked white paper shall be placed for 3-5 minutes at the end of the pipe to check for oil. However the duration of blowing depends on length of pipeline, velocity of gas, amount of dust present etc. The oxygen pipeline is considered blown if there is no mark of dust or moisture coming out of the pipe.
- 8.3 If the testing does not give good results, the blowing shall be continued. Checking after each hour, the cleanliness with the help of sheet of white paper.
- 8.4 After completion of blowing with air/Nitrogen, the line shall be filled with Nitrogen, then oxygen shall be gradually introduced into the line and Nitrogen slowly exhausted through the bleeder. The purity of the exhaust gas has to be checked until desired oxygen purity is reached. Then bleeder shall be closed.
- 8.5 If there is any significant time gap between blowing with air/Nitrogen and commissioning then the line shall be kept filled with Nitrogen at 1  $Kg/cm^2(g)$ .

# 9. SAFETY PROCEDURES

1

- 9.1 Some of the important safety procedures to be followed are given below. For general /specific requirements regarding safety procedures IPSS: 1-11-002-98 Safety procedure for oxygen, nitrogen, Acetylene & fuel gases' shall also be followed.
  - A) The testing, cleaning and commissioning of Oxygen gas pipework shall be carried out only in the presence of, and with the permission and guidance of senior Engineer and staff of contractor, engineer and purchaser.
  - b) All first aid and fire fighting facilities shall be readily available during cleaning, testing and commissioning of oxygen pipelines.

- c) All arrangements for cleaning, testing and commissioning shall have the concurrence of the safety engineer. The fire fighting officer or his authorized representative shall be present during cleaning, testing and commissioning.
- d) It is prohibited to put tools and materials on the pipeline.
- e) During pneumatic testing of pipelines for tightness and strength presence of unauthorized people in the guarded zone (not nearer than 25 meters) is prohibited.
- f) On the container with carbon tetrachloride and other solvents there shall be the distinct label poison and dangerous and shall be kept away from the source of heat and fire.
- g) Prolonged inhalation of vapours and contact of solvent with the skin shall be avoided.
- NOTE: General safety rules for working at heights shall also be followed as per IPSS:1-11-005 & 008 " Safety Procedure for Working at height by Contractor's worker" & " Safety Procedure for Working at height by regular employee of plant/mines" respectively (under formulation)
- 10. HANDING AND TAKING OVER OF OXYGEN PIPELINES TO OPERATION DEPARTMENT
- 10.1 A proper protocol shall be drawn containing the compliance of the following points:
- 10.1.1 Certificates for welding works.
- 10.1.2 Reports of inspection of internal cleaning of the pipelines.
- 10.1.3 Reports of tests of accessories.
- 10.1.4 Reports of tests of pipelines on strength and tightness.
- 10.1.5 Log book of welding works.
- 10.1.6 Lists of welders who took part in welding works pointing numbers of their certificates and marks.
- 10.1.7 Reports of cleaning, flushing and blowing of the pipelines (including accessories).
- 10.1.8 Drawings of the pipelines, sketches explanatory notes.

#### APPENDIX-A


(Ref.Cl.3.2.5)

(Based on IPSS:1-06-035 (under formulation))

# CATHODIC PROTECTION FOR UNDER GROUND PIPELINES


- A-1 Cathodic protection systems reverse the electro-chemical corrosive force by creating an external circuit between the pipeline to be protected and an auxiliary anode (sacrificial metal) buried in the ground at a predetermined distance from the pipe. Direct current applied to the circuit is discharged from the anode surface and the travels through the surrounding electrolyte to the pipe (cathode) surface.
- A-2 Two (2) methods are available for generating a current of sufficient magnitude to guarantee protection. In the first method, sacrificial anode material such as magnesium or zinc is used to create galvanic cell. The electrical potential generated by the cell causes current to flow from the anode to the pipe, returning to the anode through a simple connecting wire (refer Fig 1A). This system is generally used where it is desirable to apply small amounts of current at a number of locations, most often on coated pipelines in lightly or moderately corrosive soils.
- A-3 The second method of current generation is to energize the circuit with an external DC power supply, such as rectifier. This technique, commonly referred to as the impressed current method, uses relatively inert anodes (usually graphite or silicon cast iron) connected to the positive terminal of a DC power supply, with the pipe connected to the negative terminal (refer Fig 1B). This system is generally used where large amount of current is required at relatively few locations, and in many cases it is more economical than sacrificial anodes.
- A-4 For cathodic protection, a corrosion survey including chemical-physical analysis of the soil must be performed along the pipeline.

C



CATHODIC PROTECTION - GALVANIC ANODE TYPE

(Ref. Appendix 'A' CL A-2)



EIG.-18

CATHODIC PROTECTION -- RECTIFIER TYPE

(Ref. Appendix 'A' CL A-3)

300

# APPENDIX-B " PROCEDURE FOR PICKLING AND PHOSPHATING" (Ref.Cl.5.3.2)

#### B-1 GENERAL

- B-1.1 Pickling is a chemical process for removal of rust, scale and other coatings from pipes, fittings etc. This is normally done by subjecting the surface of the material to be treated in an aqueous solution of an acid. To prevent the acid from attacking the base metal an inhibitor may be added. Pickling bares the metal of the surface treated which become highly acceptable to corrosion. This operation is, therefore, followed by an anti corrosion treatment which retards the corrosion of surface that have been pickled. Phosphating is one such chemical process which deposits a thin protective layer on the surface.
- B-1.2 The procedure given below is applicable for pickling and phosphate treatment of carbon steel pipes and components. The process requires the pipes to be immersed in vats/baths of adequate dimensions to take full lengths of pipes as supplied by the manufacturers/stockists. It also requires close supervision and availability of a chemical testing laboratory to assure that proper control is exercised during the process. Arrangements are also required for heating of the chemical solutions used for the treatment.

#### R-2 PROCEDURE

- B-2.1 Pre-cleaning
- B-2.1.1 The pipes and fittings as supplied are cleaned to remove surface contamination. First a high pressure water wash is to be given on both the internal and external surfaces. If the pipes as supplied contain excessive oil, grease or lacquer the same has to be first removed by cleaning the surface with an approved chemical solvent prepare the materials for pickling.
- B-2.2 Pickling
- B-2.2.1 Immerse each length of pipe in a solution of 18 to 20%. Hydraulic acid by volume having a inhibitor of stannine low foam or equivalent for a duration of atleast 10 minutes and not more than 20 minutes.
- B-2.2.2 Drain and wash in hot clean water.
- B-2.3 Phosphating
- B-2.3.1 Immerse the pickled pipes in the phosphating bath having solution with the following parameters:
  - i) Concentration of Pyroband 847 x 30-35 points.
  - ii) Bath temperature (phosphate) 60-75 Deg C. The duration of the immersion shall be between 15 to 20 minutes.
- B-2.3.2 Rinse the pipes im hot water bath maintained at 80 Deg C.
- B-2.3.3 The phosphating procedure and coating weight per sq. metre shall generally conform to IS 3618:1966 Phosphate treatment of Iron & Steel for protection against corrosion.
- B-2.3.4 It is recommended that a production test coupon is used with each batch during the phosphating process to ensure coating weight as per IS:3618.

# INTER PLANT STANDARDS - STEEL INDUSTRY

**AMENDMENT NO. 1 FEBRUARY 2001** 

TO

CODE OF PRACTICE FOR LAYING OF UNDERGROUND PIPELINES FOR WATER SERVICES, IPSS:1-06-035 (MAY 99)

# **ALTERATION**

[Page-1, clause 2.1 (ii)] - Rewrite as under:

**Ductile Iron -** "For conveyance of raw and drinking water from distant place, ductile iron pipes are also used"

Clause 7.5 - TEST PRESSURE - Rewrite as under :

All water pipe work as erected shall be tested at 1.5 times the Maximum working pressure of the pipe work or the pressure to which the pipeline shall be subjected under surge condition, whichever is higher.

									•
4				•					
*	•								
e de la companya de l									
				•				•	
•									•
			•	•				•	
								• .	· · · · · · · · · · · · · · · · · · ·
					•			•	
e. P								u in	
		(18 전 18 전		ing a salatai in sa Taga salatai in sa				Frank Configuration	
		•	2.* €			• .			
								٠.	
			. ,				•		
		•							
			•	•			• . •		
						•	•		
* <del>1</del>		. '			•				•
	• •		•	•					
		•						•	
		,				•		• . • .	
					•			in Sighter Again	
	na Propinsi na Propinsi na Propinsi na Pr	ja en trajaka ajabah Propinsi en en en engan en	electorist see						
			•						•
						• 4		• •	
						•		•	
				• •	~				
		•				•			
	•								
				* .					•
		٠.		•			·.	· ·	•
		•							
	•								
	* * * * *			*					