

Ø23.5

Ø 16

250

2.5

2.5/









JOB TITLE/HA3BAHNE PAGOTH: XXI-KPM-26-2-1000-18-ExtraNew

Адрес: 199034, Россия, Санкт-Петербург, В.О., 14 линия, д. 7. Тел.: +7(812)3202959 Контакт: info@psiglass.ru

SCALE/ масытаь:

DRAWING NUMBER/HOMEP YEPTEXA:

5017-LUG-1

KO/INHECTBO: QUANTITY/

> ДАТА: DATE/ ДИЗАЙНЕР: DESIGNER/

24.04.20

НАПЛАВКА: WELDING/ МАТЕРИА Л:

MATERIAL.


DATE/AATA


REVISIONS/U3MEHEHUS

STEEL


MACHINE/ MALJUHA:

EMHART GLASS-BB-DG-5 1/2"-8









1. Both halves of mould (A & B) must be marked with same ordinal number and used together.

ASSEMBLY NUMBER/

НОМЕР СБОРКИ: INVERT CENTRE/

ИНВЕРТ:

53

125

- 'H' DIMENSION/ 57.15 QUANTITY/PA3MEP 'H': (PACCTOSHINE OT OCH POPMI) DO BEPXHER 195KW) KO/NYECTBO:

2. Gap in mould joint must be not more than 0.05 mm.

1

REVISIONS/U3MEHEHU9

- 3. Positional tolerance of forming cavity axis T 0.1 mm. Base joint plane
- 4. Allowed deviation of forming cavity dimensions is not more than ±0.05 mm. except for dimensions that are specially shown.
- 5. Keep sharp edges P.
- 6. *Reference only dimensions
- 7. H14, h14, ±IT14/2.

24.04.20

DATE/ДАТА

- 8. Hardness after welding HRC335..40.
- 9. Mark: XXI-KPM-26-2-1000-18-ExtraNew Mark: 5017

Mark ordinal number (h=8) & PSI logo. Depth of marking-0.2...0.3 mm.

10. Cap holes with screws M8x8 and punch.

MACHINE/ MAШИНА:

DESIGNER/

ДИЗАЙНЕР:

DATE/ ДАТА:

EMHART GLASS-BB-DG 5 1/2"-8

24.04.20

11. Cap holes with screws M6x8 and punch.

CAST IRON (GS900)

Base and seams (HRC 35...40)

MATERIAL/ MATEPИA/I:

WELDING/

НАПЛАВКА:

	 	Α
		В
		Τ

Адрес: 199034, Россия, Санкт-Петерьэрг, В.О., 14 линия, д. 7. Тел: +7(812)3202959 Контакт: info@psiglass.ru

]B	TITL	E/H	43BAF	HUE F	Α	БОТЫ:	
	XX	I-KP	M-26	-2-1	00	00-18-ExtraNew	
RA۱	VING	NUM	BER/	HOME	P	ЧЕРТЕЖА:	

SCALE/ MACWTAB: DRA 5017-MLD3-2

1:1