JOB REPORT (sample form)

Customer: Northwind Bakery Date: 2026-10-24

Summary of work

Replaced the worn drive belt on the dough mixer, realigned both pulleys, and tested the mixer at all three speeds under full load for twenty minutes. Cleaned the motor housing and the cooling vents, tightened the guard bolts, and logged the serial numbers of the new parts. The customer was shown how to check belt tension each month and asked to call if the squeal comes back. Next visit: routine service in six months, or sooner if the oven door seal is replaced.

Work log

08:10 Arrived on site, met the shift lead and agreed on a two-hour window while the morning batch was cooling
08:25 Isolated power, removed guard
08:40 Belt cracked along its length; pulleys 2 mm out of line
09:15 Fitted new belt, realigned pulleys
09:45 Load test at speeds 1 to 3, no slip or noise
10:05 Cleaned vents, refitted guard, restored power and walked the shift lead through the monthly tension check

Parts used

Drive belt A-42 x1, guard bolts M6 x4, cable ties x6

Signed: J. Rivera