JOB REPORT (sample form)

Customer: Northwind Bakery Date: 2026-10-24

Summary of work

Replaced the v

Work log

08:10	Arrived on site, met the shift lead and agreed on a two-hour window while the
08:25	Isolated power, removed guard
08:40	Belt cracked along its length; pulleys 2 mm out of line
09:15	Fitted new belt, realigned pulleys
09:45	Load test at speeds 1 to 3, no slip or noise
10:05	Cleaned vents, refitted guard, restored power and walked the shift lead throu

Parts used

Drive belt A-42 x1, guard bo

Signed: J. Rivera