safety plan

Hot Glue:

 Is hot. It burns. Remove it from skin immediately and run water over it. Contact an instructor.

Soldering & Wire cutting:

- Always wear safety glasses when soldering or cutting wires. Eyes don't grow back.
- Keep long hair in ponytail holder. Burning hair stinks!
- Run water over burns and contact instructor.
- Wash hands after soldering.

Cuts:

- Contact instructor.
- Wash, neosporin, band aid.

Maker Rules:

- Be Cool, we are all here to have fun.
- Be Safe, getting hurt is not cool, or fun.
- Be Patient, ask a friend for help first.
- Be Persistent, you can figure it out!