

MES Routing Sheet Report

Report Date: 05-MAY-2026 00:23

IO ID BTM Main WH (F51)

PAPERLESS

Page 1 of 7

54990717

Job No: 54990717 		Item Description: LANDING SUB PART,LATCH RING CARRIER,36.000 X 2.000 WALL, 4130-CL 95 DIMENSIONS: A DIA. = 32.000 WEIGHT: 2,040 LBS. (CALC)	Qty: 4	Bill revision: A	06-FEB-26	00:00	Project No:
Cell Code :			UOM: EA	Routing revision: 0	22-APR-26	00:00	Project Name:
Assembly: H57437-23 			Scheduled Start: 04-MAR-26	23:48	Scheduled Finish: 05-MAR-26	07:22	Sales Order:
Serial No:	F51-54990717-1 to F51-54990717-4		Lot No:	NA			

Operation No : 1 		Operation Description: ROUTING PREPARATION		Scheduled Start: 04-MAR-26	23:48
		Department: ME	Operation Code / Machine: ME101	Scheduled Finish: 04-MAR-26	23:48
10 		WF ID # 5408 -SSWE- (OSP2) (REF. WF ID #4833, 4585) SO : 90000444 - SAFETY STOCK-DUMMY SO.1-PS-BTN SCOPE: MACHINING TO VENDOR & PHOSPHATE AT INHOUSE ----- EY, 23 APR 2026 NOTE : - MATERIAL SUPPLY: AS PER BOM ----- ME INSPECT .			
REVIEWED By Eka Yuzananda at 12:15 pm, May 05, 2026					

Requirements							
Component Item	Description	Supply			Date Required	UOM	Require d Quantity
		Type	Subinventory	Locator			
H450320-40	RAW-FORGE,STRAIGHT, 37.500 O	Push			04-Mar-2026	EA	4.00

Resource Seq:	Resource	Usage Rate	UOM	Basis	Operation Start Stamp/Date	Operation Complete Date/Stamp
---------------	----------	------------	-----	-------	----------------------------	-------------------------------

Operation No : 3 		Operation Description: QC IDENTIFY ITEMS		Scheduled Start: 04-MAR-26	23:48
		Department: QC	Operation Code / Machine: Q2000	Scheduled Finish: 04-MAR-26	23:48
10		QC VERIFY MATERIAL & DOCUMENTS ----- > MATERIAL SUPPLY AS PER MPL > MATERIAL SEND TO VENDOR QC INSPECT .			
20		* DOCUMENT:			

Job No: 54990717 		Item Description: LANDING SUB PART,LATCH RING CARRIER,36.000 X 2.000	Qty: 4	Bill revision:	A	06-FEB-26	00:00	Project No:
Cell Code :			UOM: EA	Routing revision:	0	22-APR-26	00:00	Project Name:
Assembly: H57437-23 			Scheduled Start: 04-MAR-26	23:48	Scheduled Finish: 05-MAR-26		07:22	Sales Order:
Serial No:	F51-54990717-1 to F51-54990717-4		Lot No:	NA				
		EPS H57437-23/A DWG AAAB29307/008 (H57437/008) VGS2.5.8/003 VGS2.6.1/4 QF-SS-BAT-QUA-087 REV 3.0 QF-SS-BAT-QUA-055 REV 3.0 VGS6.2.3/030 (F/R) VGS6.4.1/8 (F/R) =====						
		- HSE AWARENESS - (F/R): Document no need to print .						
Resource Seq:			Resource	Usage Rate	UOM	Basis	Operation Start Stamp/Date	Operation Complete Date/Stamp

Operation No : 400 		Operation Description: QC OUTGOING INSPECTION			Scheduled Start: 04-MAR-26		23:48		
		Department: QC	Operation Code / Machine: Q2000		Scheduled Finish: 04-MAR-26		23:48		
10		- QC CHECK & VERIFY PARTS BEFORE SEND PART TO VENDOR FOR MACHINING QC OUTGOING INSPECT .							
Resource Seq:				Resource	Usage Rate	UOM	Basis	Operation Start Stamp/Date	Operation Complete Date/Stamp

Operation No : 500 		Operation Description: OUTSIDE MACHINING		Scheduled Start: 04-MAR-26	23:48
		Department: OSP	Operation Code / Machine: OSP1/	Scheduled Finish: 04-MAR-26	23:48
10	* VENDOR TO MACHINE LANDING SUB 36 PER EPS H57437-23 & DWG H57437 SCOPE: MACHINING & COAT PER VGS6.4.1 (PHOSPHATE EXCLUDED, WILL PERFORM AT INHOUSE BH) STRESSLESS STAMP AS BELOW (on ▲E1 location per Drawing shown): P/N. H57437-23 REV A S/N. # - PO No.				

Job No: 54990717 		Item Description: LANDING SUB PART,LATCH RING CARRIER,36.000 X 2.000		Qty: 4	Bill revision:	A	06-FEB-26	00:00	Project No:
Cell Code :		WALL, 4130-CL 95 DIMENSIONS: A DIA. = 32.000 WEIGHT: 2,040 LBS. (CALC)		UOM: EA	Routing revision:	0	22-APR-26	00:00	Project Name:
Assembly: H57437-23 				Scheduled Start: 04-MAR-26	23:48	Scheduled Finish: 05-MAR-26		07:22	Sales Order:
Serial No:	F51-54990717-1 to F51-54990717-4			Lot No:	NA				
		NOTE: * VENDOR TO SUBMIT ALL MANUFACTURING REPORT TO BH PRIOR TO SHIPPING THE GOOD. QC INCOMING TO INSPECT .							

Resource Seq:	Resource	Usage Rate	UOM	Basis	Operation Start Stamp/Date	Operation Complete Date/Stamp
10 	X1001	1.00	EA	Run		

Operation No : 600 		Operation Description: CLEAN UP		Scheduled Start: 04-MAR-26	23:48
		Department: TA	Operation Code / Machine: TA00/B2002	Scheduled Finish: 05-MAR-26	00:36
10	- TA CLEAN UP PART FREE FROM COATING, GREASE, DEBRIS, STRANGER MATERIAL. (PRIOR QC INCOMING INSPECT) TS INSPECT .				

Resource Seq:	Resource	Usage Rate	UOM	Basis	Operation Start Stamp/Date	Operation Complete Date/Stamp
30 	LAB-TA1	0.20	HR	Run		

Job No: 54990717 		Item Description: LANDING SUB PART,LATCH RING CARRIER,36.000 X 2.000	Qty: 4	Bill revision:	A	06-FEB-26	00:00	Project No:
Cell Code :			UOM: EA	Routing revision:	0	22-APR-26	00:00	Project Name:
Assembly: H57437-23 			Scheduled Start: 04- MAR-26	23:48	Scheduled Finish: 05-MAR-26		07:22	Sales Order:
Serial No:	F51-54990717-1 to F51-54990717-4		Lot No:	NA				

Operation No : 700 		Operation Description: QC INCOMING INSPECTION			Scheduled Start: 05-MAR-26		00:36		
		Department: QC	Operation Code / Machine: QC101		Scheduled Finish: 05-MAR-26		00:36		
10		- QC INCOMING VERIFY, INSPECT PART & DOCUMENT AFTER RECEIVED FROM VENDOR. (PHOSPHATE EXCLUDED, WILL PERFORM AT INHOUSE BH) QC INCOMING INSPECT .							
Resource Seq:				Resource	Usage Rate	UOM	Basis	Operation Start Stamp/Date	Operation Complete Date/Stamp

Operation No : 3900 		Operation Description: CLEAN UP			Scheduled Start: 05-MAR-26		00:36		
		Department: TA	Operation Code / Machine: P3001		Scheduled Finish: 05-MAR-26		00:55		
10		PER VGS6.2.3 - CLEAN UP PARTS FROM OIL & ANY FOREIGN DEBRIS PRIOR TO PROCESS PHOSPHATING. TS INSPECT .							
Resource Seq:				Resource	Usage Rate	UOM	Basis	Operation Start Stamp/Date	Operation Complete Date/Stamp
30 				LAB-TA1	0.08	HR	Run		

Job No: 54990717 	Item Description: LANDING SUB PART,LATCH RING CARRIER,36.000 X 2.000	Qty: 4	Bill revision:	A	06-FEB-26	00:00	Project No:
Cell Code :	WALL, 4130-CL 95 DIMENSIONS: A DIA. = 32.000 WEIGHT: 2,040 LBS. (CALC)	UOM: EA	Routing revision:	0	22-APR-26	00:00	Project Name:
Assembly: H57437-23 		Scheduled Start: 04- MAR-26	23:48	Scheduled Finish: 05-MAR-26	07:22	Sales Order:	
Serial No:	F51-54990717-1 to F51-54990717-4	Lot No:	NA				

Operation No : 4000 		Operation Description: PHOSPHATING			Scheduled Start: 05-MAR-26		00:55		
		Department: TA	Operation Code / Machine: TA07/P3001		Scheduled Finish: 05-MAR-26		06:15		
10		PER EPS H57437-23 (PD#F) - PHOSPHATE PART PER VGS6.2.3.2 - PRIOR OILING QC NEED TO INSPECT ADHESIVE MATERIAL GRADE : 4130, 95KSI TS INSPECT .							
Resource Seq:				Resource	Usage Rate	UOM	Basis	Operation Start Stamp/Date	Operation Complete Date/Stamp
30 				LAB-TA1	1.33	HR	Run		

Operation No : 4100 		Operation Description: PHOSPHATING INSPECTION				Scheduled Start: 05-MAR-26		06:15		
		Department: QC	Operation Code / Machine: QC15/QC101			Scheduled Finish: 05-MAR-26		06:34		
10		PER VGS6.2.3 SEC 6.1.1, 6.1.2 & 6.2 - VISUAL INSPECT RESULT OF PHOSPHATING - ADHESION TEST PRIOR OILING & OILING INSPECTION QC INSPECT .								
Resource Seq:					Resource	Usage Rate	UOM	Basis	Operation Start Stamp/Date	Operation Complete Date/Stamp

Job No: 54990717 		Item Description: LANDING SUB PART,LATCH RING CARRIER,36.000 X 2.000		Qty: 4	Bill revision:	A	06-FEB-26	00:00	Project No:
Cell Code :		WALL, 4130-CL 95 DIMENSIONS: A DIA. = 32.000 WEIGHT: 2,040 LBS. (CALC)		UOM: EA	Routing revision:	0	22-APR-26	00:00	Project Name:
Assembly: H57437-23 				Scheduled Start: 04-MAR-26	23:48	Scheduled Finish: 05-MAR-26		07:22	Sales Order:
Serial No:	F51-54990717-1 to F51-54990717-4			Lot No:	NA				
30 				LAB-QC1	0.08	HR	Run		

Operation No : 9000 		Operation Description: STACKING & COATING		Scheduled Start: 05-MAR-26	06:34			
		Department: TA	Operation Code / Machine: B2002	Scheduled Finish: 05-MAR-26	06:58			
10	- STACKING LANDING SUB ON TO PALLET/SKID - COAT PER VGS6.4.1 TS INSPECT .							
Resource Seq:			Resource	Usage Rate	UOM	Basis	Operation Start Stamp/Date	Operation Complete Date/Stamp
30 			LAB-TA1	0.10	HR	Run		

Operation No : 9500 		Operation Description: FINAL INSPECTION		Scheduled Start: 05-MAR-26	06:58
		Department: QC	Operation Code / Machine: QC101	Scheduled Finish: 05-MAR-26	07:22
10	- QC VERIFY ALL PROCESS HAS COMPLETED & ACCEPTABLE - VERIFY TRACEABILITY, MARKING & DOCUMENTS QC INSPECT .				
20	MINI PACKET DATA BOOK: (DATE & SIGN) ----- .				
30	- GATE 2 VERIFYING				

Job No: 54990717 		Item Description: LANDING SUB PART,LATCH RING CARRIER,36.000 X 2.000		Qty: 4	Bill revision:	A	06-FEB-26	00:00	Project No:
Cell Code :		WALL, 4130-CL 95 DIMENSIONS: A DIA. = 32.000 WEIGHT: 2,040 LBS. (CALC)		UOM: EA	Routing revision:	0	22-APR-26	00:00	Project Name:
Assembly: H57437-23 				Scheduled Start: 04-MAR-26	23:48	Scheduled Finish: 05-MAR-26		07:22	Sales Order:
Serial No:	F51-54990717-1 to F51-54990717-4			Lot No:	NA				
		GCI INSPECT .							

Resource Seq:	Resource	Usage Rate	UOM	Basis	Operation Start Stamp/Date	Operation Complete Date/Stamp
30 	LAB-QC1	0.10	HR	Run		

Operation No : 9900 		Operation Description: TAKE TO STOCK		Scheduled Start: 05-MAR-26	07:22
		Department: WHS	Operation Code / Machine: W0000	Scheduled Finish: 05-MAR-26	07:22
10	- CLOSE WO & SUBCON PO WH INSPECT .				
20	WAREHOUSE RP RECEIVED DATE & SIGN _____ .				

Resource Seq:	Resource	Usage Rate	UOM	Basis	Operation Start Stamp/Date	Operation Complete Date/Stamp
---------------	----------	------------	-----	-------	----------------------------	-------------------------------