

MAINTENANCE NOTICE

The cooling loop on line 3 will be serviced on Friday. All sensors connected to junction box B must be powered down before 08:00. Contact the shift supervisor to confirm the lockout checklist has been completed and signed.