

Material: Brass Aluminium is not recommended (friction to the MVX-10-zoom axis becomes too high over time, part cannot be removed anymore)

		1			Date	Name			
				Drawn	26.01.2018	voiat	<u> </u>		
				Checked			Dynamixel-Adapter V2 (AL)		
				Standard			'		
		-							
							Servo-Dynamixel-Adapte <u>r-1V2</u>		
							A4		
State	Changes	Date	Name						