

Course Robots Repository

Maintenance Form

Robot Model: _____

Robot ID: 15

Maintained By: Allen Paily

Date: 2/13/26

Issue Being Investigated:

Wires on camera are disconnected

Fixes Attempted:

Attempted to solder wires back on to camera connector

Issues Resolved:

Camera works properly. Also seems that camera stability is fixed

Issues Discovered:

Stability issues with cameras might be due to loose wires in the connector pin

Additional Notes: