CC.2003/061986/23 Vat: 4650208780

Bank: Standard Bank Menlyn

Branch: 012345 Acc: 012747335

Ad-Hoc Plumbers cc PO Box 25437 GEZINA 0031

Tel: 012 331 5440 Fax: 012 331 5441
 Tax Invoice

 Date
 07/12/2013

 Page
 1

 Document No
 IN244271

FOGI

Deliver to POOLE M

ORDER NO:964351

DATE:07/12/2013

Account	Your Reference	Tax Exempt Tax Reference Sales Code			
FOGI	77895 - 16149	N	SA008		Inclusive
Code	Description	Quantity Unit	Unit Price Disc%	Tax	Nett Price
01	REPAIR TO BURST PIPE IN ROOF	1.00	127.72	15.68	127.72

EXCESS PAID R500.00

Sub Total	112.04
Discount @ 0.00%	0.00
Amount Excl Tax	112.04
Tax	15.68
Total	127.72

FOGI PLUMBING SOLUTIONS					
System	Actions				
EPC Report	Contact		3717371		
Reports	EPC PIP	E REPORT			
Claim Information					
Report Date	10 Dec 2013	Policy Type	Red I (Platinum 201		
Claim Date	07 Dec 2013	Policy Holder	POOLE M		
Order No	964351	Contractor	Ad-Hoc Plumbers		
Claim No	NED13156759		,		
Claim Detail					
Did you do any repairs?	Yes ® No ○	Claim Outcome	Repairs Coverec		
No Claim Reason	· · · · · · · · · · · · · · · · · · ·	Was income derived from anyone on this claim (excluding FAP)?	Yes○ No •		
	1	What purpose of the building?	Residential ·		
Comments	REPAIRED UNCONC GEYSER.	EALED PIPE IN ROOF, C	:LOSE TO		
Repair Information					
Intormation		Compuel			
Type of Repair	Unconcealed	General condition of this system	Poor		
Is it a reoccurring leak?	Yes○ No 🏵	Type of pipe or joint failed	Galvanised		
Size of pipe or joint replaced	20 - 25	Where is the failure?	IN ROOF CLOSE TO		
What was repaired?	Pipe	Was the Failure on Hot water pipe?	Yes○ No •		
Is the piping corroded / pitted / deteriorated?	Yes ● No ○	If tiles were damaged to gain access, does client have spare	1V/A		

127-72

of the damages that YOU created to effect the repair	Save Report	Submit Report Delo		
Brief description				
Was Leak Detection Done?	Yes○ No ⑨			!
Was there Damages cause by the Failure.	lYes⊕ No⊖	tiles to reinstate the repairs? Appoint a Prep Contractor to effect repairs to the access created by YOU?	Yes○ No ⑨	

Pipe Report

96,4351

EPC Report (D1)

Revision (01/01/2011)

fogi

Concealed Pipe Repair			
Type of repair	In brick/plaster/screed cavity/earth	In concrete	No Claim
Constal a system failed	Hot & Cold Water system		Overflow Pipes
Is it a recognizion of this system	Good	Fair	Poor
Type of pipe or joint foiled		Yes'	(No)
' The or pipe or joint railed		Copper	Poly
Size of pine or joint replaced		Other	
or joint replaced			28 -35
Brief description of repair		·	200 & Above
I STATE OF THE STA			usee in roof
	Was the failure on a het water all		Joint
	Is the piping correded/pitted?		6 0)'
Was there Damages caused by the	e Failure		No
Does resultant Contractor need to	be appointed to effect final finishing		No
Created by YOU	as appointed to effect mild mildfilling	res	(No)
Was Leak Detection Done?	Yes	<u> </u>	
Brief description of the damages the	nat YOU created to effect the repair	168	<u>(Vo2)</u>
	Does resultant Contractor need to created by YOU Was Leak Detection Done?	Type of repair What plumbing system failed General condition of this system Is it a reoccurring leak? Type of pipe or joint failed Size of pipe or joint replaced Brief description of repair What was repaired? Was the failure on a hot water pipe Is the piping corroded/pitted? Was there Damages caused by the Failure Does resultant Contractor need to be appointed to effect final finishing created by YOU	Type of repair What plumbing system failed General condition of this system Is it a reoccurring leak? Type of pipe or joint failed Galvanised Green of pipe or joint replaced Size of pipe or joint replaced Green of the system Size of pipe or joint replaced Galvanised Galvanised Copper UPVC Other Size of pipe or joint replaced 15 - 17 20 - 25 Brief description of repair Where? What was repaired? What was repaired? Was the failure on a hot water pipe Is the piping corroded/pitted? Was there Damages caused by the Failure Does resultant Contractor need to be appointed to effect final finishing Created by YOU Was Leak Detection Done?

Unblocking of Davi			
Unblocking of Drain			
1 Type of unblock	Without exposing	With exposing	No Claim
			110 Oldsii
ls it a reoccurring blockage		Yes	No
What caused the blockage			
What caused the blockage		Common Household Bi	ockane
		Broken/Collansed Pipe	/Collar
Type of pipe or joint failed			
Type of pipe of joint falled		Earthenware	uPVC
		Cast Iron	Other
Size of pipe or joint replaced			
s. p.po or joint replaced	40	50	75
	110	150	200 & Above
Was there Damages caused by the Fai	1		
Does resultant Contractor pood to be	ore	Yes	No
Does resultant Contractor need to be appointed to effect final finishing created by YOU		Yes	No
Was Leak Detection Done?			
Was Leak Detection Done? Brief description of the damages that YOU created to effect the repair		Yes	No
Toner description of the damages that You	OU created to effect the repair	3	

	Sanitary Ware Repair			
1	Item failed	Cistern mechanism	Basin	Acrylic shower base
 		Low level toilet	Basin & Pedestal	Other shower base
 	<u> </u>	Low level including Cistern	Sink / Prep Bowl	Baths
		Close couple toilet	Outlet - basin/sink	Outlets - baths
		Bidet	Cistern	Terminal fitting
ļ	<u> </u>	Outlet - toilet	Other	No Claim
2	Brief description of repair			
	oner description of repair	Where		
3	Man the D	Nature of failure		· · · · · · · · · · · · · · · · · · ·
	Was there Damages caused by the	Failure	Yes	No
4	Does resultant Contractor need to to created by YOU	be appointed to effect final finishing	Yes	No ·
5	Was Leak Detection Done?		Yes	
_6	Brief description of the damages that	at YOU created to effect the repair	162	No No

	Additional Notes			
	Why is it not a claim?	Repairs done not covered by Policy	No Repairs done	Repairs done Less than FAP
3	Was income derived from anyo Comments	ne on this claim?	Yes -	No

CETCING damages



No 77895

Reg. 2003/061986/23

Vat/Btw. 465 020 8780

Tel: 012 331 5440 Fax: 012 331 5441 Cell: 072 796 1313

804 Michael Brink street Villieria Pretoria PO Box 25437 Gezina 0031

Domestic, Commercial, Industrial

Th. 19 32-N		
CUSTOMER / KLIËNT FOOT -	BESTEL NR	
ADDRESS/ADRES 35 Carl D.	AVIES SHR	Eesterus
CLIENTS ID / KLIËNT ID		
VEHICLE REGNO. VOERTUIG REG NO.		24
TEL		
DATE / DATUM 07/12/2013	JOB CARD NO	D. 161(19
		10191
	·	
Repair to Bust	DIDE IN	CASH
,		R500-00
100/		7/12/2013
		107387
1x romm Cascada	Clamo.	
		
FERMS AND CONDITIONS (INCLUDING DEED OF	SURETY) ON OVERLEA	F 7
Therefore a second of the property of the		
Market of the Control of the Market of the M	Salvertay	
Juin Jew Lucas	nwastz	
All material All m	rs until paid in full	gargen in the del
() () () () () () () () () ()	· ·	
A -Hoc Plumbers accepts to responsibility for mate	rials under factory guara	ntee
	<u> </u>	
PAYMENTS STRICTLY C.O.D./ BETALING STRENG KBA EE CONDITIONS NO SERVEY OF SERVEY OF SERVEY	Cover charge / Heffing	gsfooi
Work Completed By Plumber PEW) Werk Voltooi Deur Loodgieter	Normal time / Normal	
Clientia Catinta di	Over time / O	`
Client's Satisfaction YES/JA NO/NEE NO/NEE	SUB TOTAL / SUB TOT	
Clients Approval Kliënt Goedkeuring	VAT /	
Geyser On Site Off Site	AMOUNT / BED	TRAG (
Consignment Stock YES/JA NØ/NEE	Cheque	Cash Account
	Cuntomode Si-	
Kwikhot Duratherm	Customer's Signatur	0

AD-HOC ACCEPT NO RESPONSIBILITY FOR MATERIALS UNDER FACTORY GUARANTEE.

BANKING DETAILS / BANK BESONDERHEDE



BANKING DETAILS / BANK BESONDERHEDE

V₀ 77895

Reg. 2003/061986/23

Vat/Btw. 465 020 8780

Tel: 012 331 5440 Fax: 012 331 5441 Cell: 072 796 1313

804 Michael Brink street Villieria Pretoria PO Box 25437 Gezina 0031

Domestic, Commercial, Industrial

	000000000000000000000000000000000000000	=1 ND
CUSTOMER / KLIËNT	ORDER NO / BESTE	
ADDRESS/ADRES 35 Carl D	AVIES SHE EE	esterus
CLIENTS ID / KLIËNT ID		
VEHICLE REGNO. VOERTUIG REG NO.		24
TEL		
DATE / DATUM 07/12/2013	JOB CARD NO.	6119
0		
Repair to Bust	0/08/10	CASA
		K 2000 -
roof		9/13/2013
		UNCI
1x romm Cascade	Clamo.	
40 3		
<u> </u>		
ERMS AND CONDITIONS (INCLUDING DEED OF	SURETY) ON OVERLEAF	
	Saturday	
Tuur Lean Kucas	umbers	
Ill material property of Ad-Hoc Plumbe	ers until paid in full	
-Hoc Plumbers accepts no responsibility for mat	erials under factory guarantee	
PAYMENTS STRICTLY C.O.D / BETALING STRENG KBA	Cover charge / Heffingsfooi	
Work Completed By Plumber LP(V)	Normal time / Normale fooi	-
Werk Voltooi Deur Loodgieter !	Over time / Oortyd	
Client's Satisfaction Kliënt Tevredenheid YES/JA NO/NEE	SUB TOTAL / SUB TOTAAL	
Clients Approval Kliënt Goedkeuring	VAT / BTW	
	AMOUNT / BEDRAG	
Geyser On Site Off Site	Cheque	Cash Account
Consignment Stock YES/JA NO/NEE		
Kwikhot Duratherm	Customer's Signature	

Standard Bank Gezina Account no/rek no. 012747335 Cheque acc/tjek rek. Bank code/kode 051001 Acc name/Rek naam. Ad-Hoc Plumbers

Deidre Dreyer

16149.

From:

acc@fogi.co.za

Sent:

07 December 2013 07:53 AM

To:

deidre@adhoc.co.za

Subject:

ClaimNo: NED13156759 PolicyNo: 0000637191034 CallCentreReferenceNo: R15675

OrderNo: 964351 PolicyHolder: POOLE M - Appointment

Provider Instruction Form

PLEASE CONTACT FOGI IMMEDIATELY IF YOU CANNOT ATTEND TO THIS CLIENT.

Organisation:

REDi Solutions (Pty) Ltd

Advisor:

Yamkela Zibobo

Tel:

0860 142 241

Fax:

011 361 1046

Email:

Yamkela.Zibobo@digicall.co.za

rolicy No:

0000637191034

Policy Type:

Platinum 2012

Claim No:

NED13156759

Call Centre Reference No:

R15675

Order No:

964351

Claim Date:

07 Dec 2013 07:44:12

Notification Date:

07 Dec 2013 07:48:37

Claim Limit Amount:

10000.00

FAP:

500.00

KINDLY NOTE: This policy has a LIMIT of R10000.00, the client has a standard FAP of R500.00. Your invoice can only be R9500.00 including vat and therefore any amount including vat over this total must be added to the FAP and collected from the Client.

Policy Holder:

POOLE M

Address:

35 CARLS DAVIDS EERSTERUST

City:

Pretoria

Home No:

084 442 2254

ork No:

cell No:

072 942 0852

Job Type: Plumbing

Plumbing Failure: Date Of Loss: 07 Dec 2013 - Leaking or Burst Geyser

Plumber: Ad-Hoc Plumbers Person: Kallie / Thea Tel: 072 796 1313

08:21 - P Enige tyd.

Typ Lell cold.

PLUMBING CLEARANCE CERTIFICATE (A 2)

Revision (14/11/2012)

Signature



IMPORTANT INFORMATION

- This document must only be completed when all PLUMBING repairs have been satisfactorily concluded by the PLUMBING Contractor appointed to carry out the PLUMBING portion of your claim.
- Your answers to the SERVICE QUESTIONNAIRE are monitored by the Insurance Company.
- 3. Any insured item that has been replaced such as geyser, valve, etc, is regarded as SALVAGE in terms of your policy and therefore is the property of the Insurance Company.
- 4. It is COMMON PRACTICE to leave the failed geyser in its current location, provided it is properly drained, this to avoid the dismantling the roof or other part of the building.
- 5. By this notice, the Insured is informed that, in terms of the Occupational Health and Safety Act 1993, it is the responsibility of the Insured to install an electrical ISOLATING DEVICE in accordance with SANS 10142 at each operational Hot Water Cylinder on the premises. The Insurance Company takes no responsibility and will not be liable for any loss or damages caused to anyone or anything because of the absence of the isolating device.
- 6. Please note that reinstatement of tiles, sanitary ware or cupboards which were dismantled or broken to enable a repair, will be rectified using similar item(s) should the same item(s) no longer be available.
- 7. SHOULD YOUR INSURANCE POLICY BE INACTIVE, PAYMENT OF THE REMEDIAL WORK WILL BE FOR YOUR ACCOUNT AND PAYABLE TO FOGI.

CLAIM DETAILS (Please use a black pen and write inside the boxes)

FOGI Order No	964351				
Insurance Claim No	NE013156750	>			
Date Work Completed	61122013	1			/
 Rate the performance of the PLU Did the Plumber gain access thro Did you settle the first amount pa 	URANCE CLAIMS REPRESENTATIVE. IMBER who carried out the remedial work. Bugh the roof and not the ceiling? Implication yable (Excess) with the plumber? Implication carried out?	Yes Yes Yes	Fair Fair No No	Poor Neutral N/A N/A	Poor
	n 2 or Yes to Question 6 above please c		elow:		
		 			
FURTHER COMMENTS AND ARRA	ANGEMENTS:				
Insured Name Poole	D-1-	· · · · · · · · · · · · · · · · · · ·	07-1	2-2013;	
	——— Date		<u> </u>	2 20131	

Please note that you may contact the plumbing contractor should the plumbing work performed by them develop a malfunction.

Insurance Clearance Code



Company RegNo: 2003/061986/23

VAT No: 4650208780

COMPUTER CENERATED

TAX INVOICE

Invoice To:

Digicall FOGI Plumbing Solutions

PO Box 30979

Tokai 7966

VAT No:

4720192592

Invoice No:

Invoice No:

IN244271

Insured:

11 December 2013 POOLE M

Order No:

964351

DESCRIPTION	AMOUNT
EPC Pipe - Unconcealed Pipe repairs EPC Pipe - STANDARD AFTER HRS LABOUR	475.00 75.63
Total excluding VAT VAT	550.63 77.09
Total including VAT Less Excess	627.72 -500.00
Amount due	127.72