CC.2003/061986/23

Vat: 4650208780 Bank: Standard Bank Menlyn

Branch: 012345

Ad-Hoc Plumbers cc PO Box 25437 GEZINA 0031 Tel: 012 331 5440

Fax: 012 331 5441

Acc: 012747335

Tax inv	/olce
Date	11/06/2013
Page	1
Document No	IN239027

FOGI

Deliver to WILSON

ORDER NO:904342

DATE:11/06/2013

Account	Your Reference	Tax Exempt Tax Refer	rence Sales Code		
FOGI	72933 - 9444	N	SA017		Inclusive
Code	Description	Quantity Unit	Unit Price Disc%	Тах	Nett Price
01	CALL-OUT ONLY	1.00	438.90	53.90	438.90

AD-Hoc Projects services building,painting,paving, Contact: 079 209 0014. Received in good order Signed_ Date_

Sub Total		385.00
Discount @	0.00%	0.00
Amount Excl Ta	ЭX	385.00
Tax		53.90
Total		438.90

JOBCARD

CASE NUMBER: 9444

Despatcher: Amanda

Address: Randjesfontein Estate

63 Bally James Duff ave

Midrand

Logged: 10 Jun 2013 06:00

Contact: Mrs Wilson - 0823000212

Access Amount: R0 Cash

Nature of call: Geyser Repairs - Leaking Geyser

Other: 200lt solar

Client: Wilson (ID No)

Email Address:

Category: Fogi

Order No: 904342

Policy No: 6526358818

Claim No: 2397042

Reference No:

Payment Method: Account

Notes: Deidre (07 Jun 2013 15:29): Notification Date: 07 Jun 2013 14:22:28 Replacement FAP:

500.00 Repair FAP: 250.00 Policy Holder: WILSON Address: 63 BALLY JAMES DUFF AVENUE RANDJESFONTEIN ESTATE City: MIDRAND Home No: 082 459 1954 Work No: Cell No: 082 300 0212 Job Type: Solar Plumbing Failure: Date Of Loss: 25 May 2013 - GEYSER IS LEAKING

(SOLAR 200 L

Gerda (11 Jun 2013 08:47): J/nr: 72933 Klient se solar geyser het gebars - Selmate 200 - KCE

1018-0076

Vehicle: WRC837GP

Crew 1: Wayne

Crew 2: Wayne

904342 "DIGICALL FOGI PLUMBING SOLUTIONS

No Cover Instruction or EGC Report (G 3) Revision (13/02/2013)

	Date:	Ord No:			Claim	No:		_				Clai	m Nan	ne:						
L	1 Electric Geyser Details																			
L	Manufacturer &	Brand									Τ				_	T				
L	Size										1	50	T 10	o T	150	20	00	250	\top	other
L	Actual size (if ot	her is selected)									\top		1				لــــــــــــــــــــــــــــــــــــــ			Other
L	Geyser Code &								•		+	Code	, .			ļ <u>:</u>	Serial			
L		tag per Annex A5							~		1									
L	Geyser Pressure										 	100	Τ	200	40	00	1	500	Ğ	ravity
L	Geyser Position										 									,,
L		eyser installed to 5	SANS	10254?							\top	• • •	Yes	3				No		
2											·					Ł				
L	Manufacturer &																			
L	code and serial	number										Code	,				Serial			
L	Output in kW										7~~	3.2	3.	5.	5.2	7	.0	,		
L	Type of Heat pur												integr	ral				Split		
L	Heat Pump insta			·									Insid	le				Outsi	de	
Ļ		stalled to SANS 1:	352?										Yes	3				No		
3	-7																			
H	Solar System he											D ir	ect)		Indi	irect		Pi	e-hea	ater
┝	Solar system Co											S	olit		Close	coup	le)		ntegr	ral
┝	Solar system Tra				···	_				-	 		Pump					ermo s		P
┝	Manufacturer &	Brand									 -	- //	Electric			<u> </u>	P	hotovo	ltaic	
ļ	Size	Di ariu			:						∤≥		pal		150	_				
_	Actual size (if oth	ner is selected)									╁	50	10	0	150	(21	לטנ	250		other
	Solar Geyser Co	de & Serial No			-		·· -			•	╁	Code	. 1			١.,	Sorial	VC E		·C. –
	Record Date on	tag per Annex H					_		_	•	+	0000	1			<u></u>	OGITAL	<u>rc</u> <u></u>		18- 576
	System Pressure	rating (kPa)			₩ 	X	, (VC	2		\top	100	\top	200	(40	700	1 6	500	$\overline{}$	ravity
	System Position				_						10	کر بر در	cole							
	Collector Manufa	cturer				٠.			~ C	`	Q		ct/L	200	<u>ン</u>					
_	Collector type				15	C	KV/), F	_		Εv	acuate	d tube		[Flat Pl	ate)	
_		and tubes/manifo					1001 F				Manifold					Tubes				
-		ate collectors and					_				Oty				ļ. <u></u>	Size 2 184×1100×212				
		sition of the Solar			S	S	7	$^{\prime}C$	Ce 1		9	s de		lo	lade	C747.	e/			
_		nstalled to SANS					_				Yes				<u> </u>	No				
4	General Informa	ing used for any t	usine	ss or comm	ioi ciai pur	pose	9?						Yes	·				No		
_			failure	2		 ,	Cornet		No Don				Descri							
	What is the overa	Resultant damaged caused by the failure? Carpet No Damaged Carpet Source Carpet No Damaged Carpet				iage			Resul			ļ	Hest	litant 8		pet				
		all condition of the			oof?	G000			Fair Fair						Poo					
	What is the overa	all condition of the	piping	in the roof	?	Good			Fair					Poor						
	11	itive geysers insta				1			2				. · u	•		L				
		nected to another	devic	:e?		(So	lar Colle	ctor	> Hea	at Pum	р	In Para	Ilel	In Ser	ies	Oth	ner de	vice	TN	No.
_	Is System balance												Ι.		Yes>	•			No	
4	What PRV is inst	alled?				Old	PRV -	Mak	е			kPa	1	Vew Pf	RV - Ma	ike			k	Pa
5	Type of Failure							,												
\dashv	Components	Electric Geyser			Baffle	Ele	ment			Therm	10	TP		her/TP	The	r/Ele		ocket		ect
ļ		Electric geyser &		D.Cock	Baffle		Elem			asket		Thern		TP		$\overline{}$	er/TP		Ther	/Ele
-				Pocket D.Cock	Elect	=1-	Twin	7		Conbo		LongF		Difus			Pum		т	
		Solar System			Baffle TPConbo	—	ment			Therm		TP		her/TF		r/Ele		cket	Ele	ect
J	Overflows			TP	11 COUNT	LLUI	INI II	ווטו	Relief	COHEC	<u></u>	IAUPU	IIID L	CPum In	<u>p (PV)</u> Drip Tra	^a nel	(Al	rRel		
	Valves	Electric Geyser	_	NRV	PRV	Ti	Relief		VB	Sh	nutof	f	Straine		RV Ca		Finat	valve		
\Box		Electric gevser &	HP_I	NRV	PRV	_	Relief		VB.		utof		Straine		RV Ca		Temp		AntiF	reeze
-		Solar System		NRV	PRV	Relief VB		VB.	S	nutoff Stra		Straine	iner PRV C		Cart					
	Warranty	Electric Geyser		D.Cock NRV	Baffle PRV	_	Element Relief		Gaske VB		erm utof		P		ocket	_	Geyse		E14 - 1	
1			1	D.Cock	Baffle		Elem	ent		asket	<u>iuiO</u> [Thern	Straine 10	T IF	PRV Ca		Float eyser		Elect	
	Electric geyser & I						Twin	PDC	TI	Conb	Ó	Long	PTP	Difus	er	AÇ	Pum			reeze
7				NRV PRV			Relie		VI Coeko		Ther	Shuto		Strai	ner		V Ca	rt	Tem	pValv
		D.Cock Baffle TwinPDC TPConbo									TP PVPa	Panel SolGeys					IDC	Pump		
\dashv	NRV PRV Relief			VB		Control PVPanel SolGev Shutoff Strainer PRV C														
	Other Failure		E	ElectricGey	ser HP				SolarGe	eyser		Collec			SolarS			Othe		
6	Additional Note:	S	TV-	15		Ι_														
Did you do any repairs				ot co	vered			less tha							<u>.</u>					
ا			No	FAP lap	sed	R	epairs r	ot co	vered	Clie	ent to be cash Not plumbing					Clien	t repai	r ther	nselves	
+	Did you derive income from client or manufacturer										Client repair themselves									
J	Did you derive inc	come from client o	r man	nufacturer									Yes			- 1		1	Vo.	



No. 72933

Tel: 012 331 5440 Fax: 012 331 5441 Cell: 072 796 1313

Vat/Btw. 465 020 8780

804 Michael Brink street Villieria Pretoria PO Box 25437 Gezina 0031

Domestic, Commercial, Industrial

CUSTOMER / KLIËNT	ORDER NO / BES	STELNR 5444	
	mes Duff are	Rand whitein	
CLIENTS ID / KLIËNT ID	0	00	
VEHICLE REGNO. VOERTUIG REG NO.			24
TEL		·	1.0
DATE/DATUM 10 June. 2013	JOB CARD NO.		
STANIA REPORT AND A STANIA	MENZIONIZAN	100	160
Rheit de solor ge gelas.	yser het	Schmote 2000 KCE 1018-00	76
est fly troffetor de	Tan Tan		
NJ W		-	
PAYMENTS STRICTLY C.O.D / BETALING STRENG KBA EE CONDITIONS ON OVERLEAF / SIEN VOORWAARDES OP KEERSY Work Completed By Plumber Werk Voltooi Deur Loodgieter	Normal time / Normale fo	oi i	
Client's Satisfaction	Over time / Oorty		
Kliënt Tevredenheid YES/JA NO/NEE	SUB TOTAL / SUB TOTAL VAT / BT		
Kliënt Goedkeuring	AMOUNT / BEDRA	——————————————————————————————————————	
Geyser On Site Off Site			
Consignment Stock YES/JA NO/NEE	Cheque	Cosh	
Kwikhot Duratherm	Crieque	Cash Acco	ount

STRICTLY C.O.D AND ALL MATERIALS REMAIN THE PROPERTY OF AD-HOC PLUMBERS UNTIL PAID IN FULL AD-HOC ACCEPT NO RESPONSIBILITY FOR MATERIALS UNDER FACTORY GUARANTEE.

BANKING DETAILS / BANK BESONDERHEDE

Deidre Dreyer

From:

misc@fogi.co.za

Sent:

07 June 2013 02:24 PM

To:

deidre@adhoc.co.za

Subject:

ClaimNo: 2397042 PolicyNo: 6526358818 CallCentreReferenceNo: OrderNo: 904342

PolicyHolder: WILSON - Appointment

Provider Instruction Form

PLEASE CONTACT FOGI IMMEDIATELY IF YOU CANNOT ATTEND TO THIS CLIENT.

Organisation:

Absa Insurance Services Ltd [Private Bank]

Advisor:

Claims Department - Private Bank

Tel:

0860 112 229

Fax:

Email:

aicprivatebank2@absa.co.za

olicy No:

6526358818

Policy Type:

HOC June 11

Claim No:

2397042

Order No:

Call Centre Reference No: 904342

Claim Date:

07 Jun 2013 14:11:11

Notification Date:

07 Jun 2013 14:22:28

Replacement FAP:

500.00

Repair FAP:

250.00

Policy Holder:

Address:

City:

MIDRAND

Home No:

Work No:

Cell No:

082 300 0212

Job Type: Solar

Plumbing Failure: Date Of Loss: 25 May 2013 - GEYSER IS LEAKING (SOLAR 200 L

Plumber: Ad-Hoc Plumbers cc Person: Kallie / Thea Tel: 072 796 1313

Deidre Dreyer

From:

misc@fogi.co.za

Sent: To:

07 June 2013 02:24 PM

deidre@adhoc.co.za

Subject:

ClaimNo: 2397042 PolicyNo: 6526358818 CallCentreReferenceNo: OrderNo: 904342

PolicyHolder: WILSON - Appointment

Provider Instruction Form

PLEASE CONTACT FOGI IMMEDIATELY IF YOU CANNOT ATTEND TO THIS CLIENT.

Organisation:

Absa Insurance Services Ltd [Private Bank]

Advisor:

Claims Department - Private Bank

Tel:

0860 112 229

Fax:

Email:

aicprivatebank2@absa.co.za

olicy No:

6526358818

Policy Type:

HOC June 11

Claim No:

2397042

Call Centre Reference No:

Order No:

904342

Claim Date:

07 Jun 2013 14:11:11

Notification Date:

07 Jun 2013 14:22:28

Replacement FAP: Repair FAP:

500.00 250.00

Policy Holder:

WILSON

Address:

63 BALLY JAMES DUFF AVENUE RANDJESFONTEIN ESTATE

City:

MIDRAND

Home No:

082 459 1954

Work No:

Cell No:

082 300 0212

Job Type: Solar

Plumbing Failure: Date Of Loss: 25 May 2013 - GEYSER IS LEAKING (SOLAR 200 L

Plumber: Ad-Hoc Plumbers cc Person: Kallie / Thea Tel: 072 796 1313

PLUMBING CLEARANCE CERTIFICATE (A 2)

Revision (14/11/2012)

IMPORTANT INFORMATION





- 1. This document must only be completed when all PLUMBING repairs have been satisfactorily concluded by the PLUMBING Contractor appointed to carry out the PLUMBING portion of your claim.
- 2. Your answers to the SERVICE QUESTIONNAIRE are monitored by the Insurance Company.
- 3. Any insured item that has been replaced such as geyser, valve, etc, is regarded as SALVAGE in terms of your policy and therefore is the property of the Insurance Company.
- 4. It is COMMON PRACTICE to leave the failed geyser in its current location, provided it is properly drained, this to avoid the dismantling the roof or other part of the building.
- 5. By this notice, the Insured is informed that, in terms of the Occupational Health and Safety Act 1993, it is the responsibility of the Insured to install an electrical ISOLATING DEVICE in accordance with SANS 10142 at each operational Hot Water Cylinder on the premises. The Insurance Company takes no responsibility and will not be liable for any loss or damages caused to anyone or anything because of the absence of the isolating device.
- 6. Please note that reinstatement of tiles, sanitary ware or cupboards which were dismantled or broken to enable a repair, will be rectified using similar item(s) should the same item(s) no longer be available.
- SHOULD YOUR INSURANCE POLICY BE INACTIVE, PAYMENT OF THE REMEDIAL WORK WILL BE FOR YOUR ACCOUNT AND PAYABLE TO FOGI.

CLAIM DETAILS (Please use a black pen and write inside the boxes)

FOGI Order No

Insurance Claim No

Date Work Completed

SERVICE QUESTIONNAIRE

(Scratch out the word in the appropriate box and ensure that it is not visible.)

1. Rate the performance of the INSURANCE CLAIMS REPRE	SENTATIVE. Good Fair Poor
2. Rate the performance of the PLUMBER who carried out the	remedial work. Good Fair Neutral Poor
3. Did the Plumber gain access through the roof and not the ce	eiling? Yes No N/A
4. Did you settle the first amount payable (Excess) with the plu	ımber? Yes No N/A
5. In the instance of a concealed pipe leak was leak detection	carried out? Yes No N/A
6. Did the plumber accidentally damage your property?	Yes No
If you answered POOR to Question 2 or Yes to Question 6 a	above please comment below:
FURTHER COMMENTS AND ARRANGEMENTS:	
	ate
Signature 3/15or In	surance Clearance Code

Please note that you may contact the plumbing contractor should the plumbing work performed by them develop a malfunction.



Company RegNo: 2003/061986/23

VAT No: 4650208780

COMPUTER OFFICEATED

TAX INVOICE

Invoice To:

FOGI Pty Ltd

PO Box 30979

Tokai 7966

VAT No:

4720192592

Invoice No:

IN239027

Invoice Date:

19 June 2013

Insured:

WILSON

Order No:

904342

DESCRIPTION	AMOUNT
EGC - No Claim - Plumber	385.00
Total excluding VAT	385.00
VAT	53.90
Total including VAT	438.90
Amount due	438.90