




RMSE_T (°C)

comfort violation (%)

 m_s 

MORL observation-interface ablation: 5D failure (rerun & frozen audit) → 17D success