Fractional-kW Motors and DC Machines



Lecture No. 46 DC Machines – Principle and Construction

Lecture delivered by:



Objectives

At the end of this lecture, student will be able to:

- Explain the basic principle of induced E.M.F. and electromagnetic torque
- Discuss the need for commutator
- Identify different parts of a DC machine and understand their function



Topics


- Fleming's left-hand rule
- The Action of a Commutator
- D.C. Machine Construction
- Principle of operation of a simple DC Motor
- Back e.m.f



Introduction


- Motor converts electrical energy into mechanical energy
- Generator converts mechanical energy to electrical energy

Brushed DC Motor
Anatomy






Introduction





Fleming's left-hand rule

Left Hand Rule




First finger - Field


Second finger - Current

Thumb - Motion



Fleming's Right-hand rule






First finger—Field

Thumb—Motion

Second finger—E.m.f.




Generation Principle





The Action of a Commutator

 In an electric motor, conductors rotate in a uniform magnetic field.






The Action of a Commutator

 For rotation to continue in the same direction, it is necessary for the current flow to be as shown in Figure, i.e. from D to C and from F to E. This apparent reversal in the direction of current flow is achieved by a process called


commutation





D.C. Machine Construction

The basic parts of any d.c. machine are shown in Figure





D.C. Machine Construction

- a) a stationary part called the stator having,
 - I. a steel ring called the yoke, to which are attached
 - II. the magnetic poles, around which are the
 - III. field windings, i.e. many turns of a conductor wound round the pole core; current passing through this conductor creates an electromagnet




D.C. Machine Construction

- A rotating part called the armature mounted in bearings housed in the stator and having,
 - I. Yoke
 - II. armature winding
 - III. Commutator
- Armature windings can be divided into two groups,
 These are called wave windings and lap windings




Wave and Lap Windings

- In wave windings there are two paths in parallel irrespective of the number of poles. Wave wound generators produce high voltage, low current outputs
- In lap windings there are as many paths in parallel as the machine has poles. Lap wound generators produce high current, low voltage output.



Principle of operation of a simple DC Motor





Principle of operation of a simple DC Motor

- Force F to be exerted on the current-carrying conductor which, by Fleming's left-hand rule, is downwards between points A and B and upward between C and D for the current direction shown
- The current direction is reversed every time the coil swings through the vertical position and thus the coil rotates anti-clockwise for as long as the current



Back e.m.f.

 When a DC motor rotates, an e.m.f. is induced in the armature conductors. By Lenz's law this induced e.m.f. E opposes the supply voltage V and is called a back e.m.f., and the supply voltage, V is given by

$$V = E + I_a R_a$$
 or $E = V - I_a R_a$



Summary

- DC Machines work on the principle of Faraday's law,
 Flemings Left Hand and Flemings Right Hand rule
- DC Motor and Generator have same construction
- Commutator is essential for Motor to have unidirectional rotation
- Commutator is essential for Generator to have unidirectional emf at the terminal

