# IOBILE SHOP

Professional Mobile Automotive Service

Ø=Üç contact@mobileshop.com | Ø=ÜÞ (555) 123-4567 | Ø<ß www.mobileshop.com

# **WORK ORDER**

Work Order #

W@ate:509-0001

9/24/2025

Status:

**PENDIN G APPRO** 

VAL

### Ø=Üd CUSTOMER INFORMATION

Name: James Fernandez

Email: jamesfernandezone@gmail.com

Phone: 4845023620

205 Dutts Mill E, West Chester, PA Address:

19382

#### Ø=b-VEHICLE INFORMATION

Vehicle: 1997 Oldsmobile 88

VIN: 1G3HN52K8V4862978

**License:** 15-2524L Mileage: 148830

## Ø=Ý' SERVICE DETAILS

Service Description: Subframe Woes

Load metal creaking coming from bottom of vehicle, especially when the car **Customer Complaints:** 

Diagnosis: Subframe is rusted through where the bushings mount to the unibody. All the bushings are

shot as well.

med: Front subframe R&R. All 6 subframe bushings, as well as all 4 control arm bushings Work Performed:

R&R.

#### LABOR

Subframe R&R: 6 hrs @ \$80/hr = \$480.00

#### **PARTS**

Subframe Poly Bushings: 4 @ \$80.00 = \$320.00 Control Arm poly bushings: 4 @ \$50.00 = \$200.00

Front subframe: 1 @ \$850.00 = \$850.00

**TOTALS** 

Subtotal: \$1850.00 Tax (6.0%): \$111.00

**TOTAL: \$1961.00** 

Professional Mobile Automotive Service | contact@mobileshop.com | (555) 123-4567 | www.mobileshop.com

Document generated on 9/24/2025, 1:44:24 PM