
Quick start instructions:

Run: 'python3 Alves-Zach-proj.py`

Best parameters






Overshoot parameters

PI controller

Kp = 1.0

Ki = 0.1



New task parameters

Cube starting position x: 0.5 y: 0.5 phi: 0
Cube final position

x: -0.5 y: -1 phi: -1.570796

P controller Kp = 1.0 Ki = 0.0

