



VEHICLE TECHNICAL VALUATION REPORT

Corporate Ref. No.	CORP123	Customer Email	john@doe.com	ID No./Passport	12345678
Box Number	P.O Box 12345	KRA PIN	A879W0213364U	Driving License No	K1234567B
SERIAL No	VINW012345	ISSUED BY	Automobile Valuers And Assessors, Utawala		

This report is based on a brief external inspection and takes no account of any but most obvious mechanical defects. A brief examination and road test has been carried out on the vehicle described below, the findings are as follows;

REGISTRATION NO	KCM 514K	CHASSIS NO	chas12346	COLOUR	Red
NO OF AIRBAGS	2 Airbags	YEAR OF MANF.	2010	MAKE	Toyota
ENGINE RATING	1800 CC	ENGINE NO	ENG123	ODOMETER-CURRENT READING	185000
TYPES OF LIGHTS	LED Headlights and Brake lights	DATE OF REG.		TYPE	AUTO 5 SEATER S/WAGON
FUEL TYPE	Petrol				

Coachwork					
Accident Repairs Noted?	Yes	Is Paint work Scratched/ Faded/ Dented?	Yes	Has the body had a complete respray?	Yes
Accident Damages noted?	No	Are inner wings repaired or damaged?	No	Is Upholstery Torn/faded/worn out?	No
Are roof linings damaged or repaired?	N/A	Are Bumpers/ Outer Wing repaired?	N/A	Is the Chassis kinked or damaged?	N/A

Mechanical condition					
Is the parking brake effective?	Yes	Is the automatic/manual gearbox okay?	Yes	Is the cooling system operating well?	Yes
Is the braking system okay?	Yes	Is the steering system okay?	Yes	Are there signs of fluid or oil leakage?	No
Are the drive shafts/cv joints worn out?	No	Is the suspension system okay?	No	Are engine mountings worn out?	N/A

Electrical condition					
Do the indicator lights operate well?	Yes	Do the brake lights operate well?	Yes	Are the headlights operating well?	Yes
Are the wipers operating well?	Yes	Are the headlights operating well?	Yes		
Do the instrument panel lights work well?	No				

Coachwork notes	Minor scratches on the right side, cracked rear bumper, scratches noted on doors, wings and bumpers.		
Electrical notes	Instrument panel lights flicker occasionally		
Mechanical notes	Suspension system needs attention, worn out arm bushes, engine and gearbox mountings		
Extras	AC, ABS, Alloy rims, Fog Lamps, Xenon Lights, Side Mirror Indicator, Wing Indicator, Wind Breakers, Tint Windows, Car Identity, CDL, Cup Holder, 2 Cut Off, Rear Disk brakes, Rear Spoiler with high mounted brake lights, Rear Wiper, Roof aerial, Head rest, Foot Rest, Arm Rest, Digital Odometer, Dual SRS Airbags, Inbuilt R/CD/TV Player, Paddle shifters, Power mirror, Power Steering, Power Window, Sun Visors, Tiptronic Gearbox, Telescopic Bonnet Damper, Wood Print Finish,		
Anti theft	CAR ALARM		
Tyres	4 GOODYEAR TYRES 225/65R17 AND BRIDGESTONE T165/80R17 DONUT SPAREWHEEL ALL OF GOOD THREAD DEPTH		
General condition	Fair	Assessed value	850,000 /= (Eight Hundred And Fifty Thousand, Shillings Only)
Radio estimate	20000	Windscreen estimate	60000

Remarks	Assessed value consistent with low usage.		
N.B	N/A		
Remedy	Recommended suspension system repair and respray the affected panels, replace worn out arm bushes, engine and gearbox mountings.		
Country of origin	Japan	Date of inspection	2023-05-15
Examiner	John Valuer	Destination	MUA Insurance
Lcation of inspection	Nairobi, Kenya	Amendment:	None
Signed	John Doe	Receipt No:	REC12345
NB: This Report reflects the estimated Market Value of the subject vehicle in its present condition, at the time of valuation. Any future assessment will take into account any changes in the meantime, due to usage e.t.c. This report is based on information on the logbook/importation documents.			



