



Automobile Valuers And Assessors Ltd

VEHICLE TECHNICAL VALUATION REPORT



Corporate Ref. No.: CORP123 Customer Email: john@doe.com ID No./Passport: 12345678 Box Number: P.O Box 12345 KRA PIN: A879W0213364U

Driving License No: K1234567B SERIAL No: VINW012345 ISSUED BY: Automobile Valuers And Assessors, Utawala CLIENT NAME: John Doe

CONTACTS: +254 712 345 678 INSURER: MUA Insurance POLICY NO.: PL45678 EXPIRY DATE: 2023-12-31

This report is based on a brief external inspection and takes no account of any but most obvious mechanical defects. A brief examination and road test has been carried out on the vehicle described below; the findings are as follows;

REGISTRATION NO: KCM 514K	MAKE: Toyota	TYPES OF LIGHTS: LED Headlights and Brake lights
CHASSIS NO: chas12346	ENGINE RATING: 1800 CC	DATE OF REG.:
COLOUR: Red	ENGINE NO: ENG123	TYPE: AUTO 5 SEATER S/WAGON
NO OF AIRBAGS: 2 Airbags	ODOMETER-CURRENT READING: 185000	FUEL TYPE: Petrol
YEAR OF MANF: 2010		

Coachwork

Accident Repairs Noted? Yes	Is Paint work Scratched/ Faded/ Dented? Yes	Has the body had a complete respray? Yes
Accident Damages noted? No	Are inner wings repaired or damaged? No	Is Upholstery Torn/faded/worn out? No
Are roof linings damaged or repaired? N/A	Are Bumpers/ Outer Wing repaired? N/A	Is the Chassis kinked or damaged? N/A

Mechanical Condition

Is the parking brake effective? Yes	Is the automatic/manual gearbox okay? Yes	Is the cooling system operating well? Yes
Is the braking system okay? Yes	Is the steering system okay? Yes	Are there signs of fluid or oil leakage? No
Are the drive shafts/cv joints worn out? No	Is the suspension system okay? No	Are engine mountings worn out? N/A

Electrical Condition

Do the indicator lights operate well? Yes	Do the brake lights operate well? Yes
Are the wipers operating well? Yes	Are the headlights operating well? Yes
Do the instrument panel lights work well? No	

COACHWORK NOTES: Minor scratches on the right side, cracked rear bumper, scratches noted on doors, wings and bumpers.

ELECTRICAL NOTES: Instrument panel lights flicker occasionally

MECHANICAL NOTES: Suspension system needs attention, worn out arm bushes, engine and gearbox mountings

EXTRAS: AC, ABS, Alloy rims, Fog Lamps, Xenon Lights, Side Mirror Indicator, Wing Indicator, Wind Breakers, Tint Windows, Car Identity, CDL, Cup Holder, 2 Cut Off, Rear Disk brakes, Rear Spoiler with high mounted brake lights, Rear Wiper, Roof aerial, Head rest, Foot Rest, Arm Rest, Digital Odometer, Dual SRS Airbags, Inbuilt R/CD/TV Player, Paddle shifters, Power mirror, Power Steering, Power Window, Sun Visors, Tiptronic Gearbox, Telescopic Bonnet Damper, Wood Print Finish,

ANTI THEFT: CAR ALARM

TYRES: 4 GOODYEAR TYRES 225/65R17 AND BRIDGESTONE T165/80R17 DONUT SPAREWHEEL ALL OF GOOD THREAD DEPTH

GENERAL CONDITION: Fair

ASSESSED VALUE: 850,000 /= (Eight Hundred And Fifty Thousand, Shillings Only)

Radio Estimate: 20000

Windscreen Estimate: 60000

REMARKS: Assessed value consistent with low usage.

N.B: N/A

REMEDIY: Recommended suspension system repair and respray the affected panels, replace worn out arm bushes, engine and gearbox mountings.

COUNTRY OF ORIGIN: Japan

DATE OF INSPECTION: 2023-05-15

EXAMINER: John Valuer

DESTINATION: MUA Insurance

LOCATION OF INSPECTION: Nairobi, Kenya

Amendment: None

Signed John Doe **Date** 2023-05-16

Receipt No: REC12345

NB: This Report reflects the estimated Market Value of the subject vehicle in its present condition, at the time of valuation. Any future assessment will take into account any changes in the meantime, due to usage e.t.c. This report is based on information on the logbook/importation documents.



© flip. All rights reserved.