REPORT

COMPONENTS REQUIRED

- 1. BREADBOARD
- 2. ARDUINO Uno
- 3. CONNECTING WIRES
- 4. IDR
- 5. RESISTOR
- 6. SWITCH

Precaution

>Connected the wires carefully from arduino to bread board its connected properly

>major components like resistor and LDR were connected correctly so that make the job half done

>LED was connected with wire by considering anode and cathode
>In the arduino the wire are connected to suitable pin like analog and digital

>switch was connected to bread board and to the arduino these connections

CODE

```
int led=12;
switch var()
void setup()
{
   pinMode(led, OUTPUT);
}

void loop()
{
   if(analogRead(A0)<200)
      digitalWrite(led,1);
   if(analogRead(A0)>=350)
      digitalWrite(led,0);
}
```

Screenshot:

