

Mabhas compliance report

non-compliant

Plan_04 · M-4 residential · generated 2026-05-29 18:06

checked	pass	fail	review
348	13	13	322

COMPLIANCE OVERVIEW



FINDINGS — FAILURES FIRST, THEN REVIEW, THEN PASS

The main "door" must be of hinged type with a minimum clear width of 0... D-07: clear width = 0.8 m (required $\geq$ 0.9 m) → FAIL	1-5-1-5-4a
The main "door" must be of hinged type with a minimum clear width of 0... D-01: clear height = 0.9 m (required $\geq$ 2.05 m) → FAIL	1-5-1-5-4b
The main "door" must be of hinged type with a minimum clear width of 0... D-07: clear height = 0.8 m (required $\geq$ 2.05 m) → FAIL	1-5-1-5-4b
The main "door" must be of hinged type with a minimum clear width of 0... D-front: clear height = 1.0 m (required $\geq$ 2.05 m) → FAIL	1-5-1-5-4b
1-10-1-5-4 In straight corridors and public spaces or those with wind... Room_kit: glazing ratio 0.0 fails requirement $\geq$ 0.025	10-1-5-4
1-10-1-5-4 In straight corridors and public spaces or those with wind... Room_kit: glazing ratio 0.0 fails requirement $\geq$ 0.05	10-1-5-4
In dwelling spaces, in accordance with the requirements of Chapter 4-6... Room_kit: glazing ratio 0.0 fails requirement $\geq$ 0.125	2-3-2-5-4
The minimum height of a dwelling space must be 40/2 meters. This minim... Room_01: height = 9.0 m (required $\geq$ 20.0 m) → FAIL	3-2-2-5-4

The height of sanitary spaces in any area where a person normally stan...

3-2-6-5-4

Room_bath: minimum height = 4.0 m (required ≥ 5.0 m) → FAIL

In dwelling spaces, if the upper lintel of windows (excluding skylight...

3-3-2-5-4

Room_kit: glazing ratio 0.0 fails requirement ≥ 0.1667

The minimum glazing area in occupied spaces, in accordance with the re...

3-3-4-5-4

Room_kit: glazing ratio 0.0 fails requirement ≥ 0.125

If it is meters, then the required glazing area shall be one fifth of ...

4-3-2-5-4

Room_kit: glazing ratio 0.0 fails requirement ≥ 0.2

Room_kit (room_kitchen) has no exterior window — lacks natural light

natural_light_presence

Room_kit (room_kitchen) has no exterior window — lacks natural light

The free, unobstructed depth of the entrance space must be at least 1....

1-1-1-7-4a

Object 'entrance space' not mapped to a measurable value — needs review

The free, unobstructed depth of the entrance space must be at least 40...

1-1-1-7-4b

Object 'entrance space' not mapped to a measurable value — needs review

Semi-open spaces installed in all occupancies must comply with the req...

1-1-7-5-4

Relation 'must_be_compliant_with' not handled by topology agent — needs review

Open spaces in all occupancies must comply with the requirements of th...

1-1-8-5-4

Relation 'must_comply_with' not handled by topology agent — needs review

In locations where level differences exceed 0.70 m, a handrail or guar...

1-11-1-5-4

Object 'level difference' not mapped to a measurable value — needs review

After the entry door of hotel rooms, suites, or apartments, a suitable...

1-2-1-7-4a

Object 'entrance space' not mapped to a measurable value — needs review

A- The free, unobstructed depth of the entrance space must be at least...

1-2-1-7-4b

Object 'entrance space' not mapped to a measurable value — needs review

The permissible height of small vehicle parking areas, to reduce fire ... 1-2-10-5-4a
Object 'parking_area_small' not mapped to a measurable value — needs review

The permissible height of medium and large vehicle parking areas shall... 1-2-10-5-4b
Object 'parking_area_medium_large' not mapped to a measurable value — needs review

Occupancy spaces must have a minimum clear height of 4.2 metres from f... 1-2-4-5-4a
Object 'occupancy space' not mapped to a measurable value — needs review

In sloped ceilings, where the span is 30.0 metres or more, the lowest ... 1-2-4-5-4b
Conditional rule (condition: when ceiling span is ≥ 30.0 m) — needs human review

If a pre-entry area is provided inside an independent shower space, at... 1-2-6-5-4b
Conditional rule (condition: when a pre-entry area is provided) — needs human review

In all buildings with more than one occupied unit, access to the exter... 1-2-8-5-4
Relation 'must_be_provided_as' not handled by topology agent — needs review

External light and air ducts that are created to provide mandatory lig... 1-2-9-5-4
Relation 'must_not_be_used_for_other_purposes' not handled by topology agent — needs review

If there is a step, any level difference, or a wall opposite the main ... 1-3-1-5-4
Object 'step_or_level_difference_or_wall' not mapped to a measurable value — needs review

The width of the entry passage and ramp in all large parking areas and... 1-3-10-5-4
Conditional rule (condition: large_or_medium_public_parking) — needs human review

Children's play areas in buildings or their surroundings must be locat... 1-3-13-5-4
Relation 'must_be_protected_from' not handled by topology agent — needs review

Each dwelling space must have at least one door and one glazed window ... 1-3-2-5-4
Window faces external open space / light well — site condition cannot be verified from a 2D plan; confirm on site

Every occupied space that, according to labor regulations, necessarily... 1-3-4-5-4
Object 'doors and glazed windows' not mapped to a measurable value — needs review

Every occupied space that, according to labor regulations, necessarily...	1-3-4-5-4
Glazing rule not in a directly checkable ratio form — needs review	
Spaces that are used both for residence and for dining must have a min...	1-3-5-4
Object 'multi-purpose residential space' not mapped to a measurable value — needs review	
Independent kitchens must have natural light. In open and wall kitchen...	1-3-5-5-4
Relation 'must_have_natural_light' not handled by topology agent — needs review	
A mandatory opening area of at least 18.0 square meters is required fo...	1-3-6-5-4
Object 'opening' not mapped to a measurable value — needs review	
In group 4 and 6 buildings, if a private courtyard does not have a dir...	1-3-8-5-4
Relation 'must_be_provided_by' not handled by topology agent — needs review	
At least 60 percent of the internal wall surface of a sunroom enclosur...	1-3-9-5-4
Object 'internal_wall_surface_of_sunroom' not mapped to a measurable value — needs review	
At least 60 percent of the internal wall surface of a sunroom enclosur...	1-3-9-5-4
Glazing rule not in a directly checkable ratio form — needs review	
The usable free unobstructed width of internal circulation corridors t...	1-4-1-5-4
Object 'circulation corridor usable width' not mapped to a measurable value — needs review	
The floor of an independent or open kitchen and the work area opposite...	1-4-5-5-4
Relation 'must_be_covered_with' not handled by topology agent — needs review	
1-4-8-5-4 Internal courtyards enclosed as light wells, when used to pr...	1-4-8-5-4a
Object 'light well' not mapped to a measurable value — needs review	
1-4-8-5-4 Internal courtyards enclosed as light wells, when used to pr...	1-4-8-5-4a
Window faces external open space / light well — site condition cannot be verified from a 2D plan; confirm on site	
1-4-8-5-4 Internal courtyards enclosed as light wells, when used to pr...	1-4-8-5-4b
Object 'light well' not mapped to a measurable value — needs review	

1-4-8-5-4 Internal courtyards enclosed as light wells, when used to pr... 1-4-8-5-4b

Window faces external open space / light well — site condition cannot be verified from a 2D plan; confirm on site

Double-leaf doors without a central mullion used as main doors must ha... 1-5-1-5-4c

Conditional rule (condition: when the active leaf is opened) — needs human review

The width of each leaf of a door must not exceed 0.201 meters. 1-5-1-5-4d

Object 'door leaf' not mapped to a measurable value — needs review

Door stopping or movement-regulating devices must not locally reduce t... 1-5-1-5-4e

Conditional rule (condition: locally) — needs human review

Attached rooms to dwelling spaces, if at least 80% of the shared wall ... 1-5-2-5-4

Relation 'must_not_require_independent_light_and_ventilation_when_shared_wall_open_ge_80_percent' not handled by topology agent — needs review

External eaves and balconies that are situated at the beginning or end... 1-6-1-5-4

Object 'external_eave_or_balcony_surface' not mapped to a measurable value — needs review

Any space that necessarily requires natural light must have at least o... 1-6-4

Relation 'must_face' not handled by topology agent — needs review

Any space that necessarily requires natural light must have at least o... 1-6-4

Window faces external open space / light well — site condition cannot be verified from a 2D plan; confirm on site

In a building stairway, the minimum tread depth is 28.0 cm. The riser ... 1-7-1-5-4

Object 'stair_tread' not mapped to a measurable value — needs review

In a building stairway, the minimum tread depth is 28.0 cm. The riser ... 1-7-1-5-4

Conditional rule (condition: such that tread_depth + 2 * riser_height is between 0.63 and 0.64 m) — needs human review

In a building stairway, the minimum tread depth is 28.0 cm. The riser ... 1-7-1-5-4

Stair-related rule but no stair element detected — confirm whether a stair is required for this plan

In a building stairway, the minimum tread depth is 28.0 cm. The riser ... 1-7-1-5-4

Stair-related rule but no stair element detected — confirm whether a stair is required for this plan

In residential occupancies where the independent or open kitchen is us... 10-1-1-7-4a

Conditional rule (condition: when the kitchen is independent or open and used only for cooking) — needs human review

1-10-1-5-4 In straight corridors and public spaces or those with wind... 10-1-5-4

Conditional rule (condition: natural lighting provided and windows at both ends) — needs human review

1-10-1-5-4 In straight corridors and public spaces or those with wind... 10-1-5-4

Conditional rule (condition: natural lighting provided and windows at both ends) — needs human review

1-10-1-5-4 In straight corridors and public spaces or those with wind... 10-1-5-4

Conditional rule (condition: otherwise) — needs human review

1-10-1-5-4 In straight corridors and public spaces or those with wind... 10-1-5-4

Glazing rule not in a directly checkable ratio form — needs review

2-10-1-5-4 On stairways, where natural lighting is provided, the glaz... 10-1-5-4b

Conditional rule (condition: natural lighting provided) — needs human review

2-10-1-5-4 On stairways, where natural lighting is provided, the glaz... 10-1-5-4b

Glazing rule not in a directly checkable ratio form — needs review

2-10-1-5-4 On stairways, where natural lighting is provided, the glaz... 10-1-5-4b

Stair-related rule but no stair element detected — confirm whether a stair is required for this plan

In double-leaf entrance doors, the fixed latch must be secured with a ... 10-10-12-9-4

Relation 'must_be_secured_and_not_easily_opened_from_outside' not handled by topology agent — needs review

When spaces of two independent uses receive light and air from the sam... 10-3-8-5-4

Object 'distance_between_opposite_window_walls' not mapped to a measurable value — needs review

When spaces of two independent uses receive light and air from the sam... 10-3-8-5-4

Window faces external open space / light well — site condition cannot be verified from a 2D plan; confirm on site

In residential occupancies where the independent or open kitchen is us... 11-1-1-7-4

Conditional rule (condition: when the kitchen is independent or open and used for cooking and dining) — needs human review

If a building can be accessed by two or more primary or secondary traf... 11-1-10-5-4

Relation 'must_be_from_lower_performance_route' not handled by topology agent — needs review

In residential occupancies, an independent or open kitchen must have a... 12-1-1-7-4a

Conditional rule (condition: when the kitchen is independent or open) — needs human review

For kitchens used for both cooking and dining, the minimum width must ... 12-1-1-7-4b

Conditional rule (condition: when the kitchen is used for cooking and dining) — needs human review

Throughout the full length of wall kitchens in residential occupancies... 13-1-1-7-4a

Conditional rule (condition: measured from cabinet edge, free of fixed obstacles) — needs human review

The minimum length of a wall kitchen in residential occupancies is 3.0... 13-1-1-7-4b

Object 'wall kitchen' not mapped to a measurable value — needs review

All independent kitchens in residential units must have independent na... 14-1-1-7-4

Relation 'must_have_independent_natural_light_and_ventilation' not handled by topology agent — needs review

In kitchens that serve living spaces, the minimum ventilation opening ... 15-1-1-7-4

Conditional rule (condition: applies to kitchens serving living spaces) — needs human review

The kitchen exhaust system in residential units of building groups 6, ... 16-1-1-7-4

Relation

'must_start_with_central_control_or_switch_and_connect_to_emergency_power_if_no_natural_ventilation' not handled by topology agent — needs review

For the purpose of providing low-bodily-effort and movement use in any... 17-1-1-7-4

Conditional rule (condition: residential units with floor area $\geq 75 \text{ m}^2$) — needs human review

Each independent sanitary space in residential occupancies (where disa... 18-1-1-7-4a

Conditional rule (condition: accessibility for disabled persons not mandatory) — needs human review

If a vestibule is provided within an independent shower space, one dim... 18-1-1-7-4b

Conditional rule (condition: accessibility for disabled persons not mandatory) — needs human review

The minimum clear height of sanitary spaces in residential occupancies... 19-1-1-7-4

Conditional rule (condition: applies to 80% of required floor area) — needs human review

The main circulation and access routes of the building must not pass t... 2-1-1-5-4

Relation 'must_not_pass_through' not handled by topology agent — needs review

The use of wall-mounted kitchens in residential occupancies with an ar... 2-1-1-7-4d

Relation 'must_not_face' not handled by topology agent — needs review

The design and placement of open or wall kitchens in residential occup... 2-1-1-7-4e

Relation 'must_not_be_visible_from' not handled by topology agent — needs review

The only access to a dwelling room must not be from another dwelling r... 2-1-2-5-4

Could not map subject/object to room categories (subject='room', object='another_dormitory_room')

Access to an occupancy space must not be through another occupancy or ... 2-1-4-5-4

Could not map subject/object to room categories (subject='access path to an occupancy space', object='another occupancy or residential space unless hierarchy requires it or it is an attached space per 4-5-4-5')

The collection and drainage of rain and snow water in all semi-open sp... 2-1-7-5-4

Relation 'must_have' not handled by topology agent — needs review

The floor of all open spaces must have appropriate slope and a surface... 2-1-8-5-4

Unsupported comparator '>=' — needs review

2-1-9-5-4 Suitable access for reaching and cleaning these spaces and e... 2-1-9-5-4

Relation 'must_have_access_for_cleaning' not handled by topology agent — needs review

The height of handrails on sloping stairs or ramps must be at least 0.... 2-11-1-5-4

Object 'handrail height' not mapped to a measurable value — needs review

Access to independent residential rooms must not be directly from anot... 2-2-1-7-4

Could not map subject/object to room categories (subject='independent residential room', object='another independent residential room')

The internal radius of the vehicle turning path in parking areas must ... 2-2-10-5-4

Object 'turning_path' not mapped to a measurable value — needs review

Pools located on the lower floors of the building must not be built ag... 2-2-13-5-4

Conditional rule (condition: on all sides) — needs human review

Pools located on the lower floors of the building must not be built ag...

2-2-13-5-4b

Object 'pool wall' not mapped to a measurable value — needs review

The minimum free height beneath door frames, shutters, pipes, channels...

2-2-4-5-4

Object 'free height under door frames and similar elements' not mapped to a measurable value — needs review

The minimum size of a sanitary space for use by disabled persons is 70...

2-2-6-5-4

Object 'sanitary space for disabled persons' not mapped to a measurable value — needs review

These ducts must have a minimum width of 0.5 meters and be provided at...

2-2-9-5-4

Object 'external_light_and_air_duct' not mapped to a measurable value — needs review

In the building entrance area there must be space for several people t...

2-3-1-5-4

Object 'entrance space' not mapped to a measurable value — needs review

Large and medium parking areas must have at least two pedestrian exit ...

2-3-10-5-4

Conditional rule (condition: large_or_medium_parking) — needs human review

Large and medium parking areas must have at least two pedestrian exit ...

2-3-10-5-4

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

Access to the play area must be through the building's courtyard or pu...

2-3-13-5-4

Relation 'must_be_via' not handled by topology agent — needs review

In dwelling spaces, in accordance with the requirements of Chapter 4-6...

2-3-2-5-4

Conditional rule (condition: if windows on single wall and opposite wall distance $\leq$ 12.5 m) — needs human review

If a window opens toward a balcony, compliance with the regulations es...

2-3-4-5-4

Relation 'must_face' not handled by topology agent — needs review

Spaces used for residence, dining and cooking must have a minimum floo...

2-3-5-4

Object 'residential kitchen/dining space' not mapped to a measurable value — needs review

In open and wall kitchens, mechanical ventilation is mandatory.

2-3-5-5-4

Relation 'must_have_mechanical_ventilation' not handled by topology agent — needs review

Exhaust air systems for sanitary spaces in buildings of groups 7, 6, a...	2-3-6-5-4
Relation 'must_be_configured_as' not handled by topology agent — needs review	
If a passage is roofed with transparent materials, providing adequate ...	2-3-8-5-4
Relation 'must_have' not handled by topology agent — needs review	
At least 50 percent of the required glass surface of a sunroom enclosu...	2-3-9-5-4
Object 'required_glass_surface_of_sunroom' not mapped to a measurable value — needs review	
At least 50 percent of the required glass surface of a sunroom enclosu...	2-3-9-5-4
Glazing rule not in a directly checkable ratio form — needs review	
In buildings or occupied units where accessibility for persons with di...	2-4-1-5-4
Object 'circulation corridor usable width' not mapped to a measurable value — needs review	
A protrusion in passages with a width less than 12 meters and in passa...	2-4-5-4-4
Object 'protrusion' not mapped to a measurable value — needs review	
Walls surrounding the sink and stove in independent, open, and wall ki...	2-4-5-5-4
Object 'wall_surrounding_sink_and_stove' not mapped to a measurable value — needs review	
2-4-8-5-4 To provide light and air to residential and occupied spaces ...	2-4-8-5-4
Relation 'must_have_sky_view_cone_45deg' not handled by topology agent — needs review	
All doors located in access and egress routes must swing in the direct...	2-5-1-5-4
Relation 'must_swing_in_direction_of_egress' not handled by topology agent — needs review	
All doors located in access and egress routes must swing in the direct...	2-5-1-5-4
Stair-related rule but no stair element detected — confirm whether a stair is required for this plan	
In this case, when the doors are fully open, none of the required clea...	2-5-1-5-4b
Conditional rule (condition: when doors are fully open) — needs human review	
When less than 80% of the shared wall of the annexed space with the ma...	2-5-2-5-4
Relation 'must_have_independent_entrances_when_shared_wall_open_lt_80_percent' not handled by topology agent — needs review	

When less than 80% of the wall shared between the attached space and ...

2-5-4-5-4

Could not map subject 'attached space and main space' to a room category

Eaves and balconies must not have a slope greater than 2 percent in an...

2-6-1-5-4

Object 'eave_or_balcony' not mapped to a measurable value — needs review

All spaces used by people must have natural or mechanical air exchange...

2-6-4

Could not map subject 'space used by people' to a room category

The total area of roof skylights and wall windows in the desired space...

2-7-9-4

Conditional rule (condition: must be equivalent to the areas specified in Table 4-6) — needs human review

The total area of roof skylights and wall windows in the desired space...

2-7-9-4

Glazing rule not in a directly checkable ratio form — needs review

Each occupied unit in building groups 1 to 7 must have at least one se...

2-8-12-9-4a

Object 'emergency opening' not mapped to a measurable value — needs review

The minimum height is 1.30 meters.

2-8-12-9-4b

Object 'emergency opening' not mapped to a measurable value — needs review

It is implicit that beneath each emergency opening, an emergency acces...

2-8-12-9-4c

Could not map subject 'emergency opening' to a room category

The main entrance of dwelling rooms must have a minimum useful width o...

2-8-2-5-4

Conditional rule (condition: main entrance) — needs human review

In tall buildings, interior light wells (patios) may be used for light...

2-8-4a

Conditional rule (condition: for lighting/ventilation of accommodation, workspace, and kitchen spaces) — needs human review

In tall buildings, interior light wells (patios) may be used for light...

2-8-4a

Window faces external open space / light well — site condition cannot be verified from a 2D plan; confirm on site

In residential buildings of groups 6, 7, and 8 or their courtyards, at...

21-1-1-7-4

Object 'play_area' not mapped to a measurable value — needs review

On plots larger than 200 square meters, if the main living spaces of t...

24-1-1-7-4

Object 'opposite window walls' not mapped to a measurable value — needs review

On plots larger than 200 square meters, if the main living spaces of t...

24-1-1-7-4

Window faces external open space / light well — site condition cannot be verified from a 2D plan; confirm on site

In cases where kitchen and living spaces of two independent residentia...

25-1-1-7-4

Object 'opposite window walls' not mapped to a measurable value — needs review

In cases where kitchen and living spaces of two independent residentia...

25-1-1-7-4

Window faces external open space / light well — site condition cannot be verified from a 2D plan; confirm on site

In residential buildings of groups 1 to 3, the minimum clear width of ...

3-1-1-7-4

Conditional rule (condition: stair_type = straight) — needs human review

In residential buildings of groups 1 to 3, the minimum clear width of ...

3-1-1-7-4

Stair-related rule but no stair element detected — confirm whether a stair is required for this plan

In residential buildings of groups 1 to 3, the minimum clear width of ...

3-1-1-7-4b

Conditional rule (condition: stair_has_landing_or_turn) — needs human review

In residential buildings of groups 1 to 3, the minimum clear width of ...

3-1-1-7-4b

Stair-related rule but no stair element detected — confirm whether a stair is required for this plan

Access to a sanitary space in occupancy units that have at most two in...

3-1-6-5-4

Could not map subject 'occupant' to a room category

Discharging surface water from semi-open spaces onto public road surfa...

3-1-7-5-4

Could not map subject/object to room categories (subject='surface water drainage from semi-open spaces', object='public road surface')

Open spaces adjacent to a public passage must be separated from the pu...

3-1-8-5-4

Relation 'must_be_separated_by' not handled by topology agent — needs review

Open spaces adjacent to a public passage must be separated from the pu...

3-1-8-5-4

Guard/railing rule but no balcony/terrace in plan — not applicable or needs review

The horizontal distance between the nearest points of openings of two ... 3-10-12-9-4
Relation 'must_be_protected_by' not handled by topology agent — needs review

The horizontal distance between the nearest points of openings of two ... 3-10-12-9-4
Guard/railing rule but no balcony/terrace in plan — not applicable or needs review

Openings, doors, windows and underground entrances of all buildings mu... 3-12-9-4
Relation 'must_be_designed_to_provide_safety' not handled by topology agent — needs review

If there are two or more independent rooms in a suite or apartment wit... 3-2-1-7-4
Relation 'must_have_access_to_multiple_rooms' not handled by topology agent — needs review

Observance of a minimum area of 00/5 × 00/5 m² for a 90-degree vehicle... 3-2-10-5-4
Object 'turning_space_90deg' not mapped to a measurable value — needs review

Around all pools, an unobstructed and non-slippery circulation path wi... 3-2-13-5-4
Object 'circulation path around pool' not mapped to a measurable value — needs review

In heating or cooling systems, the return air of one occupancy unit mu... 3-2-6-4
Could not map subject/object to room categories (subject='return air of an occupancy unit', object='the return-air cycle of another occupancy unit')

In the entrance area, the clear height from the finished floor must no... 3-3-1-5-4a
Conditional rule (condition: over more than 50% of the entrance floor area) — needs human review

In the entrance area, the clear height from the finished floor must no... 3-3-1-5-4b
Conditional rule (condition: on the remaining 50% of the entrance floor area) — needs human review

Providing two vehicle entry points from the public right-of-way, each ... 3-3-10-5-4
Conditional rule (condition: plot_area >= 20 m) — needs human review

In dwelling spaces, if the upper lintel of windows (excluding skylight... 3-3-2-5-4
Conditional rule (condition: if window lintel height < 5 m and windows not on single wall or distance <= 12.5 m) — needs human review

The minimum glazing area in occupied spaces, in accordance with the re... 3-3-4-5-4
Object 'glazing' not mapped to a measurable value — needs review

All multi-purpose residential spaces must be ventilated naturally or m...

3-3-5-4

Could not map subject 'multi-purpose residential space' to a room category

Exhaust systems of all kitchens that are required to have a hood over ...

3-3-5-5-4

Could not map subject/object to room categories (subject='exhaust_system', object='outside_of_building')

All private courtyards and passages must have suitable access for clea...

3-3-8-5-4

Relation 'must_have' not handled by topology agent — needs review

To provide mandatory lighting and ventilation for a residential space ...

3-3-9-5-4

Relation 'must_be_at_least' not handled by topology agent — needs review

Corridors that are used solely for access to electrical, mechanical, o...

3-4-1-5-4

Object 'equipment access corridor' not mapped to a measurable value — needs review

3-4-8-5-4 Covering a light well is not permitted.

3-4-8-5-4

Relation 'must_not_be_covered' not handled by topology agent — needs review

When the occupancy load or the number of users of a stair landing is 5...

3-5-1-5-4a

Conditional rule (condition: when occupancy load $\geq$ 50 persons) — needs human review

On each side of the main building door, the occupied unit and space mu...

3-5-1-5-4b

Relation 'must_be_at_same_level_as' not handled by topology agent — needs review

The height of a landing or floor located in an accessible route for pe...

3-5-1-5-4c

Conditional rule (condition: when landing is in accessible route for persons with disabilities or mandatory egress)
— needs human review

If the floor of a balcony or terrace that serves as the main access an...

3-6-1-5-4

Relation 'must_have_refuge_or_guard' not handled by topology agent — needs review

If the floor of a balcony or terrace that serves as the main access an...

3-6-1-5-4

Guard/railing rule but no balcony/terrace in plan — not applicable or needs review

In all buildings, the minimum stair width is mandatory and is determin...

3-7-1-5-4

Object 'stair' not mapped to a measurable value — needs review

In all buildings, the minimum stair width is mandatory and is determin...

3-7-1-5-4

Object 'ramp' not mapped to a measurable value — needs review

In all buildings, the minimum stair width is mandatory and is determin...

3-7-1-5-4

Stair-related rule but no stair element detected — confirm whether a stair is required for this plan

To reduce risk in accidents, a balcony may be used as a rescue opening...

3-7-5-4

Relation 'may_be_used_as' not handled by topology agent — needs review

To reduce risk in accidents, a balcony may be used as a rescue opening...

3-7-5-4

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

In building groups 4 to 7, if the top floor has a sloped roof, the con...

3-8-12-9-4a

Object 'emergency opening in skylight/balcony' not mapped to a measurable value — needs review

In building groups 4 to 7, if the top floor has a sloped roof, the con...

3-8-12-9-4a

Glazing rule not in a directly checkable ratio form — needs review

It must also have a minimum height of 1.30 meters.

3-8-12-9-4b

Object 'emergency opening in skylight/balcony' not mapped to a measurable value — needs review

It must also have a minimum height of 1.30 meters.

3-8-12-9-4b

Glazing rule not in a directly checkable ratio form — needs review

The acceptable depth of daylighting in any room, space, or zone for li...

3-8-2-5-4

Conditional rule (condition: per window) — needs human review

The acceptable depth of daylighting in any room, space, or zone for li...

3-8-2-5-4

Glazing rule not in a directly checkable ratio form — needs review

In residential buildings of groups 4 to 7, the minimum clear width of ...

4-1-1-7-4

Conditional rule (condition: stair_type = straight) — needs human review

In residential buildings of groups 4 to 7, the minimum clear width of ...

4-1-1-7-4

Stair-related rule but no stair element detected — confirm whether a stair is required for this plan

In residential buildings of groups 4 to 7, the minimum clear width of ...

4-1-1-7-4b

Conditional rule (condition: stair_has_landing) — needs human review

In residential buildings of groups 4 to 7, the minimum clear width of ...

4-1-1-7-4b

Stair-related rule but no stair element detected — confirm whether a stair is required for this plan

Intermediate floors, if they meet all the conditions below, are consid...

4-1-4-4

Object 'intermediate floor' not mapped to a measurable value — needs review

The allocation of sanitary spaces (toilets) must not be oriented towar...

4-1-6-5-4

Relation 'must_not_face' not handled by topology agent — needs review

If the floor of a building's semi-open space is situated at a height g...

4-1-7-5-4

Conditional rule (condition: when semi-open space floor is above 70.0 m) — needs human review

If the floor of a building's semi-open space is situated at a height g...

4-1-7-5-4

Guard/railing rule but no balcony/terrace in plan — not applicable or needs review

Window openings that are accessible from public thoroughfares must be ...

4-10-12-9-4

Relation 'must_be_protected_by' not handled by topology agent — needs review

Window openings that are accessible from public thoroughfares must be ...

4-10-12-9-4

Guard/railing rule but no balcony/terrace in plan — not applicable or needs review

Underground entrances and opening windows must be designed and constru...

4-12-9-4

Relation 'must_prevent_entry_of' not handled by topology agent — needs review

The minimum length of a wall wet bar (pantry) in hotel suites and apar...

4-2-1-7-4a

Conditional rule (condition: without cooking equipment) — needs human review

The minimum length of a wall kitchenette with cooking equipment in hot...

4-2-1-7-4b

Conditional rule (condition: with cooking equipment) — needs human review

The required dimensions for two vehicles parked side-by-side are each ...

4-2-10-5-4a

Object 'parking_space_side_by_side' not mapped to a measurable value — needs review

When vehicles are parked longitudinally (one behind the other), the re...

4-2-10-5-4b

Object 'parking_space_longitudinal' not mapped to a measurable value — needs review

In all pools, at least one means of egress from the pool, such as a st...

4-2-13-5-4

Object 'means of egress from pool' not mapped to a measurable value — needs review

In all pools, at least one means of egress from the pool, such as a st...

4-2-13-5-4

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

The minimum free clearance under door frames, shutters, pipes, ducts a...

4-2-2-5-4

Object 'clearance' not mapped to a measurable value — needs review

Basement rooms, complying with the following conditions, may be used a...

4-2-5-4

Could not map subject/object to room categories (subject='basement_room', object='open_space_for_natural_light_and_ventilation')

If passage of people or wheeled equipment is possible, the upper surfa...

4-2-9-5-4

Relation 'must_be_level_with_ground_and_protected_by_metal_mesh' not handled by topology agent — needs review

If passage of people or wheeled equipment is possible, the upper surfa...

4-2-9-5-4

Guard/railing rule but no balcony/terrace in plan — not applicable or needs review

The maximum permissible height of the main entrance floor level relati...

4-3-1-5-4

Object 'entrance floor level height difference' not mapped to a measurable value — needs review

Children's play spaces must have access to at least one washbasin and ...

4-3-13-5-4a

Object 'play_space' not mapped to a measurable value — needs review

Play spaces intended for 20 persons or more must have access to at lea...

4-3-13-5-4b

Conditional rule (condition: when intended_occupancy >= 20) — needs human review

Any building or part of a building in which more than five persons of ...

4-3-2-3-4

Could not map subject 'childcare room (children under 3)' to a room category

Any building or part of a building in which more than five persons of ...

4-3-2-3-4

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

If it is meters, then the required glazing area shall be one fifth of ...

4-3-2-5-4

Object 'window' not mapped to a measurable value — needs review

If a window opens onto an iwan, the iwan must meet the following condi...

4-3-2-5-4a

Could not map subject/object to room categories (subject='iwan',
object='open_space_or_public_passage_without_obstruction')

All occupied spaces used by people must be ventilated naturally or mec...

4-3-4-5-4

Could not map subject 'occupied space' to a room category

If the lower floors of a building (basement or ground floor) are desig...

4-3-8-5-4

Relation 'must_not_extend_into' not handled by topology agent — needs review

Lighting and ventilation of a sunroom enclosure must not be provided f...

4-3-9-5-4

Relation 'must_not_be_provided_from' not handled by topology agent — needs review

The minimum required width of straight corridors not located on the bu...

4-4-1-5-4

Object 'straight non-egress corridor' not mapped to a measurable value — needs review

The minimum required width of straight corridors not located on the bu...

4-4-1-5-4

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

No part of the building shall have a protrusion into small enclosed co...

4-4-5-4-4

Relation 'must_not_have_protrusion_into' not handled by topology agent — needs review

4-4-8-5-4 The floor of light wells must be provided with adequate prov...

4-4-8-5-4

Relation 'must_have_drainage_and_access_for_cleaning' not handled by topology agent — needs review

In the main access and egress routes, doors must be designed, construc...

4-5-1-5-4

Relation 'must_be_easily_openable_from_inside' not handled by topology agent — needs review

Requirements for sanitary spaces with skylight lighting: For providing...

4-6-5-4

Glazing rule not in a directly checkable ratio form — needs review

Main living space of a residential unit — minimum required values per ...

4-6-1-جدول

Object 'Main living space of a residential unit' not mapped to a measurable value — needs review

Living, cooking and dining room — minimum required values per Table 4-6-10 جدول 4-6-10

Object 'Living, cooking and dining room' not mapped to a measurable value — needs review

Sanitary spaces — minimum required values per Table 4-6-11 جدول 4-6-11

Object 'Sanitary spaces' not mapped to a measurable value — needs review

Small vehicle parking — minimum required values per Table 4-6-12 جدول 4-6-12

Object 'Small vehicle parking' not mapped to a measurable value — needs review

Medium and large vehicle parking — minimum required values per Table 4-6-13 جدول 4-6-13

Object 'Medium and large vehicle parking' not mapped to a measurable value — needs review

Public corridors and egress access ways — minimum required values per Table 4-6-15 جدول 4-6-15

Object 'Public corridors and egress access ways' not mapped to a measurable value — needs review

Public corridors and egress access ways — minimum required values per Table 4-6-15 جدول 4-6-15

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

Stairwells (per floor) — minimum required values per Table 4-6-16 جدول 4-6-16

Object 'Stairwells (per floor)' not mapped to a measurable value — needs review

Stairwells (per floor) — minimum required values per Table 4-6-16 جدول 4-6-16

Stair-related rule but no stair element detected — confirm whether a stair is required for this plan

Basements — minimum required values per Table 4-6-17 جدول 4-6-17

Object 'Basements' not mapped to a measurable value — needs review

Other habitable spaces — minimum required values per Table 4-6-2 جدول 4-6-2

Object 'Other habitable spaces' not mapped to a measurable value — needs review

Sunshade enclosure — minimum required values per Table 4-6-21 جدول 4-6-21

Object 'Sunshade enclosure' not mapped to a measurable value — needs review

Spaces attached to the main space — minimum required values per Table 4-6-3 جدول 4-6-3

Object 'Spaces attached to the main space' not mapped to a measurable value — needs review

Spaces lit from a sunshade enclosure — minimum required values per Tab... 4-6-4-جدول

Object 'Spaces lit from a sunshade enclosure' not mapped to a measurable value — needs review

Storage spaces — minimum required values per Table 4-6.; minimum heigh... 4-6-5-جدول

Object 'Storage spaces' not mapped to a measurable value — needs review

Residential kitchen — minimum required values per Table 4-6.; minimum ... 4-6-6-جدول

Object 'Residential kitchen' not mapped to a measurable value — needs review

Wall kitchen — minimum required values per Table 4-6.; minimum height ... 4-6-7-جدول

Object 'Wall kitchen' not mapped to a measurable value — needs review

Living and dining or multipurpose room — minimum required values per T... 4-6-8-جدول

Object 'Living and dining or multipurpose room' not mapped to a measurable value — needs review

Kitchen and dining room — minimum required values per Table 4-6.; mini... 4-6-9-جدول

Object 'Kitchen and dining room' not mapped to a measurable value — needs review

The minimum width or radius of a landing must be equal to the stair wi... 4-7-1-5-4

Relation 'must_be_equal_to' not handled by topology agent — needs review

The minimum width or radius of a landing must be equal to the stair wi... 4-7-1-5-4

Stair-related rule but no stair element detected — confirm whether a stair is required for this plan

For daylighting through a window located in an eave for a used space, ... 4-7-5-4a

Conditional rule (condition: must be at least $(1/4 * \text{covered floor area}) + (2 * \text{required light opening area})$) — needs human review

For daylighting through a window located in an eave for a used space, ... 4-7-5-4a

Window faces external open space / light well — site condition cannot be verified from a 2D plan; confirm on site

The width (depth) of an eave must not exceed twice its length (project... 4-7-5-4b

Object 'eave' not mapped to a measurable value — needs review

For every use in buildings of groups 4 to 7, a free area in the buildi... 4-8-12-9-4

Relation 'must_be_connected_to' not handled by topology agent — needs review

The installation of protective devices on the building façade must com...

5-10-12-9-4

Relation 'must_not_obstruct' not handled by topology agent — needs review

In all occupancies and spaces, providing safe egress routes and instal...

5-12-9-4

Relation 'must_have' not handled by topology agent — needs review

In all occupancies and spaces, providing safe egress routes and instal...

5-12-9-4

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

The minimum width of the circulation path in large and medium parking ...

5-2-10-5-4

Object 'circulation_path_large_medium' not mapped to a measurable value — needs review

The minimum width of the circulation path in large and medium parking ...

5-2-10-5-4

Object 'circulation_path_small' not mapped to a measurable value — needs review

When a floor is inserted between levels within a dwelling space as par...

5-2-2-5-4

Object 'upper_part' not mapped to a measurable value — needs review

When a floor is inserted between levels within a dwelling space as par...

5-2-2-5-4

Object 'lower_part' not mapped to a measurable value — needs review

In the design and construction of public buildings and residential com...

5-3-1-5-4

Could not map subject 'building entrance' to a room category

In all public parking areas and large and medium private parking areas...

5-3-10-5-4

Object 'vehicle_entry_exit_door' not mapped to a measurable value — needs review

In all public parking areas and large and medium private parking areas...

5-3-10-5-4

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

The entrance to an enclosed play area must be equipped with an appropri...

5-3-13-5-4

Relation 'must_have_lock_access_control' not handled by topology agent — needs review

All residential spaces must be ventilated naturally, or in combination...

5-3-2-5-4

Relation 'must_have_direct_connection_to' not handled by topology agent — needs review

In buildings of groups 1 to 5, courtyards or passages that provide lig...

5-3-8-5-4a

Object 'courtyard' not mapped to a measurable value — needs review

In buildings of groups 1 to 5, courtyards or passages that provide lig...

5-3-8-5-4b

Object 'courtyard' not mapped to a measurable value — needs review

The openings of sanitary and kitchen spaces must not open onto the sun...

5-3-9-5-4

Relation 'must_not_open_onto' not handled by topology agent — needs review

The height of corridors must correspond to the mandatory height of the...

5-4-1-5-4

Relation 'must_be_equal_to' not handled by topology agent — needs review

A protrusion in passages must not be located within the area of electr...

5-4-5-4-4

Relation 'must_not_be_in' not handled by topology agent — needs review

The installation and use of a chain or safety lock is permitted only f...

5-5-1-5-4

Conditional rule (condition: must_be_openable_from_inside_without_key) — needs human review

1-5-5-4 General requirements 1-1-5-5-4 The floor area, dimensions and ...

5-5-4

Object 'kitchen floor area' not mapped to a measurable value — needs review

1-5-5-4 General requirements 1-1-5-5-4 The floor area, dimensions and ...

5-5-4

Object 'kitchen width between main walls' not mapped to a measurable value — needs review

1-5-5-4 General requirements 1-1-5-5-4 The floor area, dimensions and ...

5-5-4

Object 'free work area in kitchen' not mapped to a measurable value — needs review

1-5-5-4 General requirements 1-1-5-5-4 The floor area, dimensions and ...

5-5-4

Object 'clearance from shelves' not mapped to a measurable value — needs review

Flooring and wall covering: In all buildings, the walls of washrooms a...

5-6-5-4

Conditional rule (condition: in washrooms_and_toilets) — needs human review

The maximum number of steps between two landings in buildings used by ...

5-7-1-5-4

Conditional rule (condition: for buildings used by persons with disabilities or limited mobility) — needs human review

Carrying out permanent activities in rescue stations and installing us...

5-8-12-9-4

Relation 'must_not_be_occupied_by' not handled by topology agent — needs review

The minimum required width of straight corridors and internal stairs o...

6-1-1-7-4

Object 'corridor_or_internal_stair' not mapped to a measurable value — needs review

The minimum required width of straight corridors and internal stairs o...

6-1-1-7-4

Stair-related rule but no stair element detected — confirm whether a stair is required for this plan

The entrances of buildings and occupied units must be arranged so that...

6-10-12-9-4

Relation 'must_be_arranged_to_ensure' not handled by topology agent — needs review

Safe egress routes in buildings must be arranged so that, in addition ...

6-12-9-4

Relation 'must_provide' not handled by topology agent — needs review

Safe egress routes in buildings must be arranged so that, in addition ...

6-12-9-4

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

In public parking areas, covered ramps longer than 20 meters are allow...

6-2-10-5-4a

Conditional rule (condition: length > 20 m) — needs human review

For lengths less than 20 meters the maximum allowed slope is 17%; howe...

6-2-10-5-4b

Conditional rule (condition: length <= 20 m) — needs human review

The maximum slope of the first and last meter must be equal to or less...

6-2-10-5-4c

Conditional rule (condition: first_and_last_meter) — needs human review

If natural lighting cannot be provided through a regular window in the...

6-2-5-4

Conditional rule (condition: if no regular window possible) — needs human review

In small private parking areas, if there is a separate pedestrian entr...

6-3-10-5-4

Conditional rule (condition: separate_pedestrian_entrance_present) — needs human review

In small private parking areas, if there is a separate pedestrian entr...

6-3-10-5-4

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

In buildings of groups 1 to 5, if courtyards or passages are used sole...

6-3-8-5-4a

Object 'courtyard' not mapped to a measurable value — needs review

In buildings of groups 1 to 5, if courtyards or passages are used sole...

6-3-8-5-4b

Object 'courtyard' not mapped to a measurable value — needs review

In this sunroom enclosure, heating or cooling installations that use s...

6-3-9-5-4

Relation 'must_not_be_installed_unless' not handled by topology agent — needs review

The use of continuous glass facades on residential buildings facing st...

6-4-4-4

Relation 'must_not_face' not handled by topology agent — needs review

1-6-4-5-4 For providing the required natural light and ventilation of ...

6-4-5-4

Conditional rule (condition: when window area is less than the required minimum) — needs human review

The minimum clear height of steps and their landings along the entire ...

6-7-1-5-4

Object 'step_and_landing_clear_height' not mapped to a measurable value — needs review

In buildings of groups 4 and 5, the rescue station must be at least 0....

6-8-12-9-4

Object 'rescue_station_width' not mapped to a measurable value — needs review

In buildings of groups 4 and 5, the rescue station must be at least 0....

6-8-12-9-4b

Conditional rule (condition: per_additional_floor_up_to_max_0.5_m) — needs human review

In internal stairs of residential units that are not required to be ac...

7-1-1-7-4

Relation 'must_be_installed_on_one_side_if_not_accessible_or_level_difference_gt_0.70m' not handled by topology agent — needs review

In internal stairs of residential units that are not required to be ac...

7-1-1-7-4

Stair-related rule but no stair element detected — confirm whether a stair is required for this plan

If semi-open spaces are located within an access or egress route, in a...

7-1-7-5-4

Relation 'must_comply_with' not handled by topology agent — needs review

If semi-open spaces are located within an access or egress route, in a...

7-1-7-5-4

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

Taking security measures for the building and entrance (such as instal... 7-10-12-9-4
Relation 'must_have_security_measures' not handled by topology agent — needs review

In the design and construction of buildings, in accordance with sectio... 7-12-9-4
Relation 'must_accommodate' not handled by topology agent — needs review

In the design and construction of buildings, in accordance with sectio... 7-12-9-4
Egress reachability OK; specific egress details (width, signage, swing direction) need human review

The maximum slope for open ramps in medium and large private parking a... 7-2-10-5-4
Object 'open_ramp' not mapped to a measurable value — needs review

If the building has a dry sauna, it must have at least one door that c... 7-2-13-5-4
Object 'sauna window' not mapped to a measurable value — needs review

If the building has a dry sauna, it must have at least one door that c... 7-2-13-5-4
Glazing rule not in a directly checkable ratio form — needs review

If the building has a dry sauna, it must have at least one door that c... 7-2-13-5-4b
Object 'sauna window' not mapped to a measurable value — needs review

If the building has a dry sauna, it must have at least one door that c... 7-2-13-5-4b
Glazing rule not in a directly checkable ratio form — needs review

The required lighting and ventilation of the spaces, provided the cond... 7-2-5-4
Relation 'may_be_provided_via_sunroom_if_requirements_met' not handled by topology agent — needs review

In buildings of groups 1 to 5 located on sites smaller than 200 square... 7-3-8-5-4a
Object 'courtyard' not mapped to a measurable value — needs review

In buildings of groups 1 to 5 located on sites smaller than 200 square... 7-3-8-5-4a
Window faces external open space / light well — site condition cannot be verified from a 2D plan; confirm on site

In buildings of groups 1 to 5 located on sites smaller than 200 square... 7-3-8-5-4b
Object 'courtyard' not mapped to a measurable value — needs review

In buildings of groups 1 to 5 located on sites smaller than 200 square... 7-3-8-5-4b

Window faces external open space / light well — site condition cannot be verified from a 2D plan; confirm on site

In buildings with four or more above-ground floors, at least one publi... 7-7-1-5-4

Relation 'must_extend_to' not handled by topology agent — needs review

In buildings of groups 4 and 6 on northern plots, whenever the rescue ... 7-8-12-9-4a

Relation 'must_not_pass_through' not handled by topology agent — needs review

In buildings of groups 4 and 6 on northern plots, whenever the rescue ... 7-8-12-9-4b

Relation 'must_be_suitable_for' not handled by topology agent — needs review

In each residential unit with a floor area of 75 square meters or more... 8-1-1-7-4a

Conditional rule (condition: unit_floor_area >= 75 m2) — needs human review

In residential units with a floor area less than 75 square meters, tha... 8-1-1-7-4b

Conditional rule (condition: unit_floor_area < 75 m2) — needs human review

The minimum width of other accommodation spaces and rooms in residenti... 8-1-1-7-4c

Object 'other_accommodation_space_or_room' not mapped to a measurable value — needs review

1-8-1-5-4 The slope of pedestrian passages that are located in the ma... 8-1-5-4

Conditional rule (condition: located in main access or egress route) — needs human review

1-8-1-5-4 The slope of pedestrian passages that are located in the ma... 8-1-5-4

Conditional rule (condition: accessibility for disabled persons not mandatory) — needs human review

2-8-1-5-4 Slopes must have landings at the top and bottom, at turning... 8-1-5-4b

Object 'landing' not mapped to a measurable value — needs review

2-8-1-5-4 Slopes must have landings at the top and bottom, at turning... 8-1-5-4b

Conditional rule (condition: accessibility for disabled persons not mandatory) — needs human review

2-8-1-5-4 Slopes must have landings at the top and bottom, at turning... 8-1-5-4b

Conditional rule (condition: accessibility for disabled persons not mandatory) — needs human review

3-8-1-5-4 The width of slopes located in the main access and egress r...

8-1-5-4c

Conditional rule (condition: must equal required main corridor width) — needs human review

3-8-1-5-4 The width of slopes located in the main access and egress r...

8-1-5-4c

Conditional rule (condition: accessibility for disabled persons not mandatory) — needs human review

Installation of a chain lock and eye bolt on the entrance doors of res...

8-10-12-9-4

Relation 'must_have_chain_and_eye_bolt' not handled by topology agent — needs review

In building design, emergency routes from outside the building must be...

8-12-9-4a

Relation 'must_be_provided_from' not handled by topology agent — needs review

In building design, emergency routes from outside the building must be...

8-12-9-4a

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

Providing emergency routes in a building does not eliminate the mandat...

8-12-9-4b

Relation 'must_not_replace' not handled by topology agent — needs review

Providing emergency routes in a building does not eliminate the mandat...

8-12-9-4b

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

The maximum slope for covered ramps in small private parking areas is ...

8-2-10-5-4

Object 'covered_ramp' not mapped to a measurable value — needs review

All dwelling rooms must have at least one entrance door complying with...

8-2-5-4b

Object 'door_height' not mapped to a measurable value — needs review

The use of sliding or folding doors between bedrooms and annexed space...

8-2-5-4d

Relation 'must_not_be_main_entrance' not handled by topology agent — needs review

In buildings of groups 1 to 5 located on sites of 200 square meters or...

8-3-8-5-4a

Conditional rule (condition: if site area $\geq$ 200 m²) — needs human review**In buildings of groups 1 to 5 located on sites of 200 square meters or...**

8-3-8-5-4b

Conditional rule (condition: if site area $<$ 200 m²) — needs human review

All glass surfaces with a width greater than 90 m and an area greater ...

8-4-4-4a

Conditional rule (condition: adjacent_to open_space_or_passage) — needs human review

All glass surfaces with a width greater than 90 m and an area greater ...

8-4-4-4a

Window faces external open space / light well — site condition cannot be verified from a 2D plan; confirm on site

All glass surfaces with a width greater than 90 m and an area greater ...

8-4-4-4b

Conditional rule (condition: adjacent_to open_space_or_passage) — needs human review

All glass surfaces with a width greater than 90 m and an area greater ...

8-4-4-4b

Window faces external open space / light well — site condition cannot be verified from a 2D plan; confirm on site

In a building that has a ramp to its roof, access to the roof must be ...

8-7-1-5-4

Relation 'must_be_provided_through' not handled by topology agent — needs review

In a building that has a ramp to its roof, access to the roof must be ...

8-7-1-5-4

Stair-related rule but no stair element detected — confirm whether a stair is required for this plan

The minimum distance of group 7 buildings from adjacent boundaries, wh...

8-8-12-9-4

Conditional rule (condition: vehicular_access_required_for_group_7) — needs human review

The minimum distance of group 7 buildings from adjacent boundaries, wh...

8-8-12-9-4b

Conditional rule (condition: pedestrian_access_required_for_group_5) — needs human review

In residential occupancies, the height of any accommodation space of 1...

9-1-1-7-4a

Conditional rule (condition: when more than 50% of floor area and more than 75% of living room or hall area) — needs human review

Door and window hinges in buildings and public and residential occupan...

9-10-12-9-4

Relation 'must_not_be_accessible_from_outside' not handled by topology agent — needs review

Providing separate vehicle entry and exit in large public parking area...

9-2-10-5-4

Relation 'must_be_separate' not handled by topology agent — needs review

Providing separate vehicle entry and exit in large public parking area...

9-2-10-5-4

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

In all covered pools, depending on the type of use and the number of u...

9-2-13-5-4

Conditional rule (condition: for public covered pools) — needs human review

In all covered pools, depending on the type of use and the number of u...

9-2-13-5-4

Egress reachability OK; specific egress details (width, signage, swing direction) need human review

In the vicinity of or above a false ceiling, any water, sewage, gas pi...

9-4-9-4

Could not map subject/object to room categories (subject='any water, sewage, gas pipe, canal, or similar installations', object='vents, supporting network and other parts of the false ceiling')

Dwelling spaces must have a minimum floor area of 50/6 square meters.

1-2-2-5-4a

Room_01: area = 9.0 m (required ≥ 8.33 m) → PASS

The finished horizontal dimension of the smaller side of any sanitary ...

1-2-6-5-4a

Room_bath: minimum horizontal dimension = 4.0 m (required ≥ 1.0 m) → PASS

Each dwelling space must have at least one door and one glazed window ...

1-3-2-5-4

All room_bedroom rooms can reach an exit — compliant

The main "door" must be of hinged type with a minimum clear width of 0...

1-5-1-5-4a

D-01: clear width = 0.9 m (required ≥ 0.9 m) → PASS

The main "door" must be of hinged type with a minimum clear width of 0...

1-5-1-5-4a

D-front: clear width = 1.0 m (required ≥ 0.9 m) → PASS

The minimum free net floor area of the kitchen (excluding shelf/cabine...

10-1-1-7-4b

Room_kit: free floor area = 6.0 m (required ≥ 2.75 m) → PASS

A dwelling space must have a minimum width of 15/2 meters.

2-2-2-5-4

Room_01: width = 9.0 m (required ≥ 7.5 m) → PASS

Requirements for sanitary spaces with skylight lighting: For providing...

4-6-5-4

All room_bathroom rooms can reach an exit — compliant

If natural lighting cannot be provided through a regular window in the...

6-2-5-4

All habitable rooms meet glazing ratio ≤ 0.5 — compliant

All dwelling rooms must have at least one entrance door complying with...

8-2-5-4a

D-01: minimum = 0.9 m (required ≥ 0.8 m) → PASS**All dwelling rooms must have at least one entrance door complying with...**

8-2-5-4a

D-07: minimum = 0.8 m (required ≥ 0.8 m) → PASS**All dwelling rooms must have at least one entrance door complying with...**

8-2-5-4a

D-front: minimum = 1.0 m (required ≥ 0.8 m) → PASS**Over the remaining floor area of these spaces and over the entire area...**

9-1-1-7-4b

Room_01: height = 9.0 m (required ≥ 2.4 m) → PASS

Methodology. Numeric and spatial verdicts (PASS/FAIL) are produced by deterministic checks against the building model. Rules that depend on information not derivable from the plan — site conditions, interpretive requirements — are flagged "review" for a qualified professional to confirm; they are never auto-judged. Scope: M-4 residential. Engine runtime: 3.83s. This report is a decision-support tool and does not replace professional certification.