Tab. 17 - Participation factor Fp

 0°
 20°
 30°
 35°
 45°

 1,00
 0.50
 0.60
 0.65
 0.67
 0.72