Tab. 8 - Coefficient of passive resistance given by temperature

Temperature	°C	+ 20°	+ 10°	0	- 10°	- 20°	- 30°
Factor	Ct	1	1,01	1,04	1,10	1,16	1,27