NETWORK HEALTH / COORDINATOR'S DECISION SHEET

Send the technician to S07.

8 stations · 01 March–11 April 2025 · all times UTC

Use observations by sensor and interval. Keep independently corroborated weather extremes; withhold the faulty periods listed in **flags.csv**.

48,314	214	144	40
source records examined	scheduled intervals missing	replayed copies removed	issue / retained-event intervals

Data available for this summary

Station	Temp.	Humidity	Pressure	Wind	Direction	Rain	Sunlight
S01	100.0%	100.0%	100.0%	100.0%	100.0%	100.0%	100.0%
S02	100.0%	100.0%	**49.3%**	100.0%	100.0%	100.0%	100.0%
S03	**92.0%**	100.0%	100.0%	100.0%	100.0%	100.0%	100.0%
S04	**93.8%**	100.0%	100.0%	100.0%	100.0%	**89.1%**	100.0%
S05	100.0%	**91.7%**	100.0%	100.0%	100.0%	100.0%	100.0%
S06	100.0%	100.0%	100.0%	100.0%	100.0%	100.0%	100.0%
S07	100.0%	100.0%	100.0%	**61.1%**	100.0%	100.0%	100.0%
S08	**96.5%**	**96.5%**	**96.5%**	**96.5%**	**96.5%**	**96.5%**	**96.5%**

Scheduled intervals remaining after corrections, duplicate removal and exclusions; shaded cells have incomplete coverage (48,384 station-intervals expected). Report coverage alongside each channel's summary.

What changes the summary

- **S06 · Clock recovered.** 2,639 time labels corrected using independent GPS; observations retained.
- **S02 · Pressure withheld.** Later pressure excluded from 21 Mar 17:20; calibration is unverified.
- **S03 · Temperature withheld.** Stuck from 18 Mar 06:00 to 21 Mar 14:00; isolated spikes also removed.
- **S05 · Humidity withheld.** 07 Mar 12:00–11 Mar 00:00; prolonged overshoot exceeds ordinary saturation.
- **S04 · Rain totals incomplete.** Dry readings during peer rainfall and a later water release; withheld amounts are not reconstructed.
- **S07 · Wind withheld.** Scale change from about 26 Mar 16:00; check the sensor-to-logger conversion.

Do not treat gaps as zero rain or extrapolate an incomplete rain total into a complete one. Localized extremes can be real; the checker retains multi-station warm, dry, windy episodes.

Send the technician to S07 · Riverbend Farm

The wind change persists through the final day after a sensor replacement; verifying the model and logger conversion offers a focused, practical repair.

1. **0–10 min** Photograph the sensor model and logger settings; compare the documented pulse-to-speed conversion first.
2. **10–40 min** Check wiring and free rotation; change the conversion only after confirming a mismatch, never from the peer ratio alone.
3. **40–60 min** Verify against a reference or manufacturer-supported check, confirm live logging, and record settings, results and UTC intervention time.

Why this visit first: S04 is second: its sunlight-linked warming needs a reference thermometer and exposure assessment; the cause and repair are less certain.

Calls that still need judgment

S04: daytime warming against peers grew 3.5°C; strongly sunlit periods are withheld from 01 Apr 17:10. Earlier onset is unclear: defer full-window temperature maxima and trend claims.

S05: GPS and installation coordinates disagree; retain weather provisionally and verify location before mapping it.

Coverage measures availability under these checks; calibration and snow capture remain unverified. Report the observation window with each summary. See flags.csv for interval evidence.