
Labels needed to certify sensitivity
target sensitivity 0.75
target sensitivity 0.80
target sensitivity 0.85
Labelled septic patients needed
5,000
2,000
1,000
500
200
100
2.0
3.0
5.0
7.5
10.0
True sensitivity above the target (percentage points)