

Model	Part No	Part Name
4L45W	M015S030	FRM_ASM_2NDC_RH_HALF_UN_(MIX)

CHECKED	OK	REPAIR	SCRAP
100	99	1	0

TTD KASIE	TTD OPERATOR	NIK OPERATOR	TAHUN	BULAN	TANGGAL	SHIFT
A	B	C	2025	7	21	1

No	KEROPOS	KURANG	BOLONG	UNDERCUT	SPATTER	TIDAK TEPAT
1						ST
2						ST
3						ST
4						ST
5						08
6						18
7						28
8						38
9						48
10						58
11						68
12						78
13						88
14						98
15	■					09
16						19
17						29
18						39
19						49
20						59
21						69
22						79
23						89
24						99
25						001

No	KEROPOS	KURANG	BOLONG	UNDERCUT	SPATTER	TIDAK TEPAT
26						18
27						28
28						38
29						48
30						58
31						68
32						78
33						88
34						98
35						08
36						18
37						28
38						38
39						48
40						58
41						68
42						78
43						88
44						98
45						07
46						17
47						27
48						37
49						47
50						57

FOLDING KERAS	KARAT	DEFORMASI	CAT/COATING	TIDAK MASUK GONO GO	STEP LOSS	STEP LONCAT	STEP LEBIH	STEP KURANG	SAHAL PASANG	GORESAN	NOISY	TIDAK LENGKAP
CATATAN:	CATATAN											