Job Safety Analysis (JSA)

Title

Customer Name & Location: Effective Date



Step No	Task/Step	Potential Safety/Environ Hazards What can go wrong and what would the effect be?	Identified Hazard/Risk Controls hat will be done to mitigate / control the hazards?	Required PPE	Risk Ranking After engiementing stensified hazard controls	Notes/Comments
	Describe the steps to complete the job task			Enter required PPE or PPE code		
1	Disconnect DH Cable	Electrical	LOTO, Hot gloves	ABFGIKRE	low	
2	Flange up BOP	Pinch points and overhead hiszard, slips, trips	Hard hat, gloves, ST boots safety glasses, tag lines	ABFGIKR	low	
3	Unseat and remove hanger	Pinch points and overhead hazard, slips, trips	Hard hat, gloves, ST boots safety glasses	ABFGIKR	low	
4	Rig up spoolers and pull well	Pinch points and overhead hazard, slips, trips	Hard hat, gloves, ST boots safety glasses, tag lines	ABFGIKR	low	
5	Disassemble and lay down	Pinch points and overhead hazard, stips, trips	Hard hat, gloves, ST boots safety glasses, tag lines	ABFGIKR	low	
6						

FREQUENCY(FREQ)	SEVERITY (SEV)	RISK SCORES	PPE CODES	
Low - Harm or loss is unlikely to occur (Seldom - Occurs once every 5-10 ym). Medium - Harm or loss as possible, although only expected to occur occasionally (Docasional - Occurs once or more every 1 - 5 ym). High - Harm or loss is expected to occur frequently. (Prequent - Occurs one or more every 1-12 months).	Low - Minimal near miss or minor first aid injury. Medium - Recordable injury, lost time, secous property demage, free extinguished ensite. High - Serious injury or Fatelity, major equip damage, fires requiring offsite assistance, facility wide fire, explosion, offsite impact etc.	Low - Acceptable with present controls in place. Medium - Further controls should be considered and recommended. High - Additional controls must be identified and mandated.	ft: Safety Shoes	cartridge O. Supplied Air Respirator, circle: SCBA or Artine 1: Fall Protection

I hereby certify the Controls and PPE requirements stated above represent the minimum protection required to perform the task safely.

Name

Select Job Title	Signature:	
Select Job Title	Signature:	
Select Job Title	Signature:	