ORD-3_v2 Giling Computer Applications

Spax / DDX / DCC232 Booster

Revised: Aug 14 2014

Revision: 2.0

Ref	Part	Order nr
	PCBoard ORD-3	
R1	Resistor 1 KOhm ¼ Watt	
R1 R2		
	Resistor 3.3 KOhm ¼ Watt	
R3	Resistor 1 Kohm ¼ Watt	
R4	Resistor 220 KOhm ¼ Watt	EW AVIAL O 22
R5	Resistor 0.33 Ohm 5 Watt	5W AXIAL 0,33
R6	Resistor 10 KOhm ¼ Watt	
R8	Resistor 150 Ohm ¼ Watt	
R9	Resistor 330 Ohm ¼ Watt	2W PRAUT 400
R10	Resistor 100 Ohm 2 Watt	2W DRAHT 100
R11	Resistor 10 KOhm ¼ Watt	
R13	Resistor 330 Ohm ¼ Watt	***
R14	1.2 KOhm ¼ Watt 1% metali	
R15	680 Ohm ¼ Watt 1% metalfi	
R16	560 Ohm ¼ Watt 1% metalfi	
C1	220 nF MKT	MKS-2 220N
C2,C3	15 nF MKT	MKS-2 15N
C4	ELCO 100 uF 35V radial	RAD 100/35
C5	ELCO 1000 uF 25V radial	RAD 1000/25
C6,C10	ELCO 10 uF 16V radial	RAD 10/16
C9,C11	ELCO 4.700uF 35V	RAD 4.700/35
C12, C14, C1		KERKO 100n
C13	100 nF MKT 7,5 mm	MKS-4 100N
D1	Schottky diode	1N5822 OR SB330
D2	Diode	N4148
LED1,LED3	LED 3mm green	LED B-3 GN
LED2	LED 3mm red	LED B-3 RT
SW1	dip switch 3-pole	
U2	socket Dil8	
U3	socket Dil8	
U4	socket Dil14	
U5	Opto-coupler	PC817
J1	Connector	AKL230-04+AKL249-04
St1,St2,St3	RJ12 connector	MEBP 6-6s
F1	FUSE 1,85 Amp	PFRA185
*) *)	*) Cooling	V PR127/94-M3
*) *)		M3x8
VR1 *) *)	*) 5 V regulator	7805 TO220
VR2 *) *)		LM2576T-12
U1 *) *)	*) Power IC	L6203
GR1 *) *)	*) BRIDGE 6Amp	KBU6A
	Clips	MC725
U2	PIC12F675	
U3	6N137	
U4	CD4011	
	Mounting supports	DA4-10mm
	Screws	M4x8
	Connector cpl	SubD 9 male.
RS232 *)))	Female d-connector	D-Sub BU 09EU
L1	INDUCTOR 100 uH	FED 100u
		=
	Cable RJ12	

*) *) *)Important !!!!!!

For Power IC and Regulators:

First mount cooling device with screws, then insert IC and regulators, bending wires so that they are flat to cooling, then fix clamps to hold IC's and after that solder IC's.

Assemble all parts in order of this list. Insert IC's in sockets last.

*))) could be replaced by DB9-USB-F for direct USB connection