

Vehicle Diagnostic Report

The Report is created by **LAUNCH X431**

Vehicle Information



Year:2019
Make:MERCEDES-BENZ
Model:Sprinter

Engine Size:OM 642 with Brake Assist 3L 6 Dual Overhead Cam (DOHC)
Odometer:17039 miles
Vehicle Software Version:V21.98
Diagnostic Application Version:V8.00.039
Diagnostic path:Automatically Search

Repair Shop

Shop Name:
Address:
Zip Code:
Telephone:
Email:
SN:989347793502
Test Time:2026-06-18 12:05:12



System fault code 【Pre-Repair】

The following systems is abnormal:

ECM - Engine Control Module(CDI)

DTC (5)

1.P300660 AdBlue(R) System Warning Stage 1: The AdBlue(R) Fill Level Is Low.	CURRENT And STORED
2.P300E3A Ignore Event And Erase. (Only For The Development Department)	CURRENT And STORED
3.P300964 Ignore Event And Erase. (Only For The Development Department)	CURRENT And STORED
4.P300965 Ignore Event And Erase. (Only For The Development Department)	CURRENT And STORED
5.P300966 Ignore Event And Erase. (Only For The Development Department)	CURRENT And STORED

ISM - Intelligent Servo Module For DIRECT SELECT

DTC (2)

1.U012187 This Error Code Can Be Ignored And Erased.	STORED
--	--------

2.P179D00 The Redundancy System For DIRECT SELECT Was Activated. _ CURRENT And STORED

ESP - Electronic Stability Program

DTC (4)

- | | |
|--|---------|
| 1.B23AA13 The Left Brake Caliper Has A Malfunction. There Is An Open Circuit. | CURRENT |
| 2.B23AB13 The Right Brake Caliper Has A Malfunction. There Is An Open Circuit. | CURRENT |
| 3.B23AC01 The Switch " Electric Parking Brake" Has A Malfunction. There Is A General Electrical Fault. | CURRENT |
| 4.U0427EA Implausible Data Were Received From The Electronic Ignition Lock. _ | STORED |

SAM - Signal Acquisition And Actuation Module

DTC (4)

- | | |
|--|--------------------|
| 1.B11C213 No Additional Battery Is Present. There Is An Open Circuit. | CURRENT And STORED |
| 2.B174901 The Rear Interior Illumination Has A Malfunction. There Is A General Electrical Fault. | CURRENT And STORED |
| 3.B197901 The Special Equipment " Interior Illumination In Rear Passenger Compartment" Has A Malfunction. There Is A General Electrical Fault. | CURRENT And STORED |
| 4.U014341 Communication With The Multifunction Control Unit Has A Malfunction. There Is A General Checksum Error. | CURRENT And STORED |

MFK - Multifunction Camera



DTC (1)

- | | |
|---|--------------------|
| 1.U042082 Implausible Data Were Received From Control Unit " Power Steering". The Instruction Counter Is Not Updated. | CURRENT And STORED |
|---|--------------------|

IC - Instrument Cluster

DTC (1)

- | | |
|--|--------|
| 1.B226656 The Drive Authorization Data Are Implausible. An Incorrect Or Incompatible Configuration Was Detected. | STORED |
|--|--------|

ESA 'Driver' - Electrical Seat Adjustment " Driver" With Memory Function

DTC (1)

- | | |
|--|--------|
| 1.U016887 Communication With The Electronic Ignition Lock Has A Malfunction. The Message Is Missing. | STORED |
|--|--------|

ESA ' Front Passenger' - Electrical Seat Adjustment "Front Passenger" With Memory Function

DTC (1)

- | | |
|--|--------|
| 1.U016887 Communication With The Electronic Ignition Lock Has A Malfunction. The Message Is Missing. | STORED |
|--|--------|

The following systems are OK:

- 1.FSCU - Control Unit " Fuel Pump"
- 2.CPC - Control Unit " Powertrain"
- 3.DCU - LF - Left Front Door
- 4.EZS - Electronic Ignition Lock
- 5.SG - LEDSW-L - Left Headlamp

- 6.SG - LEDSW-R - Right Headlamp
- 7.AC - Air Conditioning
- 8.SRS - Supplemental Inflatable Restraint System
- 9.PARK - Parking System
- 10.EST - L - Left Electric Sliding Door
- 11.EST - R - Right Electric Sliding Door
- 12.Trailer Recognition Module - Trailer Recognition
- 13.PSM - Parameterizable Special Module
- 14.UCP - Upper Control Panel
- 15.SCM - Steering Column Module
- 16.DCU - RF - Right Front Door
- 17.ZAN - Audio/COMAND Display
- 18.HERMES - Communication Module " Telematics Services"
- 19.MTAS - Mobile Phone Cradle
- 20.Head Unit - MBUX Multimedia System
- 21.LIN:BSN - Battery Sensor
- 22.LIN:RGLS - Rain/Light Sensor
- 23.LIN:AAC-FR - Control And Operating Unit "Automatic Air Conditioning"

.....

Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!