

## Force sensor



This force sensor can measure force up to 3 Kg. Can be used as scale, pressure switch etc.

It will give an analog output of voltage that connects to a PC through USB port.







eCraft2Learn H2020-731345 - UEF.

This work is licensed under a License Creative Commons Atribution 4.0 International.

This project has rececived funding from the European Union's Horizon 2020 Coordination & Research and Innovation Action Under Grant Agreement No 731345.