$H(x, p_x, y, p_y, z, p) = (-\sqrt{p^2 - p_x^2 - p_y^2 + 1} - E/v_0)L$.