

FDZ Transport Simulator




172.68.92.1



FDZ
Simulator

198.68.92.11



RO

Sled w

Con

Settings

New Station

Transportation speed : 03 Sec

About

IO

Empty sled

No congestion



Oct 15 00:14:14: STStK001<Message-ID>0002ro
Oct 15 00:14:15: StSTA001<Message-ID>0000
Oct 15 00:15:34: STStK001<Message-ID>0003ro
Oct 15 00:14:14: StSTF001<Message-ID>0002xx
Oct 15 00:23:12: SPXSStK001<Message-ID>0002aa
Oct 15 00:23:14: StSTF000<Message-ID>0000
Oct 15 00:40:54: STStK003<Message-ID>000423io
Oct 15 00:41:00: StSTA001<Message-ID>0000
Oct 15 00:52:21: STStK002<Message-ID>000223
Oct 15 00:52:22: StSTA001<Message-ID>0000
Oct 15 00:52:22: StSTA001<Message-ID>0000
Oct 15 00:52:22: StSTA001<Message-ID>0000

Connected to 172.68.92.1
Empty sled ordered to RO
Empty sled arrived in RO
Congestion in station RO
Command not executed "SPXSSTK001<Message-ID>0002aa"
Release carriage with ID 23
Reposition the carriage with id 23 to position io
Port number changed to 23
Connection lost to 172.68.92.1