HCAI Department of Health Care Access and Information

Site Map

Lookup a facility by entering a facility number or...
17438 Healthbridge Children's Hospital-Orange

Regulatory Deadlines per 2026 CAC Chapter 6, Article 1, Section 1.2.2:
March 1, 2030: Deadline to submit construction documents for NPC 4 New Construction, and Removal of Acute Care Service projects.
March 1, 2030: Deadline for permits to be obtained for NPC 4/4D, NPC 5, Demolition, and Removal of Acute Care Service projects.
January 1, 2040: Deadline for all seismic compliance projects to be completed.

What You'll Find on This Page
This page is organized into several sections that explain how the hospital plans to achieve seismic compliance across its campus. Each section presents a different level of detail, from high-level timelines to building-specific information.

Seismic Compliance Plan for 17438 Healthbridge Children's Hospital-Orange

Status: Not Approved

"Not Approved" indicates that the submitted Compliance Plan has been reviewed and is not approved because, although the facility is reporting that Main Building is already 2030 compliant, NPC 5 is also required. According to the HCAI database, there is no recorded evaluation or construction project for BLD-03189 Main Building to achieve the NPC-5 reclassifications required for 2030 compliance. Please submit evaluation and retrofit projects and a path for compliance to reach 2030 deadline. See the following comments. An amended Compliance Plan shall be submitted to address and resolve these comments, the Office is available to discuss any comments with the facility and to provide support in resolving the outstanding issues.

Summary Schedule - Click to Hide

Summary Schedule
This section provides a visual timeline for each building on the hospital's campus, showing the reported plan for achieving seismic compliance. Milestones are represented by circles on the timeline—hover over a circle to see additional details. All milestones and dates are reported by the hospital. If HCAI has verified that a milestone was met, it is marked as met.

Summary Schedule Legend

Milestone	Missed Milestone	Met Milestone
Critical Milestone	Missed Critical Milestone	Met Critical Milestone

Compliance Type Tables - Click to Hide

Compliance Method:
This table lists each building on the hospital's campus and the method the hospital has reported it will use to achieve seismic compliance. Any comments or clarifications provided by HCAI are included alongside the hospital's reported information.

Building No.	Bldg. Name	SPC	NPC	Compliance Type (Reported by Hospital)	Narrative (Reported by Hospital)
BLD-03189	Main Building	5	4	2030 Compliant Building	Building is of original HCAI approved from 1999.

Building Milestone Description Table - Click to Hide

Description of Milestones to achieve Seismic Compliance:
This table shows detailed, building-level milestone information reported by the hospital. Each building may have up to ten milestones that describe the steps the hospital plans to take—and the timelines for taking them—to achieve seismic compliance. Any HCAI comments on the reported milestones are included in the table.

Building No.	Milestone Type	Description	Completion Date (Reported by Hospital)	HCAI Comments
BLD-03189	2030 Compliant Building	Original build/ HCAI approved	01/01/2000	This building is not yet 2030 compliant. Please add critical milestones to the Co

Facility's Request for Delay - Click to Hide

HCAI has not received an application for delay from this facility. Applications for a delay to the January 1, 2030 seismic compliance deadline under AB 869 were due on January 1, 2026 per 2026 CAC Chapter 6, Article 1, Section 1.5.2

Who owns this facility? **VSC HBO, LLC**
What type of entity owns this facility? **Private (Investor - Limited Liability Company)**
Who manages the hospital? **VSC HBO, LLC**
What type of entity manages the hospital? **Private (Investor - Limited Liability Company)**
Who is financially responsible for the seismic upgrades? **VSC HBO, LLC**
Other contact financially obligated for infrastructure improvements: **None**

Click to Download PDF