






D47 and D48 are only populated if you are using an external MAP sensor. Do not populate these locations if you are using the on-board sensor.


Do not populate C23 and C21 if you are using an external MAP sensor.




git hash: Oeafe8520d				
File: inputs.sch				
Sheet: /Inputs/				
Title: Jaguar PCB for FreeEMS				
Size: A4	Date: 16 feb 2013		Rev: 0.4-alpha	
KiCad E.D.A.	eeschema (2012-01-19 BZR 3256)-stable		ld: 4/7	











git hash: Oeafe8520d				
File: Outputs.sch				
Sheet: /Outputs/				
Title: Jaguar PCB for FreeEMS				
Size: A4	Date: 16 feb 2013	Rev: 0.4-alpha		
KiCad E.D.A.	eeschema (2012-01-19 BZR 3256)-stable	ld: 5/7		





git hash: 0e	nfe8520d			
File: PowerSupplies.sch				
Sheet: /Power Supplies/				
Title: Jaguar PCB for FreeEMS				
Size: A4	Date: 16 feb 2013	Rev: 0.4-alpha		
KiCad E.D.A.	eeschema (2012-01-19 BZR 3256)-stable	ld: 7/7		