
PP Phasors 010

Unlimited Attempts.

Find t_1 .

Express the current as a phasor

$$\mathbf{I} = A_2 \cdot e^{jB_2}$$
 with $0 \le A_2$ and $-180^\circ \le B_2 \le 180^\circ$



Given Variables:

. . . .

Calculate the following:

t1 (ms):

-2

A2 (A):

6

B2 (degrees):

60