

EG25-G-GB Release Notes

LTE Module Series

Rev. EG25-G-GB_Firmware_Release_Notes_V0707_01.001.001

Date: 2019-04-25



1. Preamble

This document provides the Release Notes for EG25-G-GB firmware version EG25GGBR07A07M2G_01.001.01.001. It describes major changes compared to for EG25-G-GB firmware version EG25GGBR07A06M2G_01.001.01.001. For a detailed listing of all changes, refer to the EC25 AT Command Set.

2. New Features

Item /Category	Brief Description	Since
AUDIO	Optimized AT command AT+QAUDCFG="encgain".	R07A04_01.
AUDIO	Optimized / (1 command AT+QAODO) O= chegan :	001.01.001
GENERAL	Added AT command AT+QODM="hostdevice" for ATT OMA.	R07A05_01.
GLINLINAL	Added AT Command ATTGODIN- HOStdevice Tot ATT OWA.	001.01.001
AUDIO	Added AT command AT+QAUDCFG="nau8810/config".	R07A05_01.
	Added All Collinated All Paragon 6- Haddo To/colling .	001.01.001
GENERAL	Added AT command AT+QODM="fumo".	R07A06_01.
GLINLINAL	Added Al Collinand Alfacolin- Idillo .	001.01.001
GENERAL	Added AT command AT+QODM="dme" to guery OMA state.	R07A06_01.
GENERAL	Added At Continiand ATTGODIN - differ to query ONA state.	001.01.001
GENERAL	Added AT command AT+QGPSCFG="fixfreq" to set the NMEA	R07A07_01.
GENERAL	output frequency.	001.01.001
VOICE CALL	Added AT commands AT+QIMSACT, AT+DIAL, AT+CHLDMPTY.	R07A07_01.
	Adda Al Commando Al Tamboaci, Al Tolicolar II.	001.01.001
VOICE CALL	Added AT command AT+QECBM only for Verizon.	R07A07_01.
VOICE CALL	Added At Tooliniana ATTGEODIN Only for Venzon.	001.01.001

3. Improved Features

Item/Category	Brief Description	Since
NETWORK	Solved the issue that scanning flag was not cleared when	R07A04_01.
	executing AT+QCOPS returned error.	001.01.001
DECTA	Ontimized DEOTA present	R07A04_01.
DFOTA	Optimized DFOTA process.	001.01.001
	Optimized below AT commands	
ALIDIO	AT+QAUDCFG="alc5616/dlgain",	R07A04_01.
AUDIO	AT+QAUDCFG="alc5616/ulgain",	001.01.001
	AT+QAUDCFG="nau8814/dlgain".	



	M. I'C. I	R07A04 01.	
SSL	Modified SSL to support TLS_ECDHE_RSA_WITH_AES_256_GCM_SHA384.	001.01.001	
TCP/UDP	Solved the problem that when established multiple TCP connection, it was abnormally to loop QIRD quickly.	R07A05_01. 001.01.001	
NETWORK	Added cell blacklist function when RRC access failure reached a certain condition.	R07A05_01. 001.01.001	
GENERAL	Optimized file system protection mechanism.	R07A05_01.	
PPP	Solved the problem that the host could not establish PPP under the GSM network.	R07A06_01.	
AUDIO	Fixed the problem that the incoming call has no ringtone.	R07A06_01.	
NETWORK	Supported WCDMA BAND19 for AT command AT+QCFG="BAND".	R07A07_01. 001.01.001	
GENERAL	Optimized parameter partition restore mechanism.	R07A07_01. 001.01.001	
NETWORK	Solved the problem that AT command AT+QNWINFO could not support B66/B71 and corresponding frequency.	R07A07_01. 001.01.001	
GENERAL	Solved the problem that no response returned or URC for manufacturer command when executed AT+CMEE=0.	R07A07_01. 001.01.001	
GENERAL	Support to update operator MBN after upgrading module FW.	R07A07_01. 001.01.001	
TCP/UDP	Solved the problem of format error when executed AT command AT+QCFG="NTP".	R07A07_01. 001.01.001	
GENERAL	Solved the problem that the value of man and model could not be changed by AT command AT+QODM="hostdevice" .	R07A07_01. 001.01.001	
GENERAL	Solved the problem of returned format error when executed AT command AT+CCLK?.	R07A07_01. 001.01.001	
GENERAL	Solved the problem that when set the parameter of AT+CTZU to illegal value 2, it would be set and take effect unexpectedly, not fail.	R07A07_01. 001.01.001	
SIMCARD	Set that when the SIM card was locked in PUK2, allowed to execute AT+CPIN=<puk2>,<new pin2=""></new></puk2> to unlock PUK2.	R07A07_01. 001.01.001	
GENERAL	Added LTE band14/band66/band71 for the TX of AT command AT+QRFTEST.	R07A07_01. 001.01.001	
TCP/UDP	Supported to report the data length also when TCPIP reporting URC.	R07A07_01. 001.01.001	
GENERAL	Solved the problem that thermal engine isn't working.	R07A07_01. 001.01.001	
SIMCARD	Updated the TS25 PLMN list.	R07A07_01. 001.01.001	
GENERAL	Optimized RF Factory Test feature.	R07A07_01. 001.01.001	
TCP/UDP	Optimized the process when sending UDP data on different destination port.	R07A07_01.	



AUDIO	Solved the problem of no sound on pcm slave mode.	R07A07_01.
AUDIO	Supported pcm slot to be configurable.	R07A07_01.
VOICE CALL	Set that if the SIM card supported STK CALL CONTROL, the module should first send STK CALL CONTROL to the card after the ATD dialing, and then initiated a call to the network after getting SIM card permission.	R07A07_01. 001.01.001
TCP/UDP	Solved the problem that if TCP half-closed, error returned when executing AT+QISEND=0,0 .	R07A07_01. 001.01.001
GENERAL	Optimized single image upgrade.	R07A07_01. 001.01.001
DFOTA	Solved the DFOTA upgrade failure.	R07A07_01. 001.01.001
MQTT	Solved the problem that the module could not receive more than 1024 bytes of data sent by the MQTT server.	



4. Functions

Basic Function								
SMS	Voice Call	Data Call	Fax	USSD	PHB	STK	CMUX	FILE
Υ	Υ	N	N	N	Υ	N	N	N
Protocol F	Protocol Function							
QMI	TCP/ UDP	PPP	FTP	HTTP	NITZ	NTP	MQTT	
Υ	Υ	Υ	Υ	Υ	Υ	Υ	Υ	
Special Function								
SIM Detection	DECTA							
Υ	Υ							

NOTES

- 1. Y means the firmware supports this function.
- 2. N means the firmware does not support this function.