# Compressor Snap Ring Installation Precaution

Oct 25, 2022

**CONDITION**: Following A/C compressor installation (with magnetic clutch R&R), compressor is noisy and cooling performance is poor.

**CAUSE**: It's possible that the snap ring used to secure the stator and rotor was improperly installed.

**CORRECTION**: Snap rings with a beveled edge must be installed with the beveled edge facing away from the compressor. The snap ring must be fully seated and retain the stator and rotor securely.

| Product Group | Assembly | Category |
|---|---|---|
| Heat & Air Conditioning | Compressor | Repair Procedures |
| **Year** | **Make** | **Model** |
| All | All | All |

## Passenger Vehicles

## Commercial Vehicles





**Where to Buy**

**Find My Part**



**Find My Part**



**Where to Buy**

## Passenger Vehicles



**Find My Part**

## Commercial Vehicles



**Find My Part**



**Where to Buy**



**Where to Buy**

## Commercial/Industrial

Automatic Data Capture
EdgeCool
MovinCool
Robotics



Privacy Policy
Terms of Use
Do Not Sell or Share My Personal Information

Site Map

©2026 DENSO Products and Services Americas, Inc. All rights reserved.
First Time Fit, Endurovision, Iridium Power, Iridium Racing, Platinum TT and Iridium TT are registered trademarks of DENSO.

