

# Simple Arduino PID-Controller

DC-Motor demo






# Schematic – Open-Loop



# Schematic – Open-Loop (simplified)


- Assume plant dynamics do not change
- Serial output not relevant for control system

Simplify schematic




### Schematic – Closed-Loop

- Remove potentiometer with fixed set point
- Add PID controller and close the loop




#### Quadrature encoders



https://dronebotworkshop.com/rotary-encoders-arduino/

# Moving Average Window



moving average with window size = 3