


- Plant dynamics do not change
- Serial output not relevant for control system

Simplify schematic



- Remove potentiometer with fixed set point
- Add PID controller
- Close the loop

