POILHO 10 G.P.SOLAPUR Practical 4 of prepare and test stronger and crossover able. 9.1) Straight / Normal network Cables are used to Connect a pc to bub someter or switch. 2) O network cable used to connect a PC to PC is Coopsover. network Cable. @ RI Stands For Registered Tack 9.3 Horite the Steps to orecate a stoight cable, D Moip jour cable. on twist the twisted pair cable. 9 Appraige the witer in the order necessary for your needs orimp the Consection. Morite the Steps to check a cable with 30 Cable tester? 1). Pyrchate 9 Retherned Cask Jester make sure it has battery init and power it on of Aug one end of the Cable inte toansmit jack Plug the other end of cable into the occeiver Tack. is check the light on the foster.