





Visualizer



X: 61.0 | Y: 111.3 | Z: 4.0

Controls

Home All

Clear BBox

Bounding Box Points

P1 X9.0 Y177.0

Go

Update

P2 X159.0 Y177.0

Go

Update

P3 X159.0 Y37.0

Go

Update

P4 X9.0 Y37.0

Go

Update

XY Speed

12000

Z Speed

12000

Dist:

1 mm

mm

10 mm

X (Left/Right)

X +

X -

Y (Fwd/Back)

Y +

Y -


Z (Pen Up/Dn)

Z Up

Z Down

Command Queue Empty

Plotting Engine



Pen Z-Hop (mm)

8

Write Text

Plot Image

☐ Draw Bounding Box

Density / Line Gap


1.6 mm

Contrast / Threshold

0.5 x

Scale / Resize

100 %



Rotation

0°

Offset X (mm)

Offset Y (mm)

Plot Speed

Plotting Method

Crosshatching (Classic)

Plotting Progress

8%

Pause

Cancel / Done

Live Camera Feed

