


Visualizer



X: 61.0 | Y: 109.3 | Z: 4.0

Controls

Home All Clear BBox

Bounding Box Points

P1	X9.0 Y177.0	Go	Update
P2	X159.0 Y177.0	Go	Update
P3	X159.0 Y37.0	Go	Update
P4	X9.0 Y37.0	Go	Update

XY Speed 12000 Z Speed 12000

Dist: 1 mm 10 mm 10 mm

X (Left/Right)

X + X -

Y (Fwd/Back)

Y + Y -


Z (Pen Up/Dn)

Z Up Z Down

Command Queue Empty

Plotting Engine

Pen Z-Hop (mm) 8 Write Text Plot Image




☐ Draw Bounding Box

Density / Line Gap 1.6 mm

Contrast / Threshold 0.5 x

Scale / Resize 100 %



Rotation

0°

Offset X (mm)

0

Offset Y (mm)

-20

Plot Speed

Fast (12000)

Plotting Method

Crosshatching (Classic)

Plotting Progress

9%

Pause

Cancel / Done

Live Camera Feed

