




(a) Process loop: PLC scan periods**(b) Process loop: exact check****(c) Converter loop: PWM-tied periods****(d) Converter loop: exact check**