
NR2 ScorpionServer Image Data Plots (Flat lines means no data corruption)



NR2 ScorpionServer Image Data Plots (Flat lines means no data corruption) 20161024-180818 BitMap 18-g2x12 = no missing) Missing Drop Indication Dispense Row Number (blank lines skiped) 20161024-181400 BitMap 19-g2x16 = no missing) Missing Drop Dispense Row Number (blank lines skiped) 20161024-181410_BitMap_20-g2x16 = no missing) Missing Drop Indication Dispense Row Number (blank lines skiped) 20161024-181410 BitMap 21-g2x16 = no missing) Missing Drop Dispense Row Number (blank lines skiped) 20161024-183827 BitMap 22-g2x4 = no missing) Missing Drop Indication Dispense Row Number (blank lines skiped)

NR2 ScorpionServer Image Data Plots (Flat lines means no data corruption)

