## STUDY of SHEET METAL

Safety Precautions

1) Avoid touching the cut postion while eafting with snip

2) use snip only formetal that can be cut by applied hand force

3) Do not reach bekind the shear blade to hold small pieces being wife. The fips of the fingers cannot be seen and can easily be placed ender the blade

4) Do not try to hold small pieces of melal while they are being cut They are liable to tip up and tip your finger into the blade

5) Donof try to bend the sheet with hands

6) Use shoes and leather gloves.

## SHEET METAL SHOP HOPPER MAKING

Exp No: 5

DATE: October 22, 2021

To make a hopper of a given specification from a sheet metal piece

Application:

Flow mill, chimmey and A/c duct eke

Malerial specification

Malerial: Grahanished ivon Sheel of dimension: 300 mm x 170 mm, thickness 33 gauge

Took Required

1 skeel rule 2) Scriber 3) Divider 4) Oot funch 5) straight snip

6) mallet 7) Anvil 8) stake

Sequence of operation

1) checking 2) Layout morking 3) shearing 4) folding

5) Locking and Finishing

Working steps: Checking:

Check whether the given sheet is having the dimensions as 300 mm × 170 mm. If the dimension is excess toim off using hand shear. If it is less change the given sheet

dayout marking:

1) Place the given sheet overworking table, so that the side of dimension 300 mm is horizontal

2) from left bottom corner, I was the 10 mm horizontal line

3) Then Mark the midpoint on horizontal line from that point to mork 50 mm, 10 mm, 80 mm and 10 mm on, and make dot with punch 4) from the middle point draw on arc of radius 50 mm; 60 mm, 140 mm and 150 mm 5) Using divider Keep 100mm between legs and with 140mm as centerdrawan are 6) Similarly out are as shown in figure.
7) From the midfoint drawan in texsection line though and fill the end.
8) In each division lines have four intersection points and make do first punch. 3) Joint the purch mork in horizontal in each division these lines are veference lines for culting and folding.

10) Hatch unwanted fortion as shown in figure using marker Shearing 1) To remove unwanted portion out along the dork line. 2) Make a small diagonal out at all corners of the seam portion as shown in figure Folding 1) Keef the pallern over taper stake such that the line lacking portion with edge of the stake. Using mallet fold the seam fortion 180° autorate

2) Similarly fold all the seams except last seam inportion

3) Place the sheet over stake such that edge of aligns with stake edge and fold the hem fortion 30° downwords 4) Now it's got happer shape without lacking.

docking and finishing 1) overlap the locking portion town on last division, Lemming the town portion both bottom and top fold outwords 2) Use proper stoke and make mallet make perfect shape 3) check for the dimension Fre lob Questions Of How many sides in hopper? There one 4 sides in hopper &2 Define sheet metal work? The manufockwing of products, components and portomode of metal Q3 What is the use of hopper?
Hopper is used in floormill, chimmey and #/eduteb She which device is used to measure angles? Protector 4/3 How many inches in one feet! 12 inches.

Post Lab Ques Hone Sheet metal is used in vorcous industries such as manufactoring.

Construction, agriculture etc. Divider is used for morking/swibing eshere as jenny califer is used for morking/swibing eshere as jenny califer is used for measuring diameter of solids 3 Mention the angle of dot Punch. Ot what is the use of mallet?
Mallet is used for bending sheet metal without doinging it Os How to call the shape forming tooks forming tooks forming tooks are parts that act as dies that band, shrenkeh or otherwise from sheet metal Resulf Thus the required hopper is made out of the given sheet metal piece

