Karnataka Fire and Emergency Services Department



Sheshadri road, Bangalore – 560 009. 080 – 22971523 / 500 / 600. Fax: 080 – 22971523.



New York Crown Contraction

50 01 2020

To.

The Chairaman, Keerimaa International Residential School, Goobalahalli Road, Kaiwara, Chintamani Taluk, Chikkaballapura District.

Sir.

Sub: Issue of 'Fire safety Recommendation' to Keerthana International Residential School Situated at Goobalahalli Road, Kaiwara, Chintamani Taluk, Chikkaballapura District

Ref. Your letter Dated 11-11-2019.

With reference to the subject above cited, the premises of Keerthane International Residential School situated at Goobalahalli Road, Kaiwar Chintamani Taluk, Chikkaballapura District was inspected by District Fire Officer Chikkaballapura Fire Station on 07-01-2020 with respect to Fire prevention, fighting and Evacuation measures to be complied in the above premises and submitted the details as under;

ANNEXURE-B

NBC-2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings Sub division B1 & B2. (These condition are indicative and not exclusive all relevant provisions related to

fire and life safety of NBC 2016 are mandatory.)

A. Details of the building / premises :-

School, Goobalahalli Road, Kaiwara, Chintamani Taluk, Chikkaballapura District	01.	Name and Address of the	:	The Chairaman,
School, Goobalahalli Road, Kaiwara, Chintamani Taluk,		Applicant.		Koorthana International Devidential
Chintamani Taluk,				
Chintamani Taluk,				Goobalahalli Road, Kaiwara
				Chintamani Taluk.
				Chikkaballapura District.
				(3)

201-2020

2 1	Name and Address of the		Koorthana International Residential Sch			
	promises		Goobalahalli Road, Kaiwara.			
			Chintamani Faluk,			
			Chikkaballapura District			
יי	Number of hall diage		Open Parity Page			
М	Number of floors		Ground & 3 upper floors			
05.	Floor-wise details of occupancy:-					
	A MANUAL LAND CONTRACTOR TO THE LORING					
	i st floor		10 class rooms & store room			
	2 nd floor	:	10 class rooms & store room			
	y mon		TO CIASS TOOMS & STOTE FOOM			
06.	Height of the building		12.40 Mus.			
07.	Site area		2.23 Acres.			
08.	Butt-up area of each floor;-					
	Ground floor	:	771.74 Sq.Mtrs.			
	l st floor		771.74 Sq.Mtrs.			
	2 ^{rm} floor		771.74 Sa.Mtrs.			
			771.74 Sq.Mtrs.			
09.	Total built-up area	:	3086.96 Sq. Mirs.			
10	Surrounding properties:-					
	East (Front)	1:	09.00 mtrs wide Goobalahalli – Kaiv			
	Watthe	-	main road			
	North (Side)		Private property			
	South (Side)	+	Government property			
11.	Set-back area available around the building :-					
	Fast (Front)		Mm 100.00 Mtrs.			
	West (Rear)	1:	05.80 Mus.			
	North (Side)	1	Min 100.00 Mtrs.			
	South (Side)		Nil			
	Allowed setbacks (open space) should be maintained free from furth					

B. On inspection of this School premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absorblely essential from the safety point of view:

Sl. No.	Details (02)	-	Recommendations (0.1)		
01.	Accessibility to the Premises	The premises is accessible from 00.0 mtrs wide Goobalahalli – Kaiwara road located on eastern side.		Adequat	
02	Number of entrances	One entry com- width has been p	Complied		
03.	Generators		Not provided	of generator should be provided & it should be connected to all	
04.	Number of	Nos. of with or staircases Width of treads tune or macro Nos. of riser per flight Unich of handrads Head room clearance	01 No 01 a0 Mus 30 Cms 15 No s 0 00 Mus	In addition of existances of the mine width should be provided for casy movement of	
0.5	Portable extinguishers	Ground floor	ABC type fire each of 04 kgs en provided.	A One water most as AIS type fire extinguisher of 0 trs capacity should	

		1st floor UZ nos of ABC type fire	n One mach
		extinguishers, each of 04 kgs capacity have been provided. 2nd 10 cm 02 nos of ABC type fire extinguishers, each of 04 kgs capacity have been provided. 3" floor 02 nos of ABC type fire extinguishers, each of 04 kgs capacity have been provided.	of 9 ltrs capacity & One ABC type extinguisher of & kgs capacity should be provided near diesel generator. C. One CO2 type fine extinguisher, of & kgs capacity should be provided each electrical extensions.
06	Uaga mad hasa		electrical room.
06.	Hose reel hose system	Not provided	One Hose Reel Hose system should be near the staircase The hose reel hose of min 19mm size and of adequate length to reach the farthest point of each floor should provided shut branch having a noz or omm size. The be reel hose should be connected at each landing.
07.	Terrace tank over respective tower terrace.	Not provided	the system should be connected to an over head tank of 10,000 ltrs capacity

l _s	At the terrace tank level with minimum pressure of	Not provided	connected to an beautiful pump of 450 LPM Further the system should be connected to an beautiful pump of 450 LPM alternative source of power supply.
10,	Locape rounes	barecuon in which the students have to move in the event of an emergency have been indicated in the corridor on each floor during evacuation.	Complied
10.	Fire order (Fire safety plans)	Not displayed	A notice board is been indicated by the employees in case of any emergency with the telephone number of Chintamani tire station i.e. 08154-250006 & 101, 550, 500 & 600 and the telephone number service & Festation.
11.	No smoking board	Not displayed	COTPA Sec-4 direct No Smoking here is an offence board should be written in English & Vancola Land Language shall be prominently displayed at inside the entry / exit of the each language.

Fire fighting training	Not imparted	At-least 40% of the
		fighting at K.A.
		Mundkur Fire and Academy, Rannerughana
Fire precautionary		road, Bangaiore

Fire precautionary measures :-

- A. Explosive and flammable materials chould not be stored in the store exploration. The store exploration is the store exploration in the store exploration in the store exploration in the store exploration.
- B. Accumulation of combustible waste in and around the premises should be avoided.
- The exit ways shall be always kept clear without any obstruction
- D. Liquefied petroleum gas should not be stored in the building.
- 1. The doors shall not be kept locked / latched during working hours and shall be free from obstruction
- 1 During the class hours the class form doors shall not be locked from made or outside.
- G. As per Hon'ble supreme court order all teachers and staff, shall be trained to handle safety equipment, initiate emergency evacuation and protect the students in the event of the and other emergency and the school shall observe the Fire Safety Day on April 11th of every year by conducting i ne Safety drills with co-ordinate with fire service department.

Under the above circumstance the Varietalia Circ & Degree Co.

Department as issuing Vice Sedets Recommendation to Keermana international School situated at Goobalahaili Road, Kaiwara, Chintamani Taluk, bikkaballapura District subject to condition and compliance of the above ecommendations in column -3 of serial - B within 3 months and compliance to the indersigned.

This 'Fire Safety Recommendation' is issued for a period of only one year the date of issue and is renewable.

All requirements recommended above are as per National Building ode- 2016 Part-4 clause 3.1.3 of Fire and Life safety will have to be complied

Yours faithfully