

Road damage type (identified by transformer)

Crack detected. Severity: Medium. Priority: Moderate.

Admin | safestreet3@gmail.com | 24/5/2025, 10:04:55 am