

BOKARO STEEL PLANT — ILLUSTRATIVE SAMPLE

Standard Operating Procedure

SOP No: BSP-FS-001

Title: Fire Emergency Response

Department: Fire Services

Revision: 05

Date: 11-Jan-2024

1. PURPOSE

To define actions for all personnel on discovering a fire anywhere in the plant.

2. ON DISCOVERING A FIRE

Step 1 — Shout "FIRE, FIRE" and break the glass of the nearest manual call point.

Step 2 — Call the Fire Station on Ext. 101 and give: location, what is burning, and whether anyone is trapped.

Step 3 — Attempt to fight the fire only if it is small, you are trained, and you have a clear escape route behind you.

Step 4 — If the fire cannot be controlled in 30 seconds, leave and close doors behind you.

3. CHOOSING THE EXTINGUISHER

- Class A (wood, paper, cloth): water or foam
- Class B (oil, grease, solvents): foam, CO2 or dry chemical powder (DCP)
- Electrical fires: CO2 or DCP only — never water
- Class D (metal fires, e.g. magnesium): special dry powder or dry sand only
- Molten metal: never use water — use dry sand

4. USING AN EXTINGUISHER — P.A.S.S.

Pull the pin, Aim at the base of the fire, Squeeze the handle, Sweep side to side. Stand 2 to 3 metres away.

5. EVACUATION

- Follow green exit signs to the designated assembly point of your department
- Do not use lifts
- Supervisors take a head count within 10 minutes and report missing persons to the Fire Officer

6. FIRE STATION CONTACTS

- Fire Station (main): Ext. 101
- Emergency Control Room: Ext. 100